

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE I	PTE LTD		Ref:	CS3/ASM22000255/Gty3e2	
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11		Date:	14/01/2022	
	ATTN: ANG YVONI	NE		Code:	ASM	
1.	1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHB 3483P	Veh. Inspected	ł	SKV 8974R	
	Policy No.	VFX/P2419140	Coverage (\$)		0.00	
	Claim No.	S2M03QH5	Excess (\$)		0.00	
	Assign From	ANG YVONNE	Assign Date		10/01/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA VEZEL 1.5X	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2015	
	Chassis No.	RU11102303	Colour		WHITE	
	Odometer	183104 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	-	MICHELIN		6 mm	
	L/H Front Tyre	-	MICHELIN		6 mm	
	R/H Rear Tyre	-	MICHELIN		6 mm	
	L/H Rear Tyre	-	MICHELIN		6 mm	
4. Description of Damages						
	THE VEHICLE SUS	HE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5.	. General Information					
	Accident Date	06/01/2022	Inspect Date /	Time	10/01/2022 (03:30 PM)	
	Survey held at	at JSSPRAYWERKS				
		5035 ANG MO KIO INDUSTRIAL PARK 2, #01-355, ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569538				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000					
5b. Estimate Days of Repair						

Report Ref No. CS3/ASM22000255/Gty3e2

Inspected By

ESTIMATED NORMAL PERIOD FOR REPAIR:

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

5 Working Days

Automotive Assessor