



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCN 9788S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	O/S FRONT FENDER	TO REPAIR SEE LABOUR	453.00	-
1	O/S FRONT FENDER INNER COWLING	NOT NECESSARY	57.00	-
6	O/S FRONT FENDER INNER COWLING CLIPS @\$4.50	NOT NECESSARY	27.00	-
1	O/S HEADLAMP	BROKEN	1,059.00	1,059.00
1	O/S HEADLAMP BRACKET	BENT	65.00	65.00
1	FRONT BUMPER	DISTORTED	418.00	418.00
1	FRONT BUMPER REINFORCEMENT	DENTED	575.00	575.00
1	FRONT BUMPER BEAM	NO SUCH PARTS	138.00	-
1	FRONT BUMPER SIDE RETAINER O/S	CRACKED	17.00	17.00
1	FRONT BUMPER ABSORBER FOAM	TORN	111.00	111.00
1	FRONT BUMPER FOG LAMP O/S	CRACKED	95.00	95.00
1	FRONT BUMPER LOWER CENTRE AIR GRILLE	NOT NECESSARY	146.00	-
8	FRONT BUMPER CLIPS @\$4.50	NECESSARY	36.00	36.00
1	FRONT BUMPER AIR GUIDE O/S	NOT NECESSARY	29.00	-
1	O/S WHEEL HUB CAP	NOT NECESSARY	121.60	-
1	O/S FRONT WHEEL RIM	NOT NECESSARY	450.00	-
1	FRONT SUPPORT PANEL	NOT NECESSARY	949.00	-
1	WASHER TANK	DEFORMED	136.20	136.20
	LESS 20% DISCOUNT		-976.56	-502.44
			3,906.24	2,009.76
<u>LABOUR</u>				
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		60.00	20.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	120.00	-
	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION.REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF O/S FRONT FENDER.		700.00	480.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		700.00	580.00
			1,660.00	1,080.00
GRAND TOTAL			5,566.24	3,089.76
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,450.00

Report Ref No. CS/AGI22000257/Uvy3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.