

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22000258/AQCN2**Date:** 17/04/2022**REFERENCE**

Insured/Claimant: NG CHONG HOU, GARVIN (HUANG ZHONGHAO)
Date of Loss: 05/01/2022

Policy No:
Nature of Claim: OD Claim No: 1832768237SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKV995H**
Make & Model: AUDI A3 SPORTBACK, 1.0 TFSI S TRONIC (LED) (A) Engine No: CHZB23633
Reg. Date: 27/06/2019 (Man. Year: 2019) Chassis No: WAUZZZ8VXKA091337
Colour: Black Odometer: 28459 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$97,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,699.00	11,551.84	14,147.16	55.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,794.00	3,592.00	9,202.00	71.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	38,493.00	15,143.84	23,349.16	60.66
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	38,193.00	14,843.84	23,349.16	61.13
+ GST 7.00/7.00% (S\$)	2,673.51	1,039.07	1,634.44	61.13
Nett Amount (S\$)	40,866.51	15,882.91	24,983.60	61.13

INSPECTION

Date of Assignment: 10/01/2022

Date Inspected: 07/01/2022 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,016.00 FS	*1,612.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	187.00 FS	*- FS
3	1		*FRONT BUMPER GUDIE SECTION-RH	Not Necessary	39.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE-CENTER	Not Necessary	160.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTER	Not Necessary	297.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT-RH	Cracked	297.00 FS	*237.20 FS
7	1		*RADIATOR GRILLE	Cracked	1,406.00 FS	*1,124.80 FS
8	1		*RADIATOR CLOSING ELEMENT	Cracked	191.00 FS	*152.40 FS
9	1		*FRONT BUMPER AIR GUIDE GRILLE-RH	Not Necessary	188.00 FS	*- FS
10	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	189.00 FS	*168.80 FS
11	1		*FRONT BUMPER REINFORCEMENT BEAM	Bent	795.00 FS	*677.20 FS
12	1		*AIR COND STICKER	Necessary	8.00 FS	*5.68 FS
13	1		*CAUTION STICKER	Necessary	14.00 FS	*10.88 FS
14	1		*HORN-RH	Not Necessary	200.00 FS	*- FS
15	1		*FRONT FENDER-RH	Buckled	851.00 FS	*680.40 FS
16	1		*POP RIVET (8 pcs)	Not Necessary	27.00 FS	*- FS
17	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	72.00 FS	*- FS
18	1		*FRONT FENDER BRACKET-RH	Bent	48.00 FS	*37.68 FS
19	1		*FRONT FENDER CLOSING ELEMENT-RH	Necessary	62.00 FS	*48.88 FS
20	1		*FRONT FENDER BRACE-RH	Bent	96.00 FS	*76.48 FS
21	1		*FRONT FENDER BRACKET END-RH	Not Necessary	28.00 FS	*- FS
22	1		*FRONT WHEEL HOUSING LINER-RH	Not Necessary	169.00 FS	*- FS
23	1		*BONNET	Dented	2,745.00 FS	*2,196.00 FS
24	1		*BONNET ATTACHMENT PARTS	Not Necessary	165.00 FS	*- FS
25	2		*BONNET HINGE-LH/RH	Not Necessary	124.00 FS	*- FS
26	1		*BONNET EDGE PROTECTION-FRONT	Necessary	28.00 FS	*22.00 FS
27	2		*BONNET STRIKER-LH/RH	Not Necessary	220.00 FS	*- FS
28	2		*BONNET MICROSWITCH-RH	Not Necessary	427.00 FS	*- FS
29	1		*BONNET CATCH HOOK	Not Necessary	90.00 FS	*- FS
30	1		*BONNET BOWDEN CABLE-CENTER	Not Necessary	58.00 FS	*- FS
31	1		*BONNET BOWDEN CABLE COVER	Not Necessary	10.00 FS	*- FS
32	1		*BONNET CATCH HOOK-LOWER	Not Necessary	63.00 FS	*- FS
33	1		*HEADLIGHT-RH	Cracked	5,455.00 FS	*4,364.00 FS
34	1		*HEADLIGHT POWER MODULE-RH	Not Necessary	758.00 FS	*- FS
35	1		*HEADLIGHT HEAT SINK-RH	Not Necessary	733.00 FS	*- FS
36	1		*HEADLIGHT CONTROL UNIT	Not Necessary	557.00 FS	*- FS
37	1		*HEADLIGHT HOSE-RH	Torn	40.00 FS	*31.68 FS
38	1		*LIFT CYLINDER-RH	Not Necessary	142.00 FS	*- FS
39	1		*LIFT CYLINDER HOSE	Not Necessary	68.00 FS	*- FS
40	1		*LOCK CARRIER	Not Necessary	727.00 FS	*- FS
41	1		*A/C CONDENSER	Not Necessary	529.00 FS	*- FS
42	1		*REFRIGERANT LINE	Not Necessary	619.00 FS	*- FS
43	2		*REFRIGERANT LINE	Not Necessary	475.00 FS	*- FS
44	1		*REFRIGERANT LINE BRACKET	Not Necessary	27.00 FS	*- FS
45	1		*REFRIGERANT LINE DUAL CLIP	Not Necessary	30.00 FS	*- FS
46	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Necessary	19.00 FS	*14.56 FS
47	1		*ADDITIONAL RADIATOR	Not Necessary	859.00 FS	*- FS
48	1		*RADIATOR	Not Necessary	951.00 FS	*- FS
49	2		*RADIATOR BRACKET-UPPER	Not Necessary	82.00 FS	*- FS
50	2		*RADIATOR BUSH LOWER-LH/RH	Not Necessary	19.00 FS	*- FS
51	1		*RADIATOR FAN	Not Necessary	1,285.00 FS	*- FS
52	1		*RADIATOR AIR GUIDE-RH	Not Necessary	25.00 FS	*- FS
53	1		*RADIATOR SEAL-RH OUTER	Not Necessary	8.00 FS	*- FS
54	1		*RADIATOR AIR GUIDE-UPPER CENTER	Not Necessary	12.00 FS	*- FS
55	6		*RADIATOR COOLANT	Not Necessary	266.00 FS	*- FS

Report was unsubmitted during this print-out.

4/17/22, 8:38 PMAdjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*AIR INTAKE GUIDE UPPER COVER (Npa)	Not Necessary	0.00 FS	*- FS
57	1		*AIR INTAKE GUIDE UPPER (Npa)	Not Necessary	0.00 FS	*- FS
58	1		*AIR INTAKE GUIDE UPPER -LH (Npa)	Not Necessary	0.00 FS	*- FS
59	1		*RADIATOR AIR DUCT-TOP	Not Necessary	66.00 FS	*- FS
60	1		*FRONT CHASSIS MEMBER PLATE-LH	Not Necessary	95.00 FS	*- FS
61	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
62	1		*SUNDRIES	Necessary	400.00 FS	*30.40 FS
63	1		*FRONT BUMPER REINFORCEMENT BEAM COVER	Not Necessary	122.00 FS	*- FS
F=Franchise part. S=SpcNett.						
				Total Parts (S\$)	25,699.00	11,551.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER,ADDITIONAL RADIATOR AND RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT.PRESSURIES COOLING SYSTEM,VACUUM AND REGAS	New	1,400.00	0.00
4	TO DISMANTLE AND RENEW FRONT BUMPER,RHS FRONT FENDER,BONNET AND RHS HEADLIGHT.TO CUT OUT AND WELD RHS FRONT CHASSIS MEMBER COVER PLATE.TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	6,300.00	1,500.00
5	TO RESPRAY FRONT BUMPER,BONNET,HINGES,RHS FRONT FENDER AND RHS FRONT CHASSIS MEMBER COVER PLATE	New	4,000.00	1,650.00
6	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	192.00
Gross Labour Cost (\$\$)			12,794.00	3,592.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >