

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22000260/ATCN2**Date:** 24/04/2022**REFERENCE**

Insured/Claimant: CECILIA CHIA HYAU LIAN Policy No: 2100379472
Date of Loss: 03/01/2022 Nature of Claim: OD Claim No: 5788742606SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SM2222U**
Make & Model: AUDI A3, 1.4 SEDAN TFSI (AMBIENTE) (A) Engine No: CXS097471
Reg. Date: 17/07/2014 (Man. Year: 2014) Chassis No: WAUZZZ8V9E1037984
Colour: Grey Odometer: 119498 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$42,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,543.00	2,898.40	4,644.60	61.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,002.00	2,542.00	2,460.00	49.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,545.00	5,440.40	7,104.60	56.63
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	11,945.00	4,840.40	7,104.60	59.48
+ GST 7.00/7.00% (S\$)	836.15	338.83	497.32	59.48
Nett Amount (S\$)	12,781.15	5,179.23	7,601.92	59.48

INSPECTION

Date of Assignment: 10/01/2022
Date Inspected: 07/01/2022 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,233.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	187.00 FS	*- FS
3	1		*FRONT BUMPER TRIM COVER-RH	Not Necessary	163.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTER	Not Necessary	163.00 FS	*- FS
5	1		*FRONT BUMPER GUIDE SECTION-RH	Not Necessary	39.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE-RH	Cut	109.00 FS	*87.20 FS
7	1		*FRONT FENDER-RH	Dented	851.00 FS	*680.40 FS
8	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	72.00 FS	*- FS
9	1		*FRONT FENDER BRACKET	Not Necessary	39.00 FS	*- FS
10	1		*FRONT FENDER BRACE	Not Necessary	96.00 FS	*- FS
11	5		*POP RIVET	Not Necessary	17.00 FS	*- FS
12	1		*HEADLIGHT-RH	Cut	2,641.00 FS	*2,112.80 FS
13	1		*LIFT CYLINDER-RH	Not Necessary	193.00 FS	*- FS
14	1		*LIFT CYLINDER HOSE	Not Necessary	182.00 FS	*- FS
15	1		*FRONT WHEEL HOUSING LINER-RH	Not Necessary	169.00 FS	*- FS
16	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	89.00 FS	*- FS
17	1		*SUNDRIES	Necessary	300.00 FS	*18.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 7,543.00 2,898.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER,RHS FRONT FENDER AND RHS HEADLIGHT.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,002.00	2,542.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >