

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22000261/AVCE2

Date: 02/08/2022

REFERENCE

Insured/Claimant: WONG HONG YEE ALVIN (HUANG HONGYI ALVIN) Policy No: 1900149540-02

Date of Loss: 06/01/2022

Nature of Claim: OD

Claim No: 0107367807SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMN7430T**
Make & Model: AUDI A3, 999cc SEDAN TFSI S TRONIC (LED) (A) Engine No: CHZC32155
Reg. Date: 27/08/2019 (Man. Year: 2019) Chassis No: WAUZZZ8V2KA111631
Colour: Grey Odometer: 30523 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$98,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,369.00	17,746.32	13,622.68	43.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,944.00	8,144.00	5,800.00	41.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	45,313.00	25,890.32	19,422.68	42.86
- Excess (S\$)	2,000.00	2,000.00	0.00	0.00
(S\$)	43,313.00	23,890.32	19,422.68	44.84
+ GST 7.00/7.00% (S\$)	3,031.91	1,672.32	1,359.59	44.84
Nett Amount (S\$)	46,344.91	25,562.64	20,782.27	44.84

INSPECTION

Date of Assignment: 10/01/2022

Date Inspected: 07/01/2022 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,987.00 FS	*1,589.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	187.00 FS	*- FS
3	2		*FRONT BUMPER GUIDE SECTION-LH/RH	Not Necessary	78.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE-CENTER	Cracked	160.00 FS	*128.00 FS
5	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTER	Not Necessary	536.00 FS	*- FS
6	2		*FRONT BUMPER CLOSING ELEMENT-LH/RH	Not Necessary	594.00 FS	*- FS
7	2		*FRONT BUMPER TRIM COVER-LH/RH	Not Necessary	326.00 FS	*- FS
8	2		*FRONT BUMPER ADAPTER-LH/RH	Not Necessary	76.00 FS	*- FS
9	1		*RADIATOR GRILLE	Cracked	1,406.00 FS	*1,124.80 FS
10	1		*RADIATOR CLOSING ELEMENT	Cracked	191.00 FS	*152.40 FS
11	2		*FRONT BUMPER AIR GUIDE GRILLE-LH/RH	Not Necessary	376.00 FS	*- FS
12	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	189.00 FS	*151.20 FS
13	1		*FRONT BUMPER REINFORCEMENT BEAM COVER	Cut	122.00 FS	*97.20 FS
14	1		*FRONT BUMPER REINFORCEMENT BEAM	Dented	795.00 FS	*636.00 FS
15	1		*AIR COND STICKER	Necessary	8.00 FS	*5.68 FS
16	1		*CAUTION STICKER	Necessary	14.00 FS	*10.88 FS
17	2		*HORN-LH/RH	Not Necessary	400.00 FS	*- FS
18	1		*FRONT FENDER-LH/RH	N/s Buckled	1,702.00 FS	*680.40 FS
19	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	72.00 FS	*- FS
20	10		*FRONT FENDER RIVET	Necessary	33.00 FS	*26.40 FS
21	1		*FRONT FENDER BRACKET-LH/RH	N/s Bent	78.00 FS	*30.72 FS
22	1		*FRONT FENDER BRACE-LH/RH	N/s Bent	192.00 FS	*76.48 FS
23	2		*FRONT FENDER BRACKET END-LH/RH	Not Necessary	56.00 FS	*- FS
24	2		*FRONT WHEEL HOUSING LINER-LH/RH	Not Necessary	338.00 FS	*- FS
25	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	89.00 FS	*- FS
26	1		*BONNET	Buckled	3,134.00 FS	*2,507.20 FS
27	1		*BONNET ATTACHMENT PARTS	Not Necessary	165.00 FS	*- FS
28	2		*BONNET HINGE-LH/RH	Bent	124.00 FS	*97.76 FS
29	1		*BONNET EDGE PROTECTION	Necessary	28.00 FS	*22.00 FS
30	1		*BONNET CATCH HOOK	Damaged	90.00 FS	*71.28 FS
31	1		*BONNET CATCH HOOK LOWER	Damaged	63.00 FS	*50.32 FS
32	2		*BONNET STRIKER-LH/RH	Not Necessary	220.00 FS	*- FS
33	2		*BONNET MICROSWITCH-LH/RH	Damaged	427.00 FS	*341.60 FS
34	1		*BONNET BOWDEN CABLE-CENTER	Damaged	58.00 FS	*46.00 FS
35	1		*BONNET BOWDEN CABLE COVER	Not Necessary	10.00 FS	*- FS
36	1		*PLENUM CHAMBER COVER	Cut	179.00 FS	*143.20 FS
37	1		*BONNET ABSOBER	Not Necessary	104.00 FS	*- FS
38	2		*HEADLIGHT-LH/RH	Cracked	10,910.00 FS	*8,728.00 FS
39	2		*LIFT CYLINDER-LH/RH	Not Necessary	284.00 FS	*- FS
40	1		*LIFT CYLINDER HOSE	Not Necessary	68.00 FS	*- FS
41	1		*LOCK CARRIER	Cracked	727.00 FS	*581.60 FS
42	1		*A/C CONDENSER	Not Necessary	529.00 FS	*- FS
43	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	19.00 FS	*- FS
44	1		*ADDITIONAL RADIATOR	Not Necessary	859.00 FS	*- FS
45	1		*RADIATOR	Not Necessary	951.00 FS	*- FS
46	2		*RADIATOR BRACKET	Not Necessary	82.00 FS	*- FS
47	2		*RADIATOR BUSH LOWER-LH/RH	Not Necessary	19.00 FS	*- FS
48	1		*RADIATOR COOLANT	Necessary	266.00 FS	*212.64 FS
			(6 Pcs)			
49	1		*RADIATOR FAN	Not Necessary	1,265.00 FS	*- FS
50	2		*RADIATOR AIR GUIDE-LH/RH	Torn	50.00 FS	*38.88 FS
51	1		*RADIATOR SEAL-RH OUTER	Not Necessary	8.00 FS	*- FS
52	1		*RADIATOR AIR GUIDE-UPPER CENTER	Torn	12.00 FS	*9.44 FS
53	2		*WINDSCREEN WATER DEFLECTOR STRIP-LH/RH	Not Necessary	186.00 FS	*- FS
54	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
55	1		*SUNDRIES	Necessary	350.00 FS	*33.04 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*WINDSCREEN NOZZLE-LH (Supplementary)	Damaged	117.00 FS	*93.60 FS
F=Franchise part. S=SpcNett.						
				Total Parts (S\$)	31,369.00	17,746.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	700.00	500.00
3	TO REMOVE AND RENEW AIRCON CONDENSER,ADDITIONAL RADIATOR AND RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT.PRESSURISE COOLING SYSTEM VACUUM AND REGAS	New	1,400.00	1,400.00
4	TO DISMANTLE AND RENEW FRONT BUMPER,BOTH FRONT FENDER,BONNET AND BOTH HEADLIGHT.TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSIITON.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	5,600.00	2,750.00
5	TO RESPRAY FRONT BUMPER,BONNET,HINGES,BOTH FRONT FENDER AND BOTH UPPER A-PILLAR	New	5,500.00	2,750.00
6	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	384.00
Gross Labour Cost (\$\$)			13,944.00	8,144.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >