

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22000262/RQCN2**Date:** 23/04/2022**REFERENCE**

Insured/Claimant:	TAN CHENG HONG	Policy No:	1800003668-03	
Date of Loss:	18/12/2021	Nature of Claim:	OD	Claim No: 9914415230SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGW7667B		
Make & Model:	AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A)	Engine No:	CVK050751
Reg. Date:	12/01/2018 (Man. Year: 2017)	Chassis No:	WAUZZZF51JA049480
Colour:	Grey	Odometer:	38923 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$135,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40ZR18	Rear Tyre Size:	245/40ZR18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,960.00	9,241.84	4,718.16	33.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,972.00	3,022.00	2,950.00	49.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,932.00	12,263.84	7,668.16	38.47
- Excess (S\$)	1,100.00	1,100.00	0.00	0.00
(S\$)	18,832.00	11,163.84	7,668.16	40.72
+ GST 7.00/7.00% (S\$)	1,318.24	781.47	536.77	40.72
Nett Amount (S\$)	20,150.24	11,945.31	8,204.93	40.72

INSPECTION

Date of Assignment:	10/01/2022	
Date Inspected:	07/01/2022	Inspected At: 24 BENOI SECTOR SINGAPORE 629857 REPAIRER: PREMIUM AUTOMOBILES PTE LTD
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,251.00 FS	*1,800.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	407.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	71.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTER	Not Necessary	228.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE-RH	Not Necessary	63.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE-RH	Not Necessary	474.00 FS	*- FS
7	1		*FRONT FENDER-RH	Bent	1,060.00 FS	*848.00 FS
8	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	53.00 FS	*- FS
9	1		*FRONT FENDER CLOSING ELEMENT-RH	Necessary	74.00 FS	*59.04 FS
10	1		*FRONT FENDER BRACKET-RH	Necessary	35.00 FS	*27.92 FS
11	5		*POP RIVET	Necessary	17.00 FS	*13.20 FS
12	1		*FRONT FENDER BRACE-RH	Not Necessary	118.00 FS	*- FS
13	1		*FRONT FENDER BRACKET-RH CENTER	Not Necessary	49.00 FS	*- FS
14	1		*FRONT FENDER TRIM-RH	Necessary	164.00 FS	*130.80 FS
15	1		*FRONT FENDER FLEDGE COVER LONG-RH	Necessary	36.00 FS	*28.24 FS
16	1		*FRONT FENDER FLEDGE COVER SHORT-RH	Necessary	16.00 FS	*12.24 FS
17	1		*FRONT WHEEL HOUSING LINER-RH	Not Necessary	275.00 FS	*- FS
18	1		*FRONT WHEEL SPOILER	Not Necessary	73.00 FS	*- FS
19	1		*FRONT WHEEL SPOILER LOWER-RH	Not Necessary	36.00 FS	*- FS
20	1		*HEADLIGHT-RH	Scratched	7,902.00 FS	*6,321.60 FS
21	1		*LIFT CYLINDER-RH	Not Necessary	198.00 FS	*- FS
22	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
23	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
Total Parts (\$\$)						13,960.00 9,241.84

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER,RHS FRONT FENDER AND RHS HEADLIGHT.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,500.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,972.00	3,022.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >