

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

		PRE-REPAIR INS	PECTION RE	PORT		
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22000263/Bvy3e2	
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11		Date:	18/01/2022	
	ATTN: KHONG LY	NN		Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHC 3446S	Veh. Inspected	k	SMA 608M	
	Policy No.	VFX/P2419138	Coverage (\$)		0.00	
	Claim No.	S2M03QIU	Excess (\$)		0.00	
	Assign From	KHONG LYNN	Assign Date		10/01/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI I30 1.4 T-GDI	c.c		1353	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	TMAH3513VJJ071516	Colour		BLUE	
	Odometer	59802 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	225/45 R17	MICHELIN		5 mm	
	L/H Front Tyre	225/45 R17	MICHELIN		5 mm	
	R/H Rear Tyre	225/45 R17	MICHELIN		5 mm	
	L/H Rear Tyre	225/45 R17	MICHELIN		5 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
5. General Information						
	Accident Date	06/01/2022	Inspect Date /	Time	11/01/2022 (01:30 PM)	
	Survey held at	TY AUTOCARE SERVICES	•			
	5033 ANG MO KIO INDUSTRIAL PARK 2 #01-271 SINGAPORE 569536					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000-\$8,000					
	Estimate Days of Repair					
5b.		Estimate	Days of Repair			

Report Ref No. CS3/ASM22000263/Bvy3e2

Inspected By

LIM TEOW GUAN

K.K.LAU CPT(RET)

Automotive Assessor

 ${\tt BEng(Hons),B.Bus,MBA,PEng,PE,\,MInstAEA,MASME,MIRTE}$

REGD Auto Consultant-SAE, Licensed Appraiser