

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22000264/RTCN2**Date:** 31/03/2022**REFERENCE**

Insured/Claimant:	CHAN TECK WEI	Policy No:	1800083915	
Date of Loss:	31/12/2021	Nature of Claim:	OD	Claim No: 8207641803SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC6973H		
Make & Model:	AUDI A3, 999cc SEDAN TFSI S TRONIC (LED) (A)	Engine No:	CHZ959070
Reg. Date:	17/07/2018 (Man. Year: 2018)	Chassis No:	WAUZZZ8VXJ1074343
Colour:	Black	Odometer:	28715 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$89,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,115.80	10,376.72	4,739.08	31.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,502.00	5,552.00	2,950.00	34.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,617.80	15,928.72	7,689.08	32.56
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	23,017.80	15,328.72	7,689.08	33.40
+ GST 7.00/7.00% (S\$)	1,611.25	1,073.01	538.24	33.41
Nett Amount (S\$)	24,629.05	16,401.73	8,227.32	33.40

INSPECTION

Date of Assignment:	10/01/2022	
Date Inspected:	07/01/2022	Inspected At: 24 BENOI SECTOR SINGAPORE 629857 REPAIRER:PREMIUM AUTOMOBILES PTE LTD
Estimated Period of Repair:	7.0 days	

Adjuster: MOHD RASUL**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,987.00 FS	*1,589.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	187.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION-RH	Cracked	39.00 FS	*30.48 FS
4	1		*FRONT BUMPER GRILLE-CENTER	Cracked	160.00 FS	*128.00 FS
5	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTER	Cracked	536.00 FS	*428.80 FS
6	1		*FRONT BUMPER CLOSING ELEMENT-RH	Not Necessary	297.00 FS	*- FS
7	1		*FRONT BUMPER TRIM COVER-RH	Cracked	163.00 FS	*130.00 FS
8	1		*FRONT BUMPER ADAPTER-RH	Not Necessary	38.00 FS	*- FS
9	1		*RADIATOR GRILLE	Cracked	1,406.00 FS	*1,124.80 FS
10	1		*FRONT CLOSING ELEMENT	Cracked	191.00 FS	*152.40 FS
11	1		*FRONT BUMPER AIR GUIDE GRILLE-RH	Scratched	188.00 FS	*150.00 FS
12	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	189.00 FS	*151.20 FS
13	1		*FRONT BUMPER TOP COVER	Not Necessary	122.00 FS	*- FS
14	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	795.00 FS	*- FS
15	1		*HORN-RH	Not Necessary	200.00 FS	*- FS
16	1		*AIR COND STICKER	Necessary	8.00 FS	*5.68 FS
17	1		*CAUTION STICKER	Necessary	14.00 FS	*10.88 FS
18	1		*FRONT FENDER-RH	Bent	851.00 FS	*680.40 FS
19	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	72.00 FS	*- FS
20	1		*FRONT FENDER BRACKET-RH	Not Necessary	39.00 FS	*- FS
21	1		*FRONT FENDER BRACE	Bent	96.00 FS	*76.48 FS
22	5		*POP RIVET	Not Necessary	17.00 FS	*- FS
23	1		*FRONT WHEEL HOUSING LINER-RH	Cracked	169.00 FS	*134.80 FS
24	1		*HEADLIGHT-RH	Cracked	5,455.00 FS	*4,364.00 FS
25	1		*LIFT CYLINDER-RH	Not Necessary	142.00 FS	*- FS
26	1		*LIFT CYLINDER HOSE	Cut	68.00 FS	*53.84 FS
27	1		*RADIATOR COOLANT LOCK CARRIER MOUNTING	Cracked	727.00 FS	*581.60 FS
28	6		*RADIATOR COOLANT	Necessary	185.00 FS	*147.36 FS
29	1		*RADIATOR AIR GUIDE-RH	Cracked	25.00 FS	*19.44 FS
30	1		*RADIATOR SEAL-RH OUTER	Not Necessary	8.00 FS	*- FS
31	1		*RADIATOR AIR GUIDE-UPPER CENTER	Not Necessary	12.00 FS	*- FS
32	1		*RADIATOR BRACKET	Not Necessary	19.00 FS	*- FS
33	1		*FRONT NO PLATE	Bent	60.00 FS	*60.00 FS
34	1		*SUNDRIES	Necessary	350.00 FS	*56.16 FS
35	1		*FRONT NOISE INSULATION	Cracked	300.80 FS	*300.80 FS

Supplementary

F=Franchise part. S=SpcNett.

Total Parts (S\$) 15,115.80 10,376.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER,ADDITIONAL RADIATOR AND RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT.PRESSURISE COOLING SYSTEM.VACUUM AND REGAS	New	1,400.00	1,400.00
4	TO DISMANTLE AND RENEW FRONT BUMPER,RHS FRONT FENDER AND RHS HEADLIGHT.TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	4,200.00	2,250.00
5	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,000.00	1,100.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			8,502.00	5,552.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >