

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 6761E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FENDER SUB-ASSY FRONT LH	DENTED	945.30	945.30
1	LINER FRONT FENDER RH	SERVICEABLE	198.50	-
1	EMBLEM SIDE PANEL (HYBRID)	NECESSARY	86.50	86.50
1	PANEL SUB-ASSY QUARTER LH	DENTED	836.70	836.70
1	MLDG ASSY BODY ROCKER PAN	DENTED	559.20	559.20
1	MIRROR ASSY OUTER REAR VI	SERVICEABLE	1,390.10	-
1	COVER OUTER MIRROR LH	TO REPAIR SEE LABOUR	141.90	-
	LESS 25% DISCOUNT		-1,039.55	-606.93
			3,118.65	1,820.77
	NETT ITEMS			
1	FRT DOOR LOGO CTPL (N)	NECESSARY	75.00	75.00
1	APP LOGO REAR DOOR L/R CT (N)	NECESSARY	80.00	80.00
1	FUEL TANK LID (PETROL ONL)(N)	NECESSARY	30.00	30.00
	LESS 10% DISCOUNT		-18.50	-18.50
			166.50	166.50
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF COVER OUTER MIRROR LH.		1,500.00	1,400.00
	SPRAYPAINT CHARGE.		1,300.00	1,250.00
	CHECK ALL LIGHTING.		50.00	20.00
	TUFF COAT ON AFFECTED PARTS.		50.00	30.00
	REMOVE/REFIX UPHOLSTERY ASST REPAIR.		120.00	120.00
			3,020.00	2,820.00
	GRAND TOTAL		6,305.15	4,807.27





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		3,850.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC22000272/Vqcn2



THEVAN THOMAS KARTHIKESAVAN



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser