

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22000273/UGA3Q2**Date:** 20/05/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210009168
<b>Claimant Vehicle No :</b>	SKS9688B	<b>Insured Vehicle No :</b>	SDJ8800E
Date of Loss:	08/01/2022	Nature of Claim:	TP
		Claim No:	5427830032SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKS9688B</b>	Engine No:	2AZ1B04042
Make & Model:	TOYOTA PREVIA AERAS, 2.4 CVT MR (A)	Chassis No:	JTEGD56M707170949
Reg. Date:	18/06/2019 (Man. Year: 2019)	Odometer:	78478 km
Colour:	Purple		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,650.20	4,207.60	442.60	9.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,910.00	770.00	1,140.00	59.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>6,560.20</b>	<b>4,977.60</b>	<b>1,582.60</b>	<b>24.12</b>
<b>+ GST 7.00/7.00% (S\$)</b>	459.21	348.43	110.78	24.12
<b>Nett Amount (S\$)</b>	<b>7,019.41</b>	<b>5,326.03</b>	<b>1,693.38</b>	<b>24.12</b>
<b>+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (S\$)</b>		321.00		
<b>Nett Liability (S\$)</b>		<b>5,647.03</b>		

INSPECTION

Date of Assignment:	10/01/2022		
Date Inspected:	10/01/2022	Inspected At:	Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	3.0 days		

**Adjuster:** MARCUS CHUA**Manager:** Jaslin Kok Chin Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	604.90 FL	*604.90 FL
2	8		*FRONT BUMPER CLIPS	Necessary	34.40 FL	*34.40 FL
3	1		*FRONT BUMPER CENTRE GARNISH	Distorted	588.00 FL	*588.00 FL
4	1		*FRONT BUMPER CENTRE GRILLE	Grazed	215.00 FL	*215.00 FL
5	1		*FRONT BUMPER TOW COVER	Missing	42.00 FL	*42.00 FL
6	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	141.80 FL	*- FL
7	1		*FRONT BUMPER UNDER PLASTIC	Distorted	155.70 FL	*155.70 FL
8	1		*FRONT BUMPER FOAM	Torn	79.60 FL	*79.60 FL
9	1		*FRONT BUMPER REINFORCEMENT	Repair	435.00 FL	*- FL
10	1		*N/S FRONT FENDER INNER COWLING	Torn	222.80 FL	*222.80 FL
11	8		*N/S FRONT FENDER INNER COWLING CLIPS	Necessary	34.40 FL	*34.40 FL
12	1		*FRONT GRILLE ASY	Cracked	589.20 FL	*589.20 FL
13	1		*N/S HEADLAMP	Cracked	2,520.00 FL	*2,520.00 FL
14	1		*HORN N/S	Cracked	134.80 FL	*134.80 FL
15	1		*FRONT GRILLE EMBLEM	Scratched	336.00 FL	*336.00 FL
16	1		*FRONT NUMBER PLATE	Cracked	50.00 FS	*40.00 FS
					Sub Total (S\$)	6,183.60 5,596.80
					- List Item Discount on L Items 25.00/25.00% (S\$)	1,533.40 1,389.20
					Total Parts (S\$)	4,650.20 4,207.60

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REINSTALL OF FRONT BUMPER PARKING SENSOR	New	80.00	50.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	80.00	20.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	150.00	0.00
4	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	800.00	300.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	800.00	400.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,910.00</b>	<b>770.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >