

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN	NCE BHD		Ref:	CS3/LPC22000286/Eqy3e2	
	300 BEACH ROAD SINGAPORE 1995		Date:	27/01/2022		
				Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	XD 3792Y	Veh. Inspected		GBF 4806K	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	21/22/22/VC00/025341	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		10/01/2022	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA HIACE	c.c		2755	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.	JTFHT02P400210368	Colour		SILVER	
	Odometer	133755 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	FAIR				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195 R15C	DUNLOP		4 mm	
	L/H Front Tyre	195 R15C	DUNLOP		4 mm	
	R/H Rear Tyre	195 R15C	DUNLOP		4 mm	
	L/H Rear Tyre	195 R15C	DUNLOP		4 mm	
4. Description of Damages						
	THE VEHICLE SUS	STAINED DAMAGES AT THE REAR N/S PORTION.				
5.	General Information					
	Accident Date	07/01/2022	Inspect Date /	Time	18/01/2022 (12:29 PM)	
	Survey held at	7 SOON LEE STREET #01-39 ISPACE S627608				
	Repairer	LYS ENGINEERING				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC22000286/Eqy3e2

Inspected By

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser