

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22000295/UPA3Q2**Date:** 07/07/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900161105
Claimant Vehicle No :	GBE2766K	Insured Vehicle No :	SMP1187A
Date of Loss:	06/01/2022	Nature of Claim:	TP
		Claim No:	7321688178SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE2766K		
Make & Model:	TOYOTA DYNA 1.5T, 3.0 (M)	Engine No:	1KD2560765
Reg. Date:	20/10/2015 (Man. Year: 2015)	Chassis No:	JTFAT35Y40K205196
Colour:	Orange/Blue	Odometer:	188791 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	155 R12
Front Left Side:	OHTSU 5 mm	Rear Left Side:	Falken 5 mm
Front Right Side:	OHTSU 5 mm	Rear Right Side:	Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,776.50	3,328.15	5,448.35	62.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,090.00	1,060.00	2,030.00	65.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,866.50	4,388.15	7,478.35	63.02
Approved Total (Overridden) (S\$)		3,500.00		
Nett Amount (S\$)	11,866.50	3,500.00	8,366.50	70.51
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
		(S\$)		
		3,900.00		
Liabe Amount (50.00%) (S\$)		1,950.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,957.45		
Global Sum Settlement (S\$)		1,900.00		

INSPECTION

Date of Assignment:	10/01/2022		
Date Inspected:	10/01/2022	Inspected At:	Asia Motorsports Solution Pte Ltd (HQ) 37A Everitt Singapore 428586
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER ASSY	Warped	1,012.00 FL	*681.10 FL
2	2		*FRONT BUMPER ASSY BRACKET	Not Necessary	230.00 FL	*- FL
3	1		*REAR BUMPER REINFORCEMENT	Not Necessary	496.00 FL	*- FL
4	1		*FRONT GRILLE ASSY	Repair	468.00 FL	*- FL
5	1		*FRONT GRILLE EMBLEM	Not Necessary	88.00 FL	*- FL
6	1		*FRONT PANEL ASSY	Not Necessary	1,296.00 FL	*- FL
7	2		*FRONT PANEL BRACKET	Not Necessary	183.00 FL	*- FL
8	1		*FRONT PANEL DYNA EMBLEM	Not Necessary	68.00 FL	*- FL
9	2		*FRONT PANEL LOWER MOUNTING	Not Necessary	285.00 FL	*- FL
10	1		*FRONT RIGHT CORNER PANEL	Dented	183.00 FL	*183.00 FL
11	1		*FRONT RIGHT UPPER CORNER PANEL	Warped	484.00 FL	*484.00 FL
12	1		*FRONT RIGHT HEADLAMP	Scratched	696.00 FL	*696.00 FL
13	1		*FRONT CENTRE GARNISH	Not Necessary	197.00 FL	*- FL
14	1		*FRONT RIGHT SIDE TOP GARNISH (BLACK)	Grazed	108.00 FL	*108.00 FL
15	1		*FRONT RIGHT WING MIRROR	Not Necessary	298.00 FL	*- FL
16	1		*FRONT TOWING HOOK	Not Necessary	179.00 FL	*- FL
17	1		*FRONT RIGHT DOOR PANEL ASSY	Dented / Bent	1,467.00 FL	*1,467.00 FL
18	1		*FRONT RIGHT DOOR REGULATOR WITH MOTOR ASSY	Not Necessary	479.00 FL	*- FL
19	1		*FRONT RIGHT DOOR LOCK MECHANISM	Not Necessary	255.00 FL	*- FL
20	2		*FRONT RIGHT DOOR PANEL HINGES	Not Necessary	165.00 FL	*- FL
21	1		*FRONT RIGHT DOOR CHECKER LINKAGE	Not Necessary	166.00 FL	*- FL
22	1		*FRONT RIGHT DOOR LOWER STEP INNER PANEL	Not Necessary	354.00 FL	*- FL
23	1		*FRONT RIGHT DOOR LOWER STEP GARNISH	Grazed	277.00 FL	*245.10 FL
24	1		*FRONT WINDSCREEN GLASS MOULDING	Not Necessary	288.00 FL	*- FL
25	6		*FRONT GRILLE CLIPS	Not Necessary	45.00 FS	*- FS
26	1		*FRONT NO PLATE	Not Necessary	100.00 FS	*- FS
27	2		*FRONT RIGHT SIDE TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
28	4		*FRONT CENTRE GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
29	1		*FRONT RIGHT DOOR COMPANY STICKER	Necessary	80.00 FS	*30.00 FS
30	1		*FRONT RIGHT DOOR ADVERTISEMENT STICKER	Necessary	650.00 FS	*400.00 FS
31	1		*FRONT WINDSCREEN GLASS SEALANT	Not Necessary	100.00 FS	*- FS
32	1		*FRONT PANEL STICKER	Not Necessary	350.00 FS	*- FS
33	1		*FRONT PANEL SEALANT	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **11,207.00** **4,294.20**
- List Item Discount on L Items 25.00/25.00% (\$\$) 2,430.50 966.05

Total Parts (\$\$) **8,776.50** **3,328.15**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING ,CUT ,WELD STRAIGHTEN FRONT AFFECTED AREA AND REPLACE FRONT DAMAGED PARTS	New	1,200.00	400.00
2	TO PUTTY AND SPRAY PAINTING FRONT PORTION	New	1,200.00	550.00
3	TO CHECK WIRING AND FOCUS FRONT HEADLAMP	New	50.00	20.00
4	TO TRANSFER FRONT RIGHT DOOR GLASS TO NEW DOOR	New	80.00	60.00
5	TO APPLY ANTI RUST PROOFING TO FRONT AFFECTED AREA	New	140.00	30.00
6	TO SYNCHRONISE FRONT RIGHT WING MIRROR FOR FUNCTION	New	80.00	0.00
7	TO REMOVE AND INSTALL FRONT RIGHT DOOR LOCK MECHANISM	New	80.00	0.00
8	TO CHECK DOOR CENTRAL LOCKING FOR FUNCTION	New	80.00	0.00
9	TO REMOVE AND INSTALL FRONT RIGHT DOOR REGULATOR WITH MOTOR ASSY	New	80.00	0.00
10	TOWING SERVICE	New	100.00	0.00
Gross Labour Cost (S\$)			3,090.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >