

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000307/KNY3M4**Date:** 27/01/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNW00013432100

Claimant Vehicle No : SLM812M **Insured Vehicle No :** CB7816X

Date of Loss: 05/01/2022 Nature of Claim: TP Claim No: SNM22D200115/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLM812M**

Make & Model: HONDA CIVIC, 1.6 VTI CVT (A) Engine No: R16B21601408

Reg. Date: (Man. Year:) Chassis No: MRHFC5650GT001108

Colour: Metallic Pearl White Odometer: 126553 km

Engine Capacity: 1597 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/50 R17 Rear Tyre Size: 215/50 R17

Front Left Side: Dunlop 8 mm Rear Left Side: Dunlop 8 mm

Front Right Side: Dunlop 8 mm Rear Right Side: Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,194.20	1,856.36	2,337.84	55.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,650.00	920.00	1,730.00	65.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,844.20	2,776.36	4,067.84	59.43
Approved Total (Overridden) (S\$)		2,200.00		
Nett Amount (S\$)	6,844.20	2,200.00	4,644.20	67.86

INSPECTION

Date of Assignment: 11/01/2022

Date Inspected: 11/01/2022 Inspected At: THIAM HENG HUAT PTE LTD
176 SIN MING DRIVE
#05-14 SINGAPORE 575721

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jan 2023)
Parts:	143	HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM812M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER O/S	Repair	902.00 FL	*- FL
2	1		*REAR FENDER COWLING O/S	Serviceable	185.00 FL	*- FL
3	1		*REAR BUMPER	Mtg Cracked	876.00 FL	*717.20 FL
4	1		*REAR BUMPER REFLECTOR O/S	Serviceable	189.00 FL	*- FL
5	1		*REAR BUMPER REFLECTOR GARNISH O/S	Serviceable	145.00 FL	*- FL
6	2		*REAR BUMPER RETAINER	Serviceable	170.00 FL	*- FL
7	1		*REAR KNUCKLE CARRIER O/S	Bent	498.00 FL	*498.00 FL
8	1		*REAR KNUCKLE CARRIER BEARING O/S	Necessary	145.00 FL	*145.00 FL
9	1		*REAR UPPER CONTROL ARM O/S	Serviceable	286.00 FL	*- FL
10	1		*REAR LOWER CONTROL ARM O/S	Distorted	329.00 FL	*329.00 FL
11	1		*REAR END LINK O/S	Serviceable	136.00 FL	*- FL
12	1		*REAR SHOCK ABSORBER O/S	Serviceable	345.00 FL	*- FL
13	1		*REAR SHOCK ABSORBER TOP MOUNT O/S	Serviceable	63.00 FL	*- FL
14	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
15	1		*REAR ALLOY WHEEL O/S	Dented	450.00 FS	*450.00 FS
16	1		*REAR TYRE O/S	Serviceable	180.00 FS	*- FS
17	8		*REAR FENDER COWLING O/S CLIPS	Not Necessary	44.00 FS	*- FS
18	10		*REAR BUMPER CLIPS	Necessary	55.00 FS	*55.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,048.00	2,194.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	853.80	337.84
Total Parts (\$\$)	4,194.20	1,856.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE/RENEW THE ACCIDENT DAMAGED PORTION.TO PANEL BEAT,RESHAPE,STRAIGHTEN,ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	New	1,200.00	450.00
2	TO CHECK AND COMPUTERIZED 4 WHEEL ALIGNMENT	New	100.00	0.00
3	TO REMOVE AND REFIT O/S REAR UNDERCARRIAGE FOR REPLACEMENT OF PARTS	New	200.00	50.00
4	TO REMOVE AND REFIT O/S REAR TYRE & RIM FOR REPLACEMENT,TO PERFORM TYRE BALANCING	New	50.00	20.00
5	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA/PANEL	New	1,000.00	400.00
6	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR	New	100.00	0.00
Gross Labour Cost (S\$)			2,650.00	920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >