

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000310/AVY3Q2**Date:** 30/05/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00031562100

**Claimant Vehicle
No :** FBF6201S**Insured Vehicle
No :** SKH4592J

Date of Loss: 04/01/2022

Nature of Claim: TP

Claim
No: SNM22D200175/C02LEEPG**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **FBF6201S**

Make & Model: YAMAHA X-1R, 135cc (M)

Engine No: 4S3304523

Reg. Date: 17/09/2011 (Man. Year: 2010)

Chassis No: 4S3304523

Colour: Blue

Odometer: 71314 km

Engine Capacity: 135 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 70/90 R17

Rear Tyre Size: 80/90 R17

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,116.00	4,991.70	1,124.30	18.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,170.00	870.00	300.00	25.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,286.00	5,861.70	1,424.30	19.55
Approved Total (Overridden) (\$\$)		4,700.00		
Nett Amount (\$\$)	7,286.00	4,700.00	2,586.00	35.49

INSPECTION

Date of Assignment: 11/01/2022

Date Inspected: 11/01/2022 Inspected At:

JEC AUTO SERVICE PTE LTD (HQ)
1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 May 2022)	
Parts:	N/A	YAMAHA X-1R 135cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBF6201S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Cut	15.00 FS	*15.00 FS
2	1		*FRONT NUMBER PLATE GARNISH	Cut	75.00 F	*75.00 FL
3	1		*FRONT WHEEL FENDER	Cut	88.00 F	*88.00 FL
4	1		*HEADLAMP	Cut	195.00 F	*195.00 FL
5	1		*HEADLAMP BRACKET	Not Necessary	25.00 F	*- FL
6	1		*HEADLAMP COWLING	Cut	182.00 F	*182.00 FL
7	1		*HEADLAMP COWLING CENTRE BLACK GARNISH	Not Necessary	93.00 F	*- FL
8	1		*HANDLE BAR	Bent	154.00 F	*154.00 FL
9	1		*SET HANDLE BAR END	Bent	75.00 F	*75.00 FL
10	1		*HANDLE GRIP LH	Cut	35.00 F	*35.00 FL
11	1		*HANDLE LEVER SYSTEM LH (BREMBO)	Damaged	500.00 FS	*450.00 FS
12	1		*BALANCER LH	Missing	38.00 F	*38.00 FL
13	1		*BRAKE RESERVOIR	Cracked	480.00 FS	*400.00 FS
14	1		*FRONT WHEEL RIM	Cut	380.00 FS	*280.00 FS
15	1		*FRONT WHEEL RIM SPINDLE	Bent	50.00 F	*50.00 FL
16	1		*FRONT TYRE	Not Necessary	180.00 FS	*- FS
17	1		*FORK ASSY	Damaged	630.00 F	*630.00 FL
18	1		*FRONT WHEEL BRACKET	Damaged	245.00 F	*245.00 FL
19	1		*FORK OIL	Necessary	30.00 FS	*30.00 FS
20	1		*FORK OIL SEAL	Necessary	50.00 FS	*50.00 FS
21	1		*SPEEDOMETER	Cracked	358.00 F	*358.00 FL
22	1		*FRONT BASKET	Dented	45.00 F	*45.00 FL
23	1		*SET WING MIRROR	Damaged	55.00 F	*55.00 FL
24	1		*HEADLAMP COWLING INNER GARNISH LH	Cracked	108.00 F	*108.00 FL
25	1		*SIDE FAIRING LH	Cut	138.00 F	*138.00 FL
26	1		*SIDE FAIRING SIGNAL LAMP LH	Cut	38.00 F	*38.00 FL
27	1		*FOOT LOWER LH	Bent	62.00 F	*62.00 FL
28	1		*FOOT REST RUBBER LH	Cut	28.00 F	*28.00 FL
29	1		*FOOT REST BRACKET	Bent	98.00 F	*98.00 FL
30	1		*ENGINE COVER	Cut	288.00 F	*288.00 FL
31	1		*ENGINE COVER GASKET	Necessary	40.00 FS	*40.00 FS
32	1		*REAR FOOT REST LH	Cut	28.00 F	*28.00 FL
33	1		*REAR FOOT REST BRACKET LH	Not Necessary	52.00 F	*- FL
34	1		*REAR SWING ARM	Dented	395.00 F	*395.00 FL
35	1		*REAR SWING ARM SHAFT	Bent	55.00 F	*55.00 FL
36	1		*REAR BOX	Cut	280.00 FS	*250.00 FS
37	1		*REAR BOX BRACKET	Bent	280.00 FS	*200.00 FS
38	1		*REAR LH FAIRING	Repair	88.00 F	*- FL
39	1		*ERP UNIT	Cut	160.00 FS	*160.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,116.00	5,338.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	346.30
Total Parts (\$)	6,116.00	4,991.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	400.00	300.00
2	SPRAY PAINTING	New	400.00	250.00
3	WIRING	New	50.00	30.00
4	TO REPAIR AND STRAIGHTEN BODY CHASSIS	New	280.00	250.00
5	TOWING CHARGES	New	40.00	40.00
Gross Labour Cost (\$)			1,170.00	870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >