

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22000321/KEA3Q2**Date:** 13/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7990000064
Claimant Vehicle No :	SLH4411L	Insured Vehicle No :	GBK3417E
Date of Loss:	07/01/2022	Nature of Claim:	TP
		Claim No:	0095024883SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH4411L	Engine No:	1NZ7949004
Make & Model:	TOYOTA AQUA, 1.5 E 1.5 SA (A)	Chassis No:	NHP102544035
Reg. Date:	02/11/2016 (Man. Year: 2016)	Odometer:	335067 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	INTERTRAC 8 mm	Rear Left Side:	Sunny 7 mm
Front Right Side:	INTERTRAC 8 mm	Rear Right Side:	Sunny 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,130.20	2,927.52	202.68	6.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,630.00	1,000.00	630.00	38.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,760.20	3,927.52	832.68	17.49
Approved Total (Overridden) (S\$)		3,100.00		
(S\$)	4,760.20	3,100.00	1,660.20	34.88
+ GST 7.00/7.00% (S\$)	333.21	217.00	116.21	34.88
Nett Amount (S\$)	5,093.41	3,317.00	1,776.41	34.88
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		60.00		
Nett Liability (S\$)		3,684.45		
Global Sum Settlement (S\$)		3,680.00		

INSPECTION

Date of Assignment:	10/01/2022		
Date Inspected:	10/01/2022	Inspected At:	Optima Werkz Pte Ltd (HQ) 6 Kung Chong Road Singapore 159143
Estimated Period of Repair:	4.0 days		

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	1,124.50 FL	*1,124.50 FL
2	1		*FRONT BUMPER SIDE BRACKET RH	Distorted	67.60 FL	*67.60 FL
3	1		*FRONT BUMPER FOG LAMP GARNISH COVER RH	Mtg Distorted	198.30 FL	*198.30 FL
4	1		*FRONT BUMPER FOG LAMP RH	Cut	341.20 FL	*341.20 FL
5	1		*FRONT HEADLAMP RH	Cracked	1,374.30 FL	*1,374.30 FL
6	1		*FRONT FENDER RH	Bent	682.50 FL	*682.50 FL
7	1		*FRONT FENDER HYBRID EMBLEM RH	Necessary	48.30 FL	*48.30 FL
8	1		*FRONT FENDER INNER SHIELD RH	Serviceable	216.90 FL	*- FL
9	1		*FRONT DOOR RH (NPA)	Repair	0.00 FL	*- FL
10	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
11	1		*FRONT FENDER INNER SHIELD CLIPS RH	Not Necessary	40.00 FS	*- FS
					Sub Total (\$\$)	4,143.60 3,886.70
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,013.40 959.18
					Total Parts (\$\$)	3,130.20 2,927.52

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,REPLACE,REPAIR ,REFIX & READJUST FRONT ACCIDENT AREAS & ETC	New	700.00	400.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER ,FRONT FENDER RH ,FRONT DOOR RH & ETC	New	700.00	550.00
3	TO TUFF KOTE & UNDERSEAL MATERIALS	New	150.00	30.00
4	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	80.00	20.00
Gross Labour Cost (\$)			1,630.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >