

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22000323/KEA3Q2**Date:** 13/05/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993549
<b>Claimant Vehicle No :</b>	SMN1272Y	<b>Insured Vehicle No :</b>	SMD8625U
Date of Loss:	06/01/2022	Nature of Claim:	TP
		Claim No:	0382081011SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMN1272Y</b>	Engine No:	27492031626105
Make & Model:	MERCEDES-BENZ E200 AMG LINE, 2.0 (A)	Chassis No:	WDD2130422A538780
Reg. Date:	25/07/2019 (Man. Year: 2018)	Odometer:	16431 km
Colour:	Metallic Black		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	245/45Z R19	Rear Tyre Size:	275/40Z R19
Front Left Side:	SUNWIDE 8 mm	Rear Left Side:	SUNWIDE 8 mm
Front Right Side:	SUNWIDE 8 mm	Rear Right Side:	SUNWIDE 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,413.00	3,272.00	2,141.00	39.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,960.00	545.00	1,415.00	72.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,373.00</b>	<b>3,817.00</b>	<b>3,556.00</b>	<b>48.23</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,050.00</b>		
<b>(S\$)</b>	7,373.00	3,050.00	4,323.00	58.63
<b>+ GST 7.00/7.00% (S\$)</b>	516.11	213.50	302.61	58.63
<b>Nett Amount (S\$)</b>	<b>7,889.11</b>	<b>3,263.50</b>	<b>4,625.61</b>	<b>58.63</b>
<b>+ Loss of Use (5.0 x S\$100.00/day) (S\$)</b>		500.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>+ Other Costs (S\$)</b>		100.00		
<b>Nett Liability (S\$)</b>		<b>3,870.95</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,870.00</b>		

**INSPECTION**

Date of Assignment:	10/01/2022		
Date Inspected:	10/01/2022	Inspected At:	Optima Werkz Pte Ltd (HQ) 6 Kung Chong Road Singapore 159143
Estimated Period of Repair:	3.0 days		

**Adjuster:** KENNETH KONG**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	2,250.00 FL	*1,615.00 FL
2	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	85.00 FL	*- FL
3	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	85.00 FL	*- FL
4	1		*REAR BUMPER LOWER BUMPER	Dented	445.00 FL	*445.00 FL
5	1		*REAR BUMPER LOWER CHROME MOULDING	Mtg Cracked	365.00 FL	*315.00 FL
6	2		*REAR BUMPER REVERSE SENSOR	Shorted	440.00 FL	*440.00 FL
7	1		*REAR BUMPER REFLECTOR LH	Mtg Cracked	65.00 FL	*65.00 FL
8	1		*REAR BUMPER REFLECTOR RH	Serviceable	65.00 FL	*- FL
9	1		*REAR EXHAUST TIP CHROME LH	Serviceable	190.00 FL	*- FL
10	1		*REAR EXHAUST TIP CHROME RH	Serviceable	190.00 FL	*- FL
11	1		*REAR REINFORCEMENT	Bent	600.00 FL	*600.00 FL
12	1		*END PANEL	Repair	750.00 FL	*- FL
13	1		*END PANEL TOP COVER	Serviceable	140.00 FL	*- FL
14	1		*BOOTLID (NPA)	Repair	0.00 FL	*- FL
15	1		*REAR BUMPER CLIPS	Necessary	100.00 FS	*100.00 FS
16	1		*REAR END PANEL JOINT SEALANT	Not Necessary	120.00 FS	*- FS
17	1		*REAR BUMPER CHROME MOULDING CLIPS	Necessary	40.00 FS	*40.00 FS
18	1		*END PANEL TOP COVER CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>5,980.00</b>	<b>3,620.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	567.00	348.00
<b>Total Parts (\$)</b>	<b>5,413.00</b>	<b>3,272.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX REPAIR & READJUST REAR ACCIDENT	New	700.00	250.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER ,REAR END PANEL & ETC	New	800.00	220.00
3	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC	New	120.00	60.00
4	TO DIAGNOSIS FAULT CODE & RESET MEMORY	New	120.00	0.00
5	TO TUFF COAT AND UNDERSEAL MATERIAL	New	120.00	0.00
6	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	100.00	15.00
			<b>Gross Labour Cost (\$)</b>	<b>1,960.00</b>
				<b>545.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >