

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22000338/Gty3e2	
	8 SHENTON WAY SINGAPORE 0688		Date:	17/01/2022		
	ATTN: WINNIE HC			Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SNB 8238C	Veh. Inspected	t	SGZ 8733X	
	Policy No.	GA581358	Coverage (\$)		0.00	
	Claim No.	S2M03QN1	Excess (\$)		0.00	
	Assign From	WINNIE HO	Assign Date		11/01/2022	
2.	. Vehicle Particulars & Condition					
	Make & Model	HONDA JAZZ 1.4	c.c		1339	
	Engine No.	HIDDEN	Year of Reg.		2007	
	Chassis No.	JHMGD18507S233457	Colour		BLUE	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/50 R15	FALKEN		6 mm	
	L/H Front Tyre	195/50 R15	FALKEN		6 mm	
	R/H Rear Tyre	195/50 R15	FALKEN		6 mm	
	L/H Rear Tyre	195/50 R15	FALKEN		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.					
5.	5. General Information					
	Accident Date	08/01/2022	Inspect Date /	Time	11/01/2022 (04:30 PM)	
	Survey held at	GARAGE 13 PTE LTD				
	8 KAKI BUKIT AVE 4 #03-46 PREMIER SINGAPORE 415875					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					

Report Ref No. CS3/ASM22000338/Gty3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor