

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000343/ATY3N2**Date:** 18/02/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00050542100	
Claimant Vehicle No :	SMF5063A	Insured Vehicle No :	SJW4853P	
Date of Loss:	07/01/2022	Nature of Claim:	TP	Claim No: SNM22D200203/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF5063A		Engine No:	G4FGJU274399
Make & Model:	HYUNDAI ELANTRA, 1.6 (A)		Chassis No:	KMHD841CMJU764377
Reg. Date:	15/11/2018 (Man. Year: 2018)		Odometer:	174266 km
Colour:	Grey			
Engine Capacity:	1591 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,260.62	10,845.98	3,414.64	23.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,800.00	3,220.00	1,580.00	32.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	19,060.62	14,065.98	4,994.64	26.20
Approved Total (Overridden) (\$\$)		11,200.00		
Nett Amount (\$\$)	19,060.62	11,200.00	7,860.62	41.24

INSPECTION

Date of Assignment:	11/01/2022	
Date Inspected:	10/01/2022	Inspected At: Eunos Motor Service (HQ) 1 Kaki Bukit Ave 6, #01-64 AutoBay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	12.0 days	

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Feb 2022)
Parts:	143	HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMF5063A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Distorted	1,782.40 FL	*1,782.40 FL
2	2		*REAR BOOTLID HINGE	Bent	188.60 FL	*188.60 FL
3	1		*REAR BOOTLID LOCK	Jammed	116.20 FL	*116.20 FL
4	1		*REAR BOOTLID RUBBER	Cut	95.20 FL	*95.20 FL
5	1		*REAR BOOTLID EMBLEM (H)	Necessary	27.98 FL	*27.98 FL
6	1		*REAR BOOTLID EMBLEM ELANTRA	Necessary	8.80 FL	*8.80 FL
7	2		*REAR BOOTLID LAMP	Cracked	569.80 FL	*569.80 FL
8	2		*REAR NUMBER PLATE LAMP	Not Necessary	42.00 FL	*- FL
9	1		*REAR FENDER RH	Repair	1,768.30 FL	*- FL
10	2		*REAR FENDER LAMP	Cracked	725.20 FL	*725.20 FL
11	1		*REAR BOOTLID INNER COVER	Crumpled	146.80 FL	*146.80 FL
12	1		*REAR BUMPER	Distorted	459.40 FL	*459.40 FL
13	2		*REAR BUMPER SIDE RETAINER	Necessary	88.60 FL	*88.60 FL
14	2		*REAR BUMPER REFLECTOR	Cracked	65.80 FL	*65.80 FL
15	1		*REAR BUMPER CLIP	Necessary	53.90 FL	*30.00 FL
		(11 Pcs)				
16	1		*REAR BUMPER REINFORCEMENT	Distorted	320.60 FL	*320.60 FL
17	1		*REAR LOWER BUMPER	Deformed	250.10 FL	*250.10 FL
18	1		*REAR END PANEL	Distorted	454.60 FL	*454.60 FL
19	1		*REAR END PANEL TOP GARNISH COVER	Deformed	59.80 FL	*59.80 FL
20	1		*REAR SPARE TYRE PANEL	Repair	640.80 FL	*- FL
21	1		*REAR BUMPER LOW COVER LH	Not Necessary	260.20 FL	*- FL
22	1		*REAR EXHAUST	Bent	688.40 FL	*688.40 FL
23	2		*SIDE FENDER GARNISH	Torn	415.80 FL	*415.80 FL
24	1		*TYRE FLOOR	Not Necessary	219.10 FL	*- FL
25	1		*FRONT BONNET	Dented	1,910.30 FL	*1,741.00 FL
26	2		*FRONT BONNET HINGE	Not Necessary	98.20 FL	*- FL
27	1		*FRONT BONNET LOCK	Damaged	129.90 FL	*129.90 FL
28	1		*FRONT BONNET INSULATOR	Not Necessary	221.10 FL	*- FL
29	14		*FRONT BONNET INSULATOR CLIP	Not Necessary	82.60 FL	*- FL
30	1		*FRONT BUMPER	Deformed	474.40 FL	*474.40 FL
31	2		*FRONT BUMPER SIDE RETAINER	Necessary	56.00 FL	*56.00 FL
32	2		*FRONT BUMPER SIDE SMALL GRILLE	Not Necessary	70.00 FL	*- FL
33	1		*FRONT GRILLE ASSY }	Cracked	529.50 FL	*529.50 FL
34	1		*FRONT GRILLE EMBLEM }	Cracked	0.00 FL	*- FL
35	1		*FRONT BUMPER RUBBER	Not Necessary	31.40 FL	*- FL
36	1		*FRONT SUPPORT PANEL	Cracked	949.30 FL	*845.00 FL
37	1		*FRONT SUPPORT PANEL TOP GARNISH COVER	Not Necessary	78.10 FL	*- FL
38	6		*FRONT SUPPORT PANEL TOP GARNISH CLIP	Not Necessary	29.40 FL	*- FL
39	2		*HEAD LAMP ASSY RH/LH	Cracked	2,397.60 FL	*2,397.60 FL
40	1		*FRONT BUMPER REINFORCEMENT	Dented	695.80 FL	*515.00 FL
41	1		*FRONT BUMPER LOWER COVER	Not Necessary	63.70 FL	*- FL
42	1		*REAR REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
43	2		*FRONT/REAR NUMBER PLATE	Dented	100.00 FS	*100.00 FS
44	1		*RADIATOR BRACKET	Not Necessary	85.10 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Sub Total (S\$)	17,730.78	13,482.48
				- List Item Discount on L Items 20.00/20.00% (S\$)	3,470.16	2,636.50
				Total Parts (S\$)	14,260.62	10,845.98

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE EXHAUST PIPE	New	150.00	80.00
2	TO REMOVE CUSHION	New	80.00	80.00
3	TO CHECK WIRING	New	120.00	60.00
4	PANEL BEATING & REPLACE PARTS-FRONT	New	1,050.00	600.00
5	PANEL BEATING & REPLACE PARTS-REAR	New	1,800.00	1,000.00
6	SPRAY PAINTING FRONT/REAR PARTS	New	1,600.00	1,400.00
Gross Labour Cost (\$)			4,800.00	3,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >