

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM22000349/Gty3e2 8 SHENTON WAY #24-01 AXA TOWER Date: 27/01/2022 SINGAPORE 068811 ATTN: STACEY NG Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SHC 3131A** Veh. Inspected SJX 1744K Policy No. Coverage (\$) 0.00 Claim No. S2M03QQ7 Excess (\$) 0.00 **Assign Date** STACEY NG 11/01/2022 Assign From 2. **Vehicle Particulars & Condition** TOYOTA COROLLA FIELDER 1496 Make & Model c.c 1.5X Engine No. **HIDDEN** Year of Reg. 2008 Chassis No. NZE1449013995 Colour BLACK 183182 KM **IN ORDER** Odometer Steering **IN ORDER** STANDARD ALLOY RIM **Brakes** Modification GOOD General **Conditions of Tyres** 3. Size Make **Balance** 205/60 R16 CONTINENTAL 6 mm R/H Front Tyre CONTINENTAL L/H Front Tyre 205/60 R16 6 mm R/H Rear Tyre 205/60 R16 CONTINENTAL 6 mm 205/60 R16 CONTINENTAL L/H Rear Tyre 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. 5. **General Information Accident Date** 10/01/2022 **Inspect Date / Time** 14/01/2022 (12:00 PM) 06-46 SYNERY BUILDING Survey held at TRIPLE-T AUTOMOBILE Repairer 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000

Report Ref No. CS3/ASM22000349/Gty3e2

Estimate Days of Repair

Inspected By

ESTIMATED NORMAL PERIOD FOR REPAIR:

5b.

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

4 Working Days

Automotive Assessor