

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22000358/KTY3E2

Date: 24/05/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00042762100
Claimant Vehicle No: SME482L Insured Vehicle No: SMJ5061J
Date of Loss: 08/01/2022 Nature of Claim: TP Claim No: SNM22D200205/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SME482L
Make & Model: TOYOTA PRIUS, 1.6 (A) Engine No: 2ZR0C37910
Reg. Date: 17/09/2018 (Man. Year: 2018) Chassis No: JTDZS3EU40J032300
Colour: Metallic Red Odometer: 34783 km
Engine Capacity: 1798 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16
Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm
Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,752.50	6,114.00	18,638.50	75.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,150.00	1,980.00	1,170.00	37.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	27,902.50	8,094.00	19,808.50	70.99
+ GST 7.00/7.00% (S\$)	1,953.18	566.58	1,386.60	70.99
Nett Amount (S\$)	29,855.68	8,660.58	21,195.10	70.99

INSPECTION

Date of Assignment: 11/01/2022
Date Inspected: 11/01/2022 Inspected At: Accord Auto Services Pte Ltd (HQ)
10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point
Singapore 568047
Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 May 2022)
Parts:	144	TOYOTA PRIUS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SME482L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR TAIL GATE	Bent	1,096.00 F	*1,096.00 FL
2	1	*REAR TAIL GATE LOCK	Repair	425.00 F	*- FL
3	1	*REAR TAIL GATE LOGO	Not Necessary	92.00 F	*- FL
4	1	*REAR TAIL GATE LOGO PRUIS+	Necessary	90.00 F	*90.00 FL
5	1	*REAR TAIL GATE LOGO HYBRID	Necessary	90.00 F	*90.00 FL
6	1	*REAR TAILGATE CENTRE PANEL	Repair	461.00 F	*- FL
7	1	*REAR TAIL GATE INNER TRIM BOARD	Serviceable	440.00 F	*- FL
8	1	*REAR LAMP LH	Serviceable	670.00 F	*- FL
9	1	*REAR LAMP LOWER BRACKET LH	Cracked	62.00 F	*62.00 FL
10	1	*REAR LAMP RH	Serviceable	670.00 F	*- FL
11	1	*REAR LAMP LOWER BRACKET RH	Serviceable	62.00 F	*- FL
12	1	*REAR BUMPER	Buckled	549.00 F	*549.00 FL
13	2	*REAR BUMPER SIDE RETAINER	Distorted	288.00 F	*288.00 FL
14	1	*REAR BUMPER LOWER	Dented	726.00 F	*726.00 FL
15	1	*REAR REFLECTOR LH	Serviceable	60.00 F	*- FL
16	1	*REAR REFLECTOR RH	Serviceable	60.00 F	*- FL
17	1	*REAR WEATHERDHIELD	Serviceable	360.00 F	*- FL
18	1	*REAR END PANEL	Repair	696.00 F	*- FL
19	1	*REAR END PANEL GARNISH	Serviceable	176.00 F	*- FL
20	1	*REAR FENDER LH	Repair	824.00 F	*- FL
21	1	*REAR FENDER SHIELD LH	Serviceable	186.00 F	*- FL
22	1	*REAR FENDER RH	Repair	824.00 F	*- FL
23	1	*REAR FENDER SHEILD RH	Serviceable	186.00 F	*- FL
24	1	*FRONT BONNET	Bent	993.00 F	*993.00 FL
25	2	*FRONT BONNET HINGE	Distorted	40.00 F	*40.00 FL
26	1	*FRONT HEADLAMP LH	Mtg Cracked	40.00 F	*40.00 FL
27	1	*FRONT HEADLAMP LOWER BRACKET LH	Serviceable	75.00 F	*- FL
28	1	*FRONT HEADLAMP RH	Mtg Cracked	2,526.00 F	*2,526.00 FL
29	1	*FRONT HEADLAMP LOWER BRACKET RH	Serviceable	75.00 F	*- FL
30	1	*FRONT BUMPER	Bent	556.00 F	*556.00 FL
31	1	*FRONT GRILLE CENTRE	Cracked	481.00 F	*481.00 FL
32	1	*FRONT GRILLE LOWER	Serviceable	550.00 F	*- FL
33	1	*FRONT EMBLEM	Necessary	85.00 F	*85.00 FL
34	1	*FRONT FOGLAMP LH	Serviceable	355.00 F	*- FL
35	1	*FRONT FOGLAMP RH	Serviceable	355.00 F	*- FL
36	1	*FRONT SIGNAL LAMP LH *BUMPER	Serviceable	617.00 F	*- FL
37	1	*FRONT SIGNAL LAMP RH *BUMPER	Serviceable	617.00 F	*- FL
38	1	*FRONT REIMFORCEMENT	Repair	656.00 F	*- FL
39	2	*FRONT REINFORCEMER ARM	Serviceable	500.00 F	*- FL
40	1	*FRONT SUPORT PANEL	Serviceable	1,464.00 F	*- FL
41	1	*FRONT NUMBER PLATE GARNISH	No such part	90.00 F	*- FL
42	1	*REVERSE SENSOR	Dented	360.00 FS	*200.00 FS
43	2	*SET REAR END PANEL GARNISH CLIPS	Not Necessary	45.00 FS	*- FS
44	1	*SET REAR BUMPER CLIPS & REAR FENDER SHIELD CLIPS	Necessary	60.00 FS	*60.00 FS
45	1	*SET REAR TAILGATE GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
46	1	*SET REAR NUMBER PLATE WITH FRAME	Serviceable	50.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*SET FRONT BUMPER & FRONT FENDER SHIELD CLIPS	Not Necessary	60.00 FS	*- FS
48	1		*SET FRONT NUMBER PLATE WITH FRAME	Bent	50.00 FS	*45.00 FS
49	1		*SET REAR TAIL GATE GLASS MOULDING	Necessary	70.00 F	*70.00 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					19,943.00	8,037.00
- List Item Discount on L Items 0.00/25.00% (\$)					0.00	1,923.00
+ Margin on L,N Items 25.00/0.00% (\$)					4,809.50	0.00
Total Parts (\$)					24,752.50	6,114.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINT ON ALL AFFECTED AREA (FRONT & REAR)	New	1,000.00	1,000.00
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	1,000.00	700.00
3	TO CHECK WIRING SYSTEM & LIGHT	New	100.00	40.00
4	TO APPLY ANTI RUST TREATMENT	New	120.00	60.00
5	TO REMOVE/REFIX REVERSE SENSOR	New	150.00	50.00
6	TO REMOVE/REFIX REAR INNER COMPARTMENT TO FACILITIES REPAIR	New	150.00	50.00
7	TO REMOVE/REFIX REAR TAILGATE, TOP SPOILER, WIPER MOTOR, MECEMISM & ETC TO NEW TAILGATE	New	300.00	60.00
8	TO CHECK WATER LEAKING	New	150.00	20.00
9	TO REMOVE/REFIX/REPLACE REVERSE SENSOR	New	180.00	0.00
Gross Labour Cost (\$\$)			3,150.00	1,980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >