

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS22000359/UVY3N2**Date:** 18/01/2022REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	MPC21A00078800
Claimant Vehicle No :	GBE960D	Insured Vehicle No :	SKL2751J
Date of Loss:	07/01/2022	Nature of Claim:	TP
		Claim No:	DMPC2200008H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE960D	Engine No:	1KD2551188
Make & Model:	TOYOTA DYNA 1.5T, 3.0 (A)	Chassis No:	JTFAT35Y20K204886
Reg. Date:	31/08/2015 (Man. Year: 2015)	Odometer:	253341 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15	Rear Tyre Size:	155R12(D)
Front Left Side:	Condor 6 mm	Rear Left Side:	Condor 6/6 mm
Front Right Side:	Condor 6 mm	Rear Right Side:	Condor 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	792.50	468.32	324.18	40.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,460.00	840.00	620.00	42.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,252.50	1,308.32	944.18	41.92
Approved Total (Overridden) (S\$)		1,000.00		
Nett Amount (S\$)	2,252.50	1,000.00	1,252.50	55.60

INSPECTION

Date of Assignment:	11/01/2022	Soc Leon Motor Works (Kaki Bukit)
Date Inspected:	12/01/2022	Inspected At: 1 Kaki Bukit Ave 6, #01-91, AutoBay@Kaki Bukit
Estimated Period of Repair:	2.0 days	Singapore 417883

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 18 Jan 2022)	
Parts:	N/A	TOYOTA DYNA 1.5T 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE960D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILLAMP (RH)	Cracked	320.00 FL	*251.10 FL
2	1		*TAILLAMP BRACKET	Repair	190.00 FL	*- FL
3	1		*SET REVERSE SENSOR	Shorted	260.00 FS	*200.00 FS
4	1		*SET REFLECTOR STICKER	Damaged	150.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	920.00	531.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	127.50	62.78
Total Parts (\$\$)	792.50	468.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & FIX REVERSE SENSOR	New	60.00	40.00
2	TO REPAIR TAILGATE BRACKET & HYDRAULIC JET }	New	1,200.00	800.00
3	TO KNOCK & REPLACE PARTS }	New	200.00	0.00
Gross Labour Cost (\$\$)			1,460.00	840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >