8/2/22, 11:25 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III22000360/UGA3Q2

02/08/2022 Date:

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D18MFL0003414_02

Claimant Vehicle SGB6633R Insured Vehicle No: SNC819Z

No:

Date of Loss: 10/01/2022 Nature of Claim: TP Claim No: MFL2022D0000491

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGB6633R**

Make & Model: BMW 730LI, 2.0 LED NAV HUD SR (A) 13315112B48B20B Engine No: Reg. Date: 26/02/2018 (Man. Year: 2017) Chassis No: WBA7E02090G245400

Colour: Odometer: 72740 km Brown

Engine Capacity: 1998 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size: 245/50 R18 Rear Tyre Size: 245/50 R18 Front Left Side: Rear Left Side: Bridgestone 6 mm Bridgestone 6 mm Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,865.88	9,471.29	2,394.59	20.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,780.00	1,170.00	610.00	34.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,645.88	10,641.29	3,004.59	22.02
Approved Total (Overridden) (S\$)		8,500.00		
Nett Amount (S\$)	13,645.88	8,500.00	5,145.88	37.71
Global Sum	Settlement (S\$)	0.00		

INSPECTION

11/01/2022 Date of Assignment:

Choo Motor Spray Painter (HQ)

1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Date Inspected: 11/01/2022 Inspected At:

Bukit

Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Aug 2022)

Parts: 143 BMW 730LI 2.0 LED NAV HUD SR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGB6633R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars		Condition	Repairer's	Amount
1	1		*FRONT BUMPER		Distorted	1,861.21 F	*1,861.21 FL
2	1		*FRONT BUMPER SIDE RETAIN!	ER N/S	Cracked	98.32 F	*98.32 FL
3	2		*FRONT BUMPER PDC SENSOR	N/S	Shorted	324.00 F	*324.00 FL
4	1		*FRONT BUMPER CHROME MO	JLDING	Cracked	231.25 F	*231.25 FL
5	1		*FRONT BUMPER LOWER CHRO	OME MOULDING N/S	Scratched	145.00 F	*145.00 FL
6	1		*FRONT BUMPER FOG LAMP N/	S	Not Necessary	450.00 F	*- FL
7	1		*SET FRONT BUMPER CLIPS &	RIVET	Necessary	50.00 F	*50.00 FL
8	1		*HEADLAMP N/S		Broken	6,500.00 F	*5,947.00 FL
9	1		*FRONT FENDER N/S		Buckled	1,018.00 F	*1,018.00 FL
10	1		*FRONT FENDER INNER SHIELD	N/S	Torn	288.10 F	*245.00 FL
11	1		*SET FRONT FENDER INNER SH	IIELD CLIPS N/S	Necessary	50.00 F	*50.00 FL
12	1		*FRONT SPORT RIM N/S		Repair	850.00 F	*- FL
F=Fra	nchise	part. L=ListIt	emDisc.		_		
					Sub Total (S\$)	11,865.88	9,969.78
			-1	ist Item Discount on L Item	s 0.00/5.00% (S\$)	0.00	498.49

Report was unsubmitted during this print-out.

Total Parts (S\$)

11,865.88

9,471.29

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

Particulars	Lab.Type	Repairer's	Amount
our Items			
TO CHECK WIRING	New	50.00	20.00
TO DISMANTLE & REPLACED FRT PDC SENSOR	New	80.00	50.00
TO RESET & REPROGRAMME SYSTEM	New	100.00	60.00
TO SPRAY RUST PROOFING	New	50.00	30.00
TO CONDUCT WHEEL ALIGNMENT	New	100.00	60.00
LABOUR FOR PANEL BEATING & REPLACED PARTS	New	600.00	450.00
TO PUTTY & SPRAY PAINTING	New	800.00	500.00
	Gross Labour Cost (S\$)	1,780.00	1,170.00
	OUIT ITEMS TO CHECK WIRING TO DISMANTLE & REPLACED FRT PDC SENSOR TO RESET & REPROGRAMME SYSTEM TO SPRAY RUST PROOFING TO CONDUCT WHEEL ALIGNMENT LABOUR FOR PANEL BEATING & REPLACED PARTS	OUR Items TO CHECK WIRING TO DISMANTLE & REPLACED FRT PDC SENSOR New TO RESET & REPROGRAMME SYSTEM New TO SPRAY RUST PROOFING New TO CONDUCT WHEEL ALIGNMENT LABOUR FOR PANEL BEATING & REPLACED PARTS New TO PUTTY & SPRAY PAINTING	Our Items TO CHECK WIRING New 50.00 TO DISMANTLE & REPLACED FRT PDC SENSOR New 80.00 TO RESET & REPROGRAMME SYSTEM New 100.00 TO SPRAY RUST PROOFING New 50.00 TO CONDUCT WHEEL ALIGNMENT New 100.00 LABOUR FOR PANEL BEATING & REPLACED PARTS New 600.00 TO PUTTY & SPRAY PAINTING New 800.00

Report was unsubmitted during this print-out. < END OF ESTIMATES >