

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS22000362/UVY3N2**Date:** 28/02/2022REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	MPC21P00106300
Claimant Vehicle No :	JPQ7868	Insured Vehicle No :	SLP3084L
Date of Loss:	03/01/2022	Nature of Claim:	TP
		Claim No:	DMPC2200002H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	JPQ7868	Engine No:	R65A60J
Make & Model:	PERODUA MYVI, 1.5 SE (A)	Chassis No:	PM2M603S002085586
Reg. Date:	03/10/2013 (Man. Year: 2013)	Odometer:	214321 km
Colour:	Silver		
Engine Capacity:	1495 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/65R14	Rear Tyre Size:	175/65R14
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,997.58	4,945.16	1,052.42	17.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,740.00	2,690.00	2,050.00	43.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,737.58	7,635.16	3,102.42	28.89
Approved Total (Overridden) (S\$)		6,100.00		
(S\$)	10,737.58	6,100.00	4,637.58	43.19
+ GST 7.00/7.00% (S\$)	751.63	427.00	324.63	43.19
Nett Amount (S\$)	11,489.21	6,527.00	4,962.21	43.19

INSPECTION

Date of Assignment:	11/01/2022		
Date Inspected:	11/01/2022	Inspected At:	Precise Auto Service (HQ) No 1 Kaki Bukit Ave 6, #02-34/36 Singapore 417883
Estimated Period of Repair:	10.0 days		

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Feb 2022)
Parts:	144	PERODUA MYVI 1.5 SE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for JPQ7868)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Badly Dented	750.00 FL	*750.00 FL
2	2		*TAIL GATE HINDGE	Not Necessary	120.00 FL	*- FL
3	2		*TAIL GATE ABSORBER	Not Necessary	282.00 FL	*- FL
4	1		*TAIL GATE LOCK	Shorted/Damaged	48.40 FL	*48.40 FL
5	1		*TAIL GATE LOCK STRIKER	Not Necessary	31.00 FL	*- FL
6	1		*TAIL GATE WEATHER STRIPE	Twisted	145.00 FL	*145.00 FL
7	2		*TAIL GATE STOPPER	Not Necessary	18.00 FL	*- FL
8	1		*TAIL GATE INNER TRIM BOARD	Not Necessary	161.80 FL	*- FL
9	8		*TAIL GATE INNER TRIM BOARD CLIPS	Not Necessary	32.00 FL	*- FL
10	1		*TAIL GATE OUTER GARNISH	Not Necessary	140.00 FL	*- FL
11	4		*TAIL GATE OUTER GARNISH CLIPS	Not Necessary	16.00 FL	*- FL
12	1		*TAIL GATE EMBLEM MYVI	Necessary	40.00 FL	*40.00 FL
13	1		*TAIL GATE EMBLEM SE 1.5	Necessary	40.00 FL	*40.00 FL
14	1		*TAIL GATE BADGE	Not Necessary	45.00 FL	*- FL
15	10		*REAR WINDSCREEN GLSSS CLIPS	Not Necessary	40.00 FL	*- FL
16	2		*REAR NUMBER PLATE LAMP	Not Necessary	36.00 FL	*- FL
17	2		*TAIL LAMP	Cracked	760.00 FL	*760.00 FL
18	4		*TAIL LAMP CLIPS	Not Necessary	16.00 FL	*- FL
19	1		*REAR BUMPER	Distorted	380.00 FL	*380.00 FL
20	2		*REAR BUMPER SIDE RETAINER	Bent	98.00 FL	*98.00 FL
21	2		*REAR BUMPER BRACKET	Bent	84.00 FL	*84.00 FL
22	2		*REAR BUMPER REFLECTOR	Cracked	120.00 FL	*120.00 FL
23	2		*REAR BUMPER PARKING SENSOR	Shorted	180.00 FL	*180.00 FL
24	1		*REAR END PANEL	Badly Dented	462.00 FL	*462.00 FL
25	1		*REAR END PANEL TOP TRIM	Twisted	120.00 FL	*120.00 FL
26	4		*REAR END PANEL TOP TRIM CLIPS	Not Necessary	16.00 FL	*- FL
27	1		*REAR FLOOR PANEL	Crumpled/Buckled	682.00 FL	*682.00 FL
28	1		*REAR FLOOR PANEL INSULATOR CLOTH	Necessary	150.00 FL	*150.00 FL
29	1		*REAR FLOOR PANEL BOARD	Torn	237.00 FL	*237.00 FL
30	2		*REAR FENDER INNER TRIM BOARD	Deformed/Torn	440.00 FL	*440.00 FL
31	12		*REAR FENDER INNER TRIM BOARD CLIPS	Necessary	48.00 FL	*48.00 FL
32	1		*EXHAUST SILENCER WITH CENTER PIPE	Bent/Twisted	588.00 FL	*588.00 FL
33	1		*REAR WINDSCREEN GLASS INNER SEAL	Necessary	50.00 FS	*30.00 FS
34	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	60.00 FS	*40.00 FS
35	1		*REAR NUMBER PLATE }	Bent	45.00 FS	*40.00 FS
36	1		*REAR NUMBER PLATE CASING }		29.00 FS	*- FS
37	1		*EXHAUST SILENCER CHROME PIPE	Serviceable	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,630.20	5,482.40
- List Item Discount on L Items 10.00/10.00% (\$\$)	632.62	537.24
Total Parts (\$\$)	5,997.58	4,945.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	80.00	0.00
2	TO CHECK WIRING SYSTEM	New	80.00	20.00
3	TO TUFF COAT AFFECTED AREAS	New	180.00	80.00
4	TO REMOVE & REFIX INTERIOR UPHOLSTERY	New	120.00	80.00
5	TO REMOVE & REFIX TAIL GATE MECHANISM	New	200.00	60.00
6	TO REMOVE & REFIX REAR WINDSCREEN GLASS	New	180.00	120.00
7	TO REMOVE & REFIX REVERSE SENSOR	New	120.00	50.00
8	TO REMOVE & REFIX EXHAUST PIPE	New	250.00	80.00
9	TO ADJUST CHASSIS ALIGNMENT ON CAR O LINER	New	380.00	0.00
10	TO RESPRAY AFFECTED AREAS	New	1,500.00	1,000.00
11	TO RENEW DAMAGED PARTS,STRAIGHTEN & REPAIR REAR CHASSIS MEMBER,REAR FENDER AND ALIGNED ALL PARTS	New	1,650.00	1,200.00
Gross Labour Cost (\$\$)			4,740.00	2,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >