

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22000370/AEA3Q2**Date:** 16/09/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SJL3431M**Insured Vehicle No :** SJX8812B

Date of Loss: 08/01/2022

Nature of Claim: TP

Claim No: 0786635150SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJL3431M**

Make & Model: TOYOTA RAV4, 2.0 PREMIUM (A)

Engine No: 3ZRB925148

Reg. Date: 20/01/2017 (Man. Year: 2016)

Chassis No: JTMDEREVX0D108839

Colour: Maroon

Odometer: 92087 km

Engine Capacity: 1987 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/65 R17

Rear Tyre Size: 225/65 R17

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,709.02	5,050.30	14,658.72	74.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,080.00	2,200.00	3,880.00	63.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	25,789.02	7,250.30	18,538.72	71.89
Approved Total (Overridden) (\$\$)		5,800.00		
Nett Amount (\$\$)	25,789.02	5,800.00	19,989.02	77.51
+ Car Rental (4.0 x S\$120.00/day) (\$\$)		480.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		6,282.00		

INSPECTION

Date of Assignment: 11/01/2022

Date Inspected: 11/01/2022 Inspected At:

SM Automotive (HQ)

756 JURONG WEST STREET 74, #12-60

Singapore 640756

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,642.80 FL	*1,580.00 FL
2	1		*REAR TAILGATE LOCK	Damaged	800.20 FL	*485.00 FL
3	1		*REAR TAILGATE INNER TRIM BOARD	Not Necessary	568.70 FL	*- FL
4	1		*REAR TAILGATE LOWER GARNISH	Deformed	262.80 FL	*262.80 FL
5	1		*REAR TAILGATE OUTER GARNISH	Not Necessary	403.10 FL	*- FL
6	2		*REAR TAILGATE LAMP	Not Necessary	612.80 FL	*- FL
7	2		*REAR TAILGATE NUMBER PLATE LAMP	Not Necessary	75.20 FL	*- FL
8	2		*REAR TAILGATE SIDE SENSOR	Not Necessary	1,109.80 FL	*- FL
9	2		*REAR TAILGATE SIDE PANEL	Not Necessary	497.80 FL	*- FL
10	2		*REAR TAILGATE SHOCK ABSORBER	Not Necessary	634.40 FL	*- FL
11	1		*REAR TAILGATE WINDSCREEN GLASS MOULDING	Necessary	196.40 FL	*196.40 FL
12	1		*REAR TAILGATE LOCK HANDLER WITH SWITCH	Not Necessary	183.80 FL	*- FL
13	1		*REAR TAILGATE LOCK DETECTOR	Damaged	148.30 FL	*148.30 FL
14	1		*REAR TAILGATE AUTO LOCK MOTOR	Not Necessary	2,862.80 FL	*- FL
15	1		*REAR TAILGATE EMBLEM TOYOTA	Necessary	56.60 FL	*56.60 FL
16	1		*REAR TAILGATE EMBLEM RAV4	Necessary	65.70 FL	*65.70 FL
17	1		*REAR WEATHERSTRIPE	Cut	371.70 FL	*371.70 FL
18	1		*REAR BUMPER TOP	Deformed	625.20 FL	*625.20 FL
19	1		*REAR BUMPER CENTER	Deformed	330.90 FL	*330.90 FL
20	1		*REAR BUMPER DIFFUSER	Deformed	335.20 FL	*335.20 FL
21	4		*REAR BUMPER REVERSE SENSOR	Damaged (2 PCS ONLY)	1,571.20 FL	*520.00 FL
22	1		*REAR BUMPER REINFORCEMENT	Dented	358.60 FL	*358.60 FL
23	2		*REAR BUMPER SIDE RETAINER	Not Necessary	120.80 FL	*- FL
24	2		*REAR BUMPER LAMP	Not Necessary	381.60 FL	*- FL
25	1		*REAR END PANEL	Dented	489.40 FL	*489.40 FL
26	1		*REAR END PANEL TOP GARNISH	Deformed	251.40 FL	*251.40 FL
27	2		*REAR END PANEL TOP GARNISH AIR VENT	Not Necessary	103.20 FL	*- FL
28	1		*REAR SPARE TYRE TRIM BOARD	Not Necessary	746.30 FL	*- FL
29	1		*REAR SPARE TYRE COMPARTMENT PANEL SPONGE	Not Necessary	356.50 FL	*- FL
30	2		*REAR FENDER	Not Necessary	2,227.60 FL	*- FL
31	2		*REAR FENDER INNER TRIM BOARD	Not Necessary	1,319.60 FL	*- FL
32	2		*REAR FENDER INNER SIDE TRIM BOARD TOP	Not Necessary	337.60 FL	*- FL
33	2		*REAR FENDER INNER SIDE TRIM BOARD BOTTOM	Not Necessary	332.60 FL	*- FL
34	2		*REAR TAILLAMP	Not Necessary	674.40 FL	*- FL
35	2		*REAR TAILLAMP LOWER BRACKET	Not Necessary	125.60 FL	*- FL
36	1		*REAR EXHAUST MUFFLER	Not Necessary	986.40 FL	*- FL
37	1		*REAR SPARE TYRE COMPARTMENT PANEL	Not Necessary	1,050.60 FL	*- FL
38	1		*REAR SPARE TYRE LOCK NUT	Not Necessary	180.20 FL	*- FL
39	1		*REAR BUMPER UNDER LOWER GARNISH	Torn	212.40 FL	*212.40 FL
40	2		*REAR BUMPER REINFORCEMENT BRACKET	Dented	270.80 FL	*270.80 FL
41	1		*REAR KEYLESS SENSOR	Not Necessary	280.30 FL	*- FL
42	2		*REAR END PANEL AIR VENT	Not Necessary	380.20 FL	*- FL
43	2		*REAR EXHAUST MUFFLER RUBBER MOUNTING	Not Necessary	57.20 FL	*- FL
44	1		*REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
45	1		*REAR REVERSE CAMERA	Not Necessary	450.00 FS	*- FS
46	1		*REAR TAILGATE WINDSCREEN GLASS SEALANT	Necessary	120.00 FS	*60.00 FS
47	2		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
48	1		*REAR NUMBER PLATE WITH CASING	Not Necessary	60.00 FS	*- FS
49	2		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	60.00 FS	*- FS
50	1		*REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*30.00 FS
51	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*10.00 FS
52	1		*REAR FLOOR PANEL INSULATOR	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 25,558.70 6,690.40
- List Item Discount on L Items 25.00/25.00% (\$\$) 6,149.68 1,640.10

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)						19,709.02
						5,050.30
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING	New	2,400.00	900.00
2	LABOUR FOR SPRAY PAINTING	New	1,600.00	900.00
3	WIRING CHECK	New	80.00	30.00
4	LABOUR FOR REMOVE & REFIX REAR WINDSCREEN GLASS	New	150.00	120.00
5	LABOUR FOR REMOVE & REFIX REAR UPHOSLTERY /ROOF LINING	New	300.00	60.00
6	LABOUR FOR REMOVE & RENEW REAR TAILGATE AUTO MOTOR ,TO RESET AND RE-PROGRAMME REAR TAILGATE AUTO LOCK	New	400.00	30.00
7	TO APPLY TUFF COATING /RUST PROOF ACCIDENT AREAS	New	300.00	80.00
8	LABOUR FOR REMOVE & TRANSFER ALL REAR TAILGATE FITTING	New	300.00	80.00
9	LABOUR FOR REMOVE & RENEW REAR EXHAUST MUFFLER ,TO REPAIR & STRAIGHTEN REAR EXHAUST PIPE	New	300.00	0.00
10	LABOUR FOR DIAGNORSE AND RESET WARNING LIGHT	New	250.00	0.00
Gross Labour Cost (\$)			6,080.00	2,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >