

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22000374/KPA3Q2**Date:** 09/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100490889
Claimant Vehicle No :	SJY3365C	Insured Vehicle No :	SDD5420U
Date of Loss:	09/01/2022	Nature of Claim:	TP
		Claim No:	0451852131SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJY3365C	Engine No:	LEB6742431
Make & Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Chassis No:	RU31322420
Reg. Date:	09/06/2020 (Man. Year: 2018)	Odometer:	59565 km
Colour:	Metallic Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 2 mm	Rear Left Side:	Dunlop 2 mm
Front Right Side:	Dunlop 2 mm	Rear Right Side:	Dunlop 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,002.24	2,750.80	3,251.44	54.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,785.00	1,375.00	1,410.00	50.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,787.24	4,125.80	4,661.44	53.05
Approved Total (Overridden) (S\$)		3,300.00		
Nett Amount (S\$)	8,787.24	3,300.00	5,487.24	62.45
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,457.45		

INSPECTION

Date of Assignment:	24/01/2022	
Date Inspected:	24/01/2022 Inspected At:	Lian Her Motor Works (HQ) Block 5034 Ang Mo Kio Avenue 3, #01-337 Ang Mo Kio Industrial Park 2 Singapore 569537
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL-GATE ASSY	Bent	1,170.30 FL	*953.00 FL
2	1		*REAR TAIL-GATE GLASS MOULDING	Necessary	105.20 FL	*105.20 FL
3	1		*REAR TAIL-GATE EMBLEM H	Not Necessary	45.10 FL	*- FL
4	1		*REAR TAIL-GATE EMBLEM VEZEL	Necessary	50.20 FL	*50.20 FL
5	1		*REAR TAIL-GATE OUTER GARNISH	Serviceable	205.70 FL	*- FL
6	1		*REAR TAIL-GATE INNER LOCK	Dented	285.60 FL	*285.60 FL
7	1		*REAR TAIL-GATE INNER LOCK SENSOR	Dented	225.10 FL	*225.10 FL
8	1		*REAR TAIL-GATE INNER TRIM BOARD	Mtg Distorted	406.10 FL	*295.00 FL
9	1		*REAR O/S TAIL-GATE LAMP COMPONENT	Serviceable	476.10 FL	*- FL
10	1		*REAR O/S FENDER INNER TRIM BOARD	Serviceable	487.10 FL	*- FL
11	1		*REAR BOOT RUBBER	Distorted / Dented	225.80 FL	*225.80 FL
12	1		*REAR END PANEL	Repair	455.10 FL	*- FL
13	1		*REAR END PANEL INNER GARNISH	Mtg Distorted	185.90 FL	*185.90 FL
14	1		*REAR BUMPER	Buckled	855.60 FL	*762.70 FL
15	1		*REAR O/S SIDE BUMPER	Serviceable	335.60 FL	*- FL
16	2		*REAR BUMPER SIDE RETAINER	Serviceable	90.20 FL	*- FL
17	1		*REAR O/S BUMPER REFLECTOR	Serviceable	155.20 FL	*- FL
18	1		*REAR BUMPER LOWER GARNISH	Serviceable	175.20 FL	*- FL
19	1		*REAR EXHAUST SILENCER	Repair	975.10 FL	*- FL
20	1		*REAR SPARE TYRE COVER BOARD	Serviceable	205.10 FL	*- FL
21	1		*REAR TAIL-GATE GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
22	1		*REAR REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
23	20		*REAR BUMPER CLIP	Necessary	40.00 FS	*40.00 FS
24	1		*REAR NO PLATE	Serviceable	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,425.30	3,368.50
- List Item Discount on L Items 20.00/20.00% (S\$)	1,423.06	617.70
Total Parts (S\$)	6,002.24	2,750.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING WELDING & CUTTING	New	1,200.00	500.00
2	TO PUTTY AND SPRAY PAINT	New	1,000.00	600.00
3	CHECK & RECONNECT WIRING	New	45.00	15.00
4	TO RESPRAY ANTI-RUST PROOFING TREATMENT	New	100.00	30.00
5	REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIR	New	120.00	120.00
6	REMOVE/REFIT REAR TAIL-GATE MECHANISM TO NEW DOOR	New	100.00	60.00
7	REMOVE/RENEW REAR EXHAUST SILENCER	New	120.00	0.00
8	REMOVE/REFIT REAR BOOT UPHOLSTERY TO FACILITATE REPAIR	New	100.00	50.00
Gross Labour Cost (\$\$)			2,785.00	1,375.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >