

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22000376/KQY3N2**Date:** 30/03/2022**REFERENCE**Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00036242103

**Claimant Vehicle  
No :** GBE3197X**Insured  
Vehicle No :** GBH2987Z

Date of Loss: 08/01/2022

Nature of Claim: TP

Claim  
No: SNM22D200235/C02/TOHHS**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **GBE3197X**

Make &amp; Model: TOYOTA DYNA 150 MANUAL, 3.0 D (M)

Engine No: 1KD2557178

Reg. Date: 27/10/2015 (Man. Year: 2015)

Chassis No: JTFAT35Y50K205059

Colour: White

Odometer: 218423 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195 R15X8	Rear Tyre Size:	155 R12X8 (D)
Front Left Side:	Triangle 5 mm	Rear Left Side:	Dunlop 2/2 mm
Front Right Side:	Triangle 5 mm	Rear Right Side:	Dunlop 2/2 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	25,405.62	7,814.67	17,590.95	69.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,260.00	2,215.00	4,045.00	64.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>31,665.62</b>	<b>10,029.67</b>	<b>21,635.95</b>	<b>68.33</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>7,600.00</b>		
<b>Nett Amount (\$\$)</b>	<b>31,665.62</b>	<b>7,600.00</b>	<b>24,065.62</b>	<b>76.00</b>

**INSPECTION**

Date of Assignment: 11/01/2022

Date Inspected: 12/01/2022 Inspected At:

RS AUTO SERVICES (HQ)  
160 Sin Ming Drive, #06-01 Sin Ming Auto City  
Singapore 575722

Estimated Period of Repair: 6.0 days

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 29 Mar 2022)	
<b>Parts:</b>	N/A	TOYOTA DYNA 150 MANUAL 3.0 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBE3197X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	980.00 FL	*699.00 FL
2	1		*FRONT BUMPER INNER BEAM	N/s Bent	585.00 FL	*182.90 FL
3	2		*FRONT BUMPER BRACKETS	Repair	380.00 FL	*- FL
4	1		*FRONT CENTER PANEL	Repair	650.00 FL	*- FL
5	1		*FRONT CENTER PANEL GARNISH	Dented	480.00 FL	*385.00 FL
6	1		*FRONT GRILLE	Mtg Cracked	480.00 FL	*480.00 FL
7	2		*HEADLAMPS	Mtg Cracked	1,980.00 FL	*1,980.00 FL
8	1		*FRONT WIPER PANEL	Repair	740.00 FL	*- FL
9	2		*TAILLAMPS	Serviceable	798.00 FL	*- FL
10	1		*FRONT LH DOOR (NPA)	Repair	0.00 FL	*- FL
11	1		*FRONT LH STEP GARNISH (DENTED)	Not Consistent With The Impact	328.50 FL	*- FL
12	1		*FRONT BUMPER INNER CENTER BEAM	Bent	680.00 FL	*420.00 FL
13	2		*TAIL GATE ASSY (LOCAL REPAIR)	Dented	8,000.00 FS	*600.00 FS
14	1		*TAILGATE CENTER LATCH	Repair	480.00 FS	*- FS
15	2		*TAILGATE OUTER HANDLER	Repair	1,460.00 FS	*- FS
16	1		*SET TAILGATE COMPANY STICKER	Necessary	2,800.00 FS	*2,800.00 FS
17	4		*TAILGATE SIDE HINGES	Repair	1,200.00 FS	*- FS
18	1		*END PANEL	Repair	980.00 FS	*- FS
19	2		*END PANEL RUBBER STOPPER	Dented	600.00 FS	*600.00 FS
20	1		*REAR SAFETY BAR	Repair	2,200.00 FS	*- FS
21	1		*SET REVERSE SENSORS	Serviceable	500.00 FS	*- FS
22	1		*FRONT LH DOOR COMPANY STICKERS	Necessary	200.00 FS	*80.00 FS
23	1		*TAILGATE FRAME COVER (ALUMINIUM)	Dented	800.00 FS	*500.00 FS
24	1		*DYNA EMBLEM	Necessary	68.00 FL	*68.00 FL
25	1		*FRONT CENTER LOGO	Necessary	98.00 FL	*98.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>27,467.50</b>	<b>8,892.90</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	2,061.88	1,078.23
<b>Total Parts (\$\$)</b>	<b>25,405.62</b>	<b>7,814.67</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES TO REPAIR,REPLACE CUTTING WELDING FRONT ACCIDENT AFFECTED AREA	New	1,400.00	500.00
2	TO DO SPRAY PAINTING FOR FRONT ACCIDENT AREA	New	1,200.00	600.00
3	FORCUS HEADLAMPS,CHECK FRONT WIRING SYSTEM	New	120.00	20.00
4	TO DO ANTI RUST FOR FRONT	New	120.00	0.00
5	TO DO SPRAY PAINTING ON FRONT LH DOOR	New	200.00	180.00
6	LABOUR TO REMOVE REFIX,REPLACE ACCIDENT DAMAGE PARTS CUTTING WELDING FOR REAR	New	1,400.00	500.00
7	TRANSFER TAILGATE PARTS TO ANOTHER TAILGATE	New	300.00	0.00
8	TO CHECK REAR LAMPS WIRING,LOCK CABLE WIRING,CHECK WIRING SYSTEM,REPLACE REVERSE SENSOR FOR REAR	New	150.00	15.00
9	TO DO ANTI RUST	New	120.00	0.00
10	TO DO SEALANT,SEAL GAP,WATER PROOFING ON ACCIDENT AFFECTED CUTTING,WELDING AREA	New	250.00	0.00
11	TO DO SPRAY PAINTING ON ACCIDENT AFFECTED AREA,INNER AND OUTER	New	1,000.00	400.00
<b>Gross Labour Cost (\$\$)</b>			<b>6,260.00</b>	<b>2,215.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >