

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMN 6785B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT DOOR RH	DENTED	2,450.00	2,450.00
1	FRONT DOOR OUTER HANDLE	* CHECK	465.71	-
1	FRONT DOOR OUTER HANDLE SEAL	* CHECK	45.90	-
1	FRONT DOOR OTR WINDOW MOULDING 8V5853284B2ZZ	* CHECK	455.75	-
1	FRONT DOOR TYRE PRESSURE STICKER	NECESSARY	79.50	79.50
1	FRONT DOOR INNER TRIM	* CHECK	2,450.70	-
10	FRONT DOOR INNER TRIM CLIPS @\$12.17	* CHECK	121.70	-
1	FRONT DOOR INSULATION / DOOR FOIL	* CHECK	155.70	-
1	FRONT DOOR WINDOW REGULATOR	* CHECK	560.79	-
1	FRONT DOOR LOCK	* CHECK	859.60	-
1	FRONT DOOR LOCK HANDLE BASE 8V0837885	* CHECK	245.80	-
1	RH FRONT DOOR AIRBAG SENSOR	* CHECK	456.77	-
1	REAR DOOR RH	DENTED	2,450.00	2,450.00
1	RH REAR DOOR OTR WINDOW MOULDING	* CHECK	455.75	-
1	RH REAR DOOR OUTER HANDLE	NOT NECESSARY	465.71	-
1	RH REAR DOOR LOCK	* CHECK	859.60	-
1	RH DOOR LOCK HANDLE BASE	NOT NECESSARY	245.80	-
1	RH REAR DOOR SEAL	NOT NECESSARY	386.91	-
1	RH REAR DOOR HINGE UPPER	BENT	345.97	345.97
1	RH REAR DOOR HINGE LOWER	BENT	345.97	345.97
1	RH REAR DOOR CHECK	BENT	179.89	179.89
1	RH REAR DOOR WIRING HARNESS (NPA)	* CHECK	-	-
1	RH REAR DOOR WINDOW REGULATOR	* CHECK	560.79	-
1	RH REAR DOOR INNER TRIM	* CHECK	2,450.70	-
1	RH REAR DOOR INSULATION / DOOR FOIL	* CHECK	155.70	-
10	RH REAR DOOR INNER TRIM CLIPS @\$12.17	* CHECK	121.70	-
1	RH B-PILLAR 8V5809848	DENTED	4,150.00	4,150.00
1	RH QTR GLASS MOULDING	NOT NECESSARY	700.71	-
1	REAR WINDOW GLASS MOULDING	NOT NECESSARY	185.00	-
1	RH DRIVER SEAT	BROKEN	1,745.60	1,745.60
1	RH DRIVER SEAT AIRBAG	BROKEN	1,695.80	1,695.80

Report Ref No. CS/SMR22000380/Eqy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	LH SEAT BELT	JAMMED	1,750.60	1,750.60
1	AIRBAG CONTROL UNIT	NECESSARY	2,580.00	2,580.00
1	ROOF LINING AIRBAG	CRUSHED	2,355.91	2,355.91
1	ROOF LINING	CRUSHED	2,380.60	2,380.60
	LESS 5% DISCOUNT		-1,745.83	-1,125.49
			33,170.80	21,384.35
	SPECIAL NETT ITEMS			
1	QUATER GLASS SEALANT (SN)	NOT NECESSARY	40.00	-
1	REAR GLASS SEALANT (SN)	NOT NECESSARY	40.00	-
1	IROAD V7 (SN)	TORN	550.00	550.00
1	SET BLIND RIVET (SN)	NECESSARY	30.00	30.00
			660.00	580.00
	<u>LABOUR</u>			
	TO PANEL BEAT / KNOCKING / WELDING AND CUT THE RH, B-PILLAR, ROCKER PANEL, REAR FENDER. TO KNOCKING & REALIGN RH A-PILLAR. TO REPLACE BOTH RH DOOR & DAMAGED PARTS.		1,850.00	1,200.00
	TO SPRAY PAINT ON RH FRONT DOOR REAR DOOR, REAR FENDER, ROCKER PANEL, B-PILLAR AND A- PILLAR.		1,250.00	1,000.00
	TO REMOVE & REFIT FRONT DASHBOARD.	NOT NECESSARY	200.00	-
	TO REMOVE & REFIT BOTH FRONT SEAT IN ORDER TO REMOVE & ROOF LINING.		200.00	80.00
	TO REMOVE & REPLACE ROOF LINING, ROOF LINING AIRBAG.		100.00	80.00
	TO APPLY BODY JOINT SEALANT ON CUTTING AREAS.		120.00	30.00
	TO APPLY ANTI RUST PROOFING ON AFFECTED AREAS.		120.00	30.00
	TO REMOVE & REFIT RH QUATER GLASS.	NOT NECESSARY	100.00	-
	TO REMOVE & REFIT REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	TO REMOVE & REFIT REAR SEAT, UPHOSTERY, SIDE TRIM / COVERING, INNER TRIM TO ASSIST REPAIR.		150.00	50.00
	TO PROGRAME AIRBAG CONTROL UNIT.		350.00	150.00
	TO TRANSFER RH FRONT DOOR WINDOW GLASS & RELATED ITEMS TO NEW UNIT.		80.00	50.00
	TO TRANSFER RH REAR DOOR WINDOW GLASS & RELATED ITEMS TO NEW UNIT.		80.00	50.00

Report Ref No. CS/SMR22000380/Eqy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO REMOVE / INSTALL IN CAR CAMERA "IROAD V7" & CHECK FUNCTIONING.		180.00	80.00
	TO CONDUCT CHASSIS ALIGNMENT CHECK ON LASER LOCK MACHINE.	* CHECK	450.00	-
	TO CONDUCT WIRING CHECK / DIAGNOSE & RESET SYSTEM AFTER REPAIR.		180.00	100.00
			5,560.00	2,900.00
	GRAND TOTAL		39,390.80	24,864.35

RECOMMENDED COST OF REPAIRS		24,864.35
(REPAIR COST NOT CONCLUDE)		
(EXCLUDE CHECK ITEMS S\$10,351.53 NETT)		

Report Ref No. CS/SMR22000380/Eqy3e2



Automotive Assessor

P

ANG BRYAN TANI

Automotive Assessor / Investigator