

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22000383/APA3Q2**Date:** 19/05/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100447428
Claimant Vehicle No :	SLE429D	Insured Vehicle No :	SKZ2932E
Date of Loss:	11/01/2022	Nature of Claim:	TP
		Claim No:	6297180414SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE429D	Engine No:	CJX117973
Make & Model:	AUDI S3, 2.0 TFSI Quattro (M)	Chassis No:	WAUZZZ8V3G1098251
Reg. Date:	04/07/2016 (Man. Year: 2016)	Odometer:	48252 km
Colour:	Blue		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/35 R19	Rear Tyre Size:	245/35 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,656.50	9,860.80	6,795.70	40.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,772.00	10,547.00	9,225.00	46.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	36,428.50	20,407.80	16,020.70	43.98
+ GST 8.00/8.00% (\$\$)	2,914.28	1,632.62	1,281.66	43.98
Nett Amount (\$\$)	39,342.78	22,040.42	17,302.36	43.98
+ Loss of Use (17.0 x \$S\$100.00/day) (\$\$)		1,700.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		23,742.42		

INSPECTION

Date of Assignment:	14/01/2022		
Date Inspected:	14/01/2022	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	14.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	2,778.00 FS	*2,222.40 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	193.00 FS	*- FS
3	1		*REAR BUMPER GUIDE SECTION -LH/RH	O/S Damaged	32.00 FS	*12.64 FS
4	2		*REAR BUMPER LOCKING MECHANISM	Not Necessary	59.00 FS	*- FS
5	1		*REAR BUMPER SPOILER	Cut	2,108.00 FS	*1,686.40 FS
6	1		*REAR LIGHT REFLECTOR -RH	Cracked	41.00 FS	*32.56 FS
7	1		*TAIL LIGHT -RH	Not Necessary	877.00 FS	*- FS
8	1		*TAIL LIGHT TRIM -RH	Not Necessary	30.00 FS	*- FS
9	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	603.00 FS	*- FS
10	2		*REAR BUMPER BRACKET LH/RH	Not Necessary	26.00 FS	*- FS
11	1		*REAR BUMPER GUIDE SECTION -RH	Cracked	67.00 FS	*52.96 FS
12	1		*REAR PARKING AID SENSOR -INNER /OUTER	Outer Damaged	264.70 FS	*211.76 FS
13	4		*REAR PARKING AID SENSOR SEAL RING	Necessary	9.00 FS	*7.04 FS
14	1		*SET REAR BUMPER WIRING	Not Necessary	515.00 FS	*- FS
15	1		*C PILLAR-RH	Buckled	4,140.00 FS	*3,312.00 FS
16	1		*REAR WINDSCREEN	Necessary	814.00 FS	*651.20 FS
17	1		*QUARTER WINDOW	Necessary	570.00 FS	*455.60 FS
18	2		*PRIMER	Necessary	40.00 FS	*31.52 FS
19	1		*REAR END PANEL	Not Necessary	360.00 FS	*- FS
20	1		*REAR END PANEL REINFORCEMENT	Not Necessary	733.00 FS	*- FS
21	2		*REAR END PANEL CONNECTING PLATE -LH/RH	Not Necessary	290.00 FS	*- FS
22	1		*REAR VENT TRIM	Not Necessary	68.00 FS	*- FS
23	1		*REAR WHEELHOUSING LINER	Not Necessary	240.00 FS	*- FS
24	1		*REAR WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	89.00 FS	*- FS
25	1		*EXHAUST TAIL PIPE TRIM -RH	Not Necessary	143.00 FS	*- FS
26	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
27	1		*ARYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
28	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
29	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
30	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
31	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
32	1		*SUNDRIES	Necessary	400.00 FS	*17.92 FS
33	1		*CONNECTING PLATE -RH REAR	Buckled	86.80 FS	*86.80 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 16,656.50 9,860.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT OUT AND WELD RHS REAR FENDER CONNECTING PLATE	New	1,400.00	500.00
2	TO RESPRAY RHS REAR CONNECTING PLATE	New	1,400.00	550.00
3	TO REMOVE AND TRANSFER REAR PARKING AID .CHECK FUNCTION	New	280.00	280.00
4	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHT .BATTERY MANAGER FUSE AND RELAY TRAYS ELECTRICAL AND AUDIO EQUIPMENT INSPECT FOR DAMAGE AN RENEW WHERE NECESSARY	New	1,400.00	1,400.00
5	TO REMOVE AND REINSTALL REAR SEAT ,BACK SEAT ,HAT TRAY ,ABCD PILLAR TRIMS ,LUGGAGE COMPARTMENT TRIMS ,DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	1,400.00
6	TO RENEW REAR WINDSCREEN RHS 1/4 GLASS TO FACILITATE RENEWAL OF LHS REAR FENDER	New	600.00	600.00
7	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND RHS 1/4 GLASS	New	400.00	0.00
8	TO CARRY OUT WATER SEEPAGE TEST ON REAR WINDSCREEN AND 1/4 GLASS	New	200.00	150.00
9	TO DISMANTLE AND RENEW REAR BUMPER .CUT OUT AND WELD RHS REAR FENDER AND REAR END PANELLING .RE-ORGANIZE REAR CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	7,000.00	3,000.00
10	TO RESPRAY REAR BUMPER,RHS REAR FENDER ,RHS SILL PANEL ,ROOF CHANNEL ,DOOR ENTRANCES ,DRAIN CHANNEL SPARE WHEEL HOUSING AND REAR END PANELLING	New	5,500.00	2,475.00
11	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			19,772.00	10,547.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >