

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFN 7691P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR DOOR O/S (CONSISTENT)	NOT NECESSARY	1,209.10	-
1	REAR FENDER O/S (CONSISTENT)	BADLY DENTED	1,145.30	1,145.30
1	REAR FENDER UNDER COVER O/S (CONSISTENT)	DISTORTED	366.50	203.00
1	SET REAR FENDER UNDER COVER CLIPS O/S (CONSISTENT)	NECESSARY	50.00	50.00
1	REAR WINDSCREEN SEALANT (CONSISTENT)	NECESSARY	50.00	50.00
1	REAR WINDSCREEN INNER SEAL (CONSISTENT)	NECESSARY	50.00	50.00
1	REAR WINDSCREEN MOULDING (CONSISTENT)	NECESSARY	118.20	108.00
1	REAR BUMPER (CONSISTENT)	DISTORTED	681.30	681.30
1	REAR BUMPER SIDE RETAINER O/S (CONSISTENT)	BENT	125.30	69.00
1	REAR BUMPER SIDE HOLDER O/S (CONSISTENT)	NOT NECESSARY	105.40	-
1	SET REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	50.00	50.00
1	REAR SPORT RIM O/S (CONSISTENT)	TO REPAIR SEE LABOUR	600.00	-
	LESS 50% DISCOUNT		-	-1,203.30
			4,551.10	1,203.30
	<u>LABOUR</u>			
	TO CHECK WIRING .		50.00	20.00
	TO DISMANTLE & REFIX REAR REVERSE SENSOR .		80.00	50.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.		150.00	120.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY .		100.00	80.00
	TO CONDUCT WHEEL ALIGNMENT.		100.00	60.00
	TO DISMANTLE & REFIX REAR DOOR MECHANISM O/S .	NOT NECESSARY	100.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF REAR SPORT RIM O/S .		880.00	800.00
	TO PUTTY & SPRAY PAINTING.		1,080.00	700.00
			2,540.00	1,830.00
	GRAND TOTAL		7,091.10	3,033.30

Report Ref No. CC4/ASM22000386/Uea3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		3,000.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM22000386/Uea3q2

CHUA KANG SENG

Licensed Appraiser