

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22000388/AVCE2

Date: 23/03/2022

REFERENCE

Insured/Claimant: LEE KAY CHAI Policy No: 1900045219
Date of Loss: 06/01/2022 Nature of Claim: OD Claim No: 2128974117SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFD228T**
Make & Model: AUDI RS5 COUPE, 2.9 TFSI QU TIP (SR) (A) Engine No: DEC014653
Reg. Date: 21/03/2019 (Man. Year: 2019) Chassis No: WUAZZZF59KA903428
Colour: Bronze Odometer: 34282 km
Engine Capacity: 2894 cc
Market Value/New Car Price: S\$310,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/30 R20 Rear Tyre Size: 275/30 R20
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,922.00	8,857.36	23,064.64	72.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,322.00	2,272.00	4,050.00	64.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	38,244.00	11,129.36	27,114.64	70.90
- Excess (S\$)	3,500.00	3,500.00	0.00	0.00
(S\$)	34,744.00	7,629.36	27,114.64	78.04
+ GST 7.00/7.00% (S\$)	2,432.08	534.06	1,898.02	78.04
Nett Amount (S\$)	37,176.08	8,163.42	29,012.66	78.04

INSPECTION

Date of Assignment: 11/01/2022
Date Inspected: 10/01/2022 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	6,264.00 FS	*5,011.20 FS
2	2		*FRONT BUMPER SECURING STRIP - LH / RH	Not Necessary	90.00 FS	*- FS
3	2		*FRONT BUMPER AIR GUIDE - LH / RH	Not Necessary	334.00 FS	*- FS
4	1		*FRONT BUMPER SPOILER - UPPER	Not Necessary	613.00 FS	*- FS
5	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	722.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Not Necessary	350.00 FS	*- FS
7	1		*FRONT BUMPER SPOILER - CENTER	Not Necessary	708.00 FS	*- FS
8	1		*FRONT BUMPER SPOILER - LOWER	Not Necessary	856.00 FS	*- FS
9	2		*FRONT BUMPER SPOILER - LH / RH	Not Necessary	1,352.00 FS	*- FS
10	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	736.00 FS	*- FS
11	1		*RADIATOR AIR GUIDE - LH	Not Necessary	75.00 FS	*- FS
12	1		*FRONT BUMPER AIR GUIDE - LH	Not Necessary	226.00 FS	*- FS
13	1		*RADIATOR GRILLE	Cracked	3,508.00 FS	*2,806.40 FS
14	2		*FRONT PARKING AID SENSOR SUPPORT - LH / RH	Not Necessary	178.00 FS	*- FS
15	1		*RSS EMBLEM	Necessary	128.00 FS	*102.40 FS
16	1		*FRONT BUMPER LOWER COVER	Torn	213.00 FS	*170.40 FS
17	1		*RADIATOR GRILLE - UPPER	Not Necessary	253.00 FS	*- FS
18	1		*LICENCE PLATE HOLDER	Cracked	621.00 FS	*496.80 FS
19	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	303.00 FS	*- FS
20	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	845.00 FS	*- FS
21	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	67.00 FS	*- FS
22	1		*FRONT BUMPER TOP COVER	Torn	242.00 FS	*193.60 FS
23	1		*CAUTION STICKER	Necessary	14.00 FS	*10.88 FS
24	1		*AIR COND STICKER	Necessary	8.00 FS	*5.68 FS
25	1		*FRONT BUMPER LOCK CARRIER BRACKET	Not Necessary	137.00 FS	*- FS
26	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	58.00 FS	*- FS
27	4		*FRONT POP RIVET	Not Necessary	4.00 FS	*- FS
28	1		*HORN - LH	Not Necessary	201.00 FS	*- FS
29	1		*HORN SUPPORT - LH	Not Necessary	50.00 FS	*- FS
30	2		*FRONT PARKING AID SENSOR - INNER / OUTER (NPA)	Not Necessary	0.00 FS	*- FS
31	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	9.00 FS	*- FS
32	1		*BONNET	Repair	3,312.00 FS	*- FS
33	3		*BONNET IMPACT PROTECTION - CENTER / LH / RH	Not Necessary	84.00 FS	*- FS
34	1		*BONNET STRIKER - LH	Not Necessary	50.00 FS	*- FS
35	1		*BONNET LOCK	Not Necessary	214.00 FS	*- FS
36	1		*HEADLIGHT - LH	Not Necessary	7,902.00 FS	*- FS
37	1		*LIFT CYLINDER - LH	Not Necessary	198.00 FS	*- FS
38	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	86.00 FS	*- FS
39	1		*BONNET TRIM RETAINER - LH	Not Necessary	49.00 FS	*- FS
40	1		*BONNET TRIM - LH	Not Necessary	402.00 FS	*- FS
41	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
42	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 31,922.00 8,857.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	450.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,700.00	500.00
4	TO RESPRAY FRONT BUMPER AND BONNET	New	2,500.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
			Gross Labour Cost (\$\$)	6,322.00
				2,272.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >