

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22000389/AVCN2**Date:** 26/05/2022**REFERENCE**

Insured/Claimant:	ANJALI GROVER SINGH	Policy No:	2100507400	
Date of Loss:	05/01/2022	Nature of Claim:	OD	Claim No: 8047340552SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN491A		
Make & Model:	AUDI A8 L, 3.0 TFSI QU (A)	Engine No:	CRE152029
Reg. Date:	20/04/2017 (Man. Year: 2017)	Chassis No:	WAUZZZ4H2HN015984
Colour:	Black	Odometer:	24651 km
Engine Capacity:	2995 cc		
Market Value/New Car Price:	S\$170,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/45R19	Rear Tyre Size:	255/45R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	65,229.00	18,250.00	46,979.00	72.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,252.00	5,352.00	10,900.00	67.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	81,481.00	23,602.00	57,879.00	71.03
- Excess (S\$)	1,400.00	1,400.00	0.00	0.00
(S\$)	80,081.00	22,202.00	57,879.00	72.28
+ GST 7.00/7.00% (S\$)	5,605.67	1,554.14	4,051.53	72.28
Nett Amount (S\$)	85,686.67	23,756.14	61,930.53	72.28

INSPECTION

Date of Assignment:	11/01/2022		
Date Inspected:	10/01/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	7.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	3,649.00 FS	*2,919.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	493.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE	Not Necessary	708.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT-LOWER	Not Necessary	262.00 FS	*- FS
5	1		*FRONT BUMPER SPOILER-LOWER	Not Necessary	297.00 FS	*- FS
6	2		*FRONT WHEEL SPOILER OUTER-LH/RH	Not Necessary	88.00 FS	*- FS
7	2		*FRONT WHEEL SPOILER INNER-LH/RH	Not Necessary	74.00 FS	*- FS
8	1		*RADIATOR GRILLE	Cracked	3,508.00 FS	*2,806.40 FS
9	1		*QUATTRO EMBLEM	Necessary	106.00 FS	*84.80 FS
10	2		*FRONT BUMPER EMBLEM CLIP	Necessary	15.00 FS	*11.36 FS
11	1		*EMBLEM COVER	Necessary	61.00 FS	*48.16 FS
12	1		*EMBLEM COVER CAP	Not Necessary	114.00 FS	*- FS
13	1		*RADIATOR GRILLE BRACKET	Cracked	27.00 FS	*21.44 FS
14	1		*RADIATOR GRILLE REINFORCEMENT-LH/RH	O/s Damaged	98.00 FS	*38.80 FS
15	2		*FRONT PARKING AID SENSOR SUPPORT-LH/RH	Not Necessary	96.00 FS	*- FS
16	1		*FRONT CAMERA	Not Necessary	959.00 FS	*- FS
17	1		*FRONT CAMERA ADAPTER	Not Necessary	416.00 FS	*- FS
18	1		*LICENCE PLATE HOLDER	Deformed	459.00 FS	*367.20 FS
19	2		*FRONT BUMPER GRILLE OUTER-LH/RH	Not Necessary	1,038.00 FS	*- FS
20	1		*FRONT BUMPER END CAP-RH	Not Necessary	68.00 FS	*- FS
21	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	127.00 FS	*101.20 FS
22	1		*FRONT BUMPER REINFORCEMENT COVER	Cracked	98.00 FS	*78.00 FS
23	1		*FRONT BUMPER TRIM BRACKET-LH/RH	O/s Damaged	50.00 FS	*19.44 FS
24	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	1,157.00 FS	*- FS
25	2		*FRONT BUMPER RETAINING BRACKET-LH/RH	Not Necessary	50.00 FS	*- FS
26	2		*FRONT BUMPER GUIDE PIECE-LH/RH	Not Necessary	106.00 FS	*- FS
27	1		*FRONT BUMPER TOP COVER	Cracked	242.00 FS	*193.60 FS
28	1		*AIR COND STICKER	Necessary	20.00 FS	*15.52 FS
29	1		*CAUTION STICKER	Necessary	14.00 FS	*10.88 FS
30	4		*FRONT BUMPER PARKING AID SENSOR Npa	Not Necessary	0.00 FS	*- FS
31	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	6.00 FS	*- FS
32	1		*FRONT BUMPER WIRING SET	Not Necessary	676.00 FS	*- FS
33	2		*HORN-HIGH/LOW TONE	Not Necessary	483.00 FS	*- FS
34	1		*HORN SUPPORT	Bent	91.00 FS	*72.72 FS
35	1		*BONNET	Repair	6,645.00 FS	*- FS
36	1		*BONNET ATTACHMENT PARTS	Not Necessary	266.00 FS	*- FS
37	1		*BONNET CATCH HOOK	Not Necessary	156.00 FS	*- FS
38	2		*BONNET HINGE-LH/RH	Not Necessary	542.00 FS	*- FS
39	1		*BONNET SEAL	Not Necessary	60.00 FS	*- FS
40	2		*BONNET LOCK BAR	Not Necessary	240.00 FS	*- FS
41	2		*BONNET LOCK-LH/RH	Not Necessary	457.00 FS	*- FS
42	2		*BONNET LOCK HOUSING -LH/RH	Not Necessary	92.00 FS	*- FS
43	2		*BONNET LOCK SWITCH -LH/RH	Not Necessary	148.00 FS	*- FS
44	2		*BONNET LOCK COVER	Not Necessary	8.00 FS	*- FS
45	1		*BONNET BOWDEN CABLE-CENTER	Not Necessary	58.00 FS	*- FS
46	1		*BONNET BOWDEN CABLE COVER	Not Necessary	10.00 FS	*- FS
47	1		*RADIATOR CATCH HOOK	Not Necessary	153.00 FS	*- FS
48	2		*TERMINAL SOCKET CABLE TIE	Not Necessary	5.00 FS	*- FS
49	2		*FRONT FENDER SIDE COVER-LH/RH	Not Necessary	30.00 FS	*- FS
50	2		*FRONT FENDER-LH/RH	Not Necessary	3,684.00 FS	*- FS
51	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	287.00 FS	*- FS
52	2		*FRONT CONNECTING PIECE-LH/RH	Not Necessary	486.00 FS	*- FS
53	2		*FRONT FENDER BRACE-LH/RH	Not Necessary	1,700.00 FS	*- FS
54	2		*FRONT FENDER BRACKET-LH/RH	Not Necessary	50.00 FS	*- FS
55	2		*FRONT FENDER BRACKET END-LH/RH	Not Necessary	68.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	2		*FRONT WHEEL HOUSING LINER-LH/RH	Not Necessary	592.00 FS	*- FS
57	2		*HEADLIGHT-LH/RH	Cracked (1 Pc only)	26,162.00 FS	*10,464.80 FS
58	2		*LIFT CYLINDER-LH/RH	Not Necessary	472.00 FS	*- FS
59	1		*LIFT CYLINDER HOSE	Not Necessary	109.00 FS	*- FS
60	2		*LIFT CYLINDER SECURING BRACKET-LH/RH	Not Necessary	376.00 FS	*- FS
61	1		*LOCK CARRIER	Not Necessary	1,131.00 FS	*- FS
62	1		*LOCK CARRIER SUPPORT	Not Necessary	741.00 FS	*- FS
63	2		*LOCK CARRIER SIDE MEMBER-LH/RH	Not Necessary	392.00 FS	*- FS
64	1		*A/C CONDENSER	Dented	960.00 FS	*768.00 FS
65	1		*OUTSIDE TEMPERATURE SENSOR	Not Necessary	59.00 FS	*- FS
66	1		*ADDITIONAL RADIATOR	Not Necessary	1,134.00 FS	*- FS
67	1		*RADIATOR COOLANT-CENTER	Not Necessary	1,355.00 FS	*- FS
68	6		*RADIATOR COOLANT	Not Necessary	266.00 FS	*- FS
69	2		*RADIATOR AIR GUIDE-LH/RH	Not Necessary	54.00 FS	*- FS
70	1		*RADIATOR AIR GUIDE-UPPER CENTER	Not Necessary	42.00 FS	*- FS
71	1		*RADIATOR AIR GUIDE SEAL-LOWER	Not Necessary	37.00 FS	*- FS
72	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
73	1		*SUNDRIES	Necessary	400.00 FS	*99.92 FS
74	1		*AIR INTAKE DUCT COVER (Supplementary)	Deformed	29.00 FS	*23.20 FS
75	1		*AIR INTAKE AIR DUCT (Supplementary)	Cracked	57.00 FS	*45.36 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	65,229.00	18,250.00
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	900.00	300.00
3	TO REMOVE AND RENEW AIRCON CONDENSER,ADDITIONAL RADIATOR AND RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT.PRESSURISE COOLING SYSTEM.VACUUM AND REGAS	New	2,000.00	780.00
4	TO DISMANTLE AND RENEW FRONT BUMPER,BOTH FRONT FENDER.BONNET AND BOTH HEADLIGHTS,TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	7,200.00	2,400.00
5	TO RESPRAY FRONT BUMPER,BONNET,HINGES AND BOTH FRONT FENDER	New	5,000.00	1,200.00
6	TO CARRY OUT CALIBRATION FOR FRONT BUMPER RADAR SENSOR	New	480.00	0.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			16,252.00	5,352.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >