

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22000390/AQCE2**Date:** 11/04/2022**REFERENCE**

Insured/Claimant:	CHUA JIA MIN	Policy No:	7210105202	
Date of Loss:	09/01/2022	Nature of Claim:	OD	Claim No: 9887507495SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX2317E		
Make & Model:	AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A)	Engine No:	CZDC49833
Reg. Date:	31/08/2021 (Man. Year: 2021)	Chassis No:	WAUZZZF30M1155597
Colour:	Blue	Odometer:	3311 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$170,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,143.00	11,468.40	7,674.60	40.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,044.00	5,672.00	5,372.00	48.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,187.00	17,140.40	13,046.60	43.22
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	29,387.00	16,340.40	13,046.60	44.40
+ GST 7.00/7.00% (S\$)	2,057.09	1,143.83	913.26	44.40
Nett Amount (S\$)	31,444.09	17,484.23	13,959.86	44.40

INSPECTION

Date of Assignment:	11/01/2022	
Date Inspected:	10/01/2022	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,008.00 FS	*806.40 FS
2	1		*FRONT BUMPER CONNECTING PIECE	Missing	145.00 FS	*115.60 FS
3	1		*FRONT BUMPER CLOSING ELEMENT - LH	Damaged	59.00 FS	*46.64 FS
4	1		*FRONT BUMPER GRILLE - CENTER	Cut	217.00 FS	*173.20 FS
5	1		*FRONT BUMPER GRILLE COVER - LOWER	Not Necessary	51.00 FS	*- FS
6	1		*FRONT BUMPER GRILLE - LH	Cut	110.00 FS	*88.00 FS
7	1		*FRONT BUMPER CLOSING ELEMENT	Dented	190.00 FS	*151.60 FS
8	1		*FRONT BUMPER SPOILER	Torn	383.00 FS	*306.40 FS
9	1		*FRONT BUMPER BRACKET	Not Necessary	21.00 FS	*- FS
10	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Missing	153.00 FS	*122.00 FS
11	1		*RADIATOR GRILLE	Cracked	1,433.00 FS	*1,146.40 FS
12	1		*RADIATOR STRIKER PLATE	Cracked	244.00 FS	*194.80 FS
13	1		*RADIATOR COVER CAP	Not Necessary	45.00 FS	*- FS
14	1		*360 CAMERA	Not Necessary	1,141.00 FS	*- FS
15	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	102.00 FS	*- FS
16	1		*FRONT BUMPER REINFORCEMENT BEAM	Damaged	916.00 FS	*732.40 FS
17	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	39.00 FS	*- FS
18	1		*FRONT BUMPER TOP COVER	Necessary	123.00 FS	*98.00 FS
19	1		*CAUTION STICKER	Necessary	14.00 FS	*10.88 FS
20	1		*AIR COND STICKER	Necessary	8.00 FS	*5.68 FS
21	2		*FRONT PARKING AID SENSOR	Not Necessary	0.00 FS	*- FS
22	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	9.00 FS	*- FS
23	1		*SET FRONT BUMPER WIRING	Not Necessary	676.00 FS	*- FS
24	1		*HORN - LH	Cut	137.00 FS	*109.60 FS
25	1		*HORN SUPPORT - LH	Damaged	22.00 FS	*17.04 FS
26	1		*FRONT FENDER - LH	Not Necessary	1,286.00 FS	*- FS
27	1		*FRONT FENDER BRACE - LH	Not Necessary	88.00 FS	*- FS
28	1		*FRONT FENDER BRACKET - LH	Not Necessary	32.00 FS	*- FS
29	1		*FRONT WHEEL HOUSING LINER - LH	Deformed	240.00 FS	*191.60 FS
30	1		*FRONT WHEEL HOUSING LINER COVER - LH	Not Necessary	16.00 FS	*- FS
31	1		*HEADLIGHT MOUNTING - LH	Cracked	118.00 FS	*94.40 FS
32	1		*HEADLIGHT - LH	Cut	5,589.00 FS	*4,471.20 FS
33	1		*LIFT CYLINDER - LH	Damaged	210.00 FS	*167.60 FS
34	1		*LIFT CYLINDER HOSE	Cut	80.00 FS	*63.44 FS
35	1		*WATER RESERVOIR	Deformed	220.00 FS	*176.00 FS
36	1		*LOCK CARRIER	Cracked	1,272.00 FS	*1,017.60 FS
37	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	7.00 FS	*- FS
38	1		*A/C CONDENSER	Not Necessary	551.00 FS	*- FS
39	1		*RADIATOR COOLANT	Necessary	266.00 FS	*212.64 FS
			(6 pcs)			
40	1		*RADIATOR AIR GUIDE - LH	Cracked	38.00 FS	*29.76 FS
41	2		*RADIATOR AIR GUIDE - UPPER / LOWER	Deformed	84.00 FS	*66.08 FS
42	2		*FRONT WHEEL ARCH COVER - LH / RH	N/S Cut / O/S Necessary	536.00 FS	*428.80 FS
43	1		*FRONT NOISE INSULATION	Not Necessary	397.00 FS	*- FS
44	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
45	1		*SUNDRIES	Not Necessary	350.00 FS	*- FS
46	1		*FRONT WHEEL HOUSING LINER - RH	Torn	260.00 FS	*208.00 FS
			(Supplementary)			
47	1		*HEADLIGHT MOUNTING - RH	Cracked	132.00 FS	*105.20 FS
			(Supplementary)			
48	1		*BONNET RELEASE ELEMENT	Damaged	65.00 FS	*51.44 FS
			(Supplementary)			

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 19,143.00 11,468.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL AND CONTROL UNIT. PRESSURISE COOLING SYSTEM VACUUM AND REGAS	New	2,200.00	2,200.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDERS AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,800.00	2,000.00
5	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,500.00	550.00
6	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE	New	280.00	0.00
7	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	192.00
Gross Labour Cost (\$\$)			11,044.00	5,672.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >