



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2204625

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 27/07/2022
Reference CC6/CTI22000394/Apa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SNB 1965H
Insured Veh. GBJ 4797G
Claim No. SNM22D200223/C02
Policy No. DMCVSNW00041322101
Accident Date 09/01/2022
Inspection Date 11/01/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22000394/Apa3q2 Date: 27/07/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBJ 4797G	Veh. Inspected	SNB 1965H	
Policy No.	DMCVSNW00041322101	Coverage (\$)	0.00	
Claim No.	SNM22D200223/C02	Excess (\$)	0.00	
Assign From		Assign Date	11/01/2022	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI AVANTE	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	KMHLN41ETNU184940	Colour	RED	
Odometer	35145 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	KUMHO	6 mm	
L/H Front Tyre	225/45 R17	KUMHO	6 mm	
R/H Rear Tyre	225/45 R17	KUMHO	6 mm	
L/H Rear Tyre	225/45 R17	KUMHO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED FRONT REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/01/2022	Inspection Date	11/01/2022	
Survey held at	KANG CAR REPAIRERS PTE LTD NO.1 KAKI BUKIT AVE 6 #02-06 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNB 1965H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET	DISTORTED	2,253.80	2,253.80
2	BONNET HINGES	NOT NECESSARY	165.80	-
2	BONNET SIDE RUBBER	NOT NECESSARY	52.40	-
1	BONNET TRIM	NOT NECESSARY	221.10	-
1	BONNET LOCK	DAMAGED	129.90	129.90
1	BONNET LOCK GARNISH	CRACKED	240.90	240.90
1	FRT AIR CLEANER AIR DUCT	CRACKED	278.10	278.10
1	FRT GRILLE	CRACKED	896.60	896.60
1	FRT GRILLE BASE	CRACKED	173.30	173.30
1	FRT FENDER RH	DENTED	1,227.70	1,227.70
1	FRT FENDER COWLING RH	TORN	194.60	194.60
1	HEADLAMP RH	CRACKED	3,034.90	3,034.90
1	HEADLAMP LOWER BRACKET RH	CRACKED	69.40	69.40
1	HEADLAMP LH	CRACKED	3,034.90	3,034.90
1	FRT BUMPER	DISTORTED	525.80	525.80
1	FRT BUMPER REINFORCEMENT	DENTED	695.80	695.80
1	FRT BUMPER SPONGE	CRACKED	140.70	140.70
1	FRT BUMPER GRILLE	NOT NECESSARY	178.90	-
1	FRT NUMBER PLATE BASE	CRACKED	56.70	56.70
1	FRT BUMPER LOWER GARNISH	NOT NECESSARY	181.40	-
1	FRT LOGO	NECESSARY	64.20	64.20
2	FRT BUMPER SIDE RETAINERS	O/S DAMAGED	64.80	32.40
1	FRT BUMPER INNER GARNISH RH	NOT NECESSARY	91.60	-
1	FRT BUMPER FOG LAMP COVER RH	CRACKED	124.20	124.20
1	FRT BUMPER CENTRE CHROME	NECESSARY	166.70	166.70
1	FRT BUMPER LOWER SIDE GARNISH RH	DEFORMED	52.70	52.70
1	FRT WIPER WASHER TANK	NOT NECESSARY	67.20	-
1	FRT WIPER WASHER TANK MOTOR	NOT NECESSARY	126.90	-
3	FRT PARKING SENSORS	DAMAGED (2 PCS ONLY)	597.60	398.40
1	FRT CHROME MOULDING RH	CUT	196.70	196.70

Report Ref No. CC6/CTI22000394/Apa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRT TOWING COVER	NOT NECESSARY	31.90	-
1	FRT SUPPORT PANEL	CRACKED	949.30	949.30
1	AIR CONDENSER	WARPED	745.00	745.00
2	AIR CONDENSER SIDE TRIM	O/S TORN	198.00	99.00
1	RADIATOR	NOT NECESSARY	636.90	-
1	RADIATOR FAN ASSY	NOT NECESSARY	677.60	-
	LESS 20% DISCOUNT		-3,708.80	-3,156.34
			14,835.20	12,625.36
	<u>SPECIAL NETT ITEMS</u>			
1	SET BONNET TRIM CLIPS (SN)	NOT NECESSARY	60.00	-
1	SET BONNET LOCK GARNISH CLIPS (SN)	NECESSARY	40.00	20.00
1	SET FRT GRILLE CLIPS (SN)	NECESSARY	40.00	20.00
1	SET FRT FENDER COWLING CLIPS RH (SN)	NECESSARY	60.00	30.00
1	SET FRT BUMPER GRILLE CLIPS (SN)	NECESSARY	30.00	10.00
1	FRT NUMBER PLATE (SN)	DENTED	50.00	50.00
1	SET FRT BUMPER INNER GARNISH CLIPS RH (SN)	NOT NECESSARY	30.00	-
1	SET FRT BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
			370.00	160.00
	<u>LABOUR</u>			
	TO REMOVE AND REPLACE THE DAMAGED PARTS ,KNOCK OUT ACCIDENT DENTED PORTIONS AND FOR CUTTING /WELDING WORKS.		1,600.00	1,100.00
	TO SPRAY PAINTING.		1,200.00	800.00
	TO SPRAY UNDERSEAL.		100.00	40.00
	TO REPLACE FRONT PARKING SENSORS.		80.00	50.00
	TO REFILL AIRCON GAS.		120.00	80.00
	TO CHECK WIRING.		50.00	30.00
	TO PROGRAMME AND RESET.		350.00	150.00
			3,500.00	2,250.00
	GRAND TOTAL		18,705.20	15,035.36

Report Ref No. CC6/CTI22000394/Apa3q2



RECOMMENDED COST OF REPAIRS			15,035.36
-----------------------------	--	--	-----------

Report Ref No. CC6/CT122000394/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SNB 1965H

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SNB 1965H

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SNB 1965H

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

