



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2205342
3 ANSON ROAD #16-00	INV Date	30/08/2022
SPRINGLEAF TOWER	Reference	CC6/CTI22000395/Apa3q2
SINGAPORE 079909	Code	CTI

PROFESSIONAL SERVICE FEE

Vehicle No.	SLE 8977K
Insured Veh.	SKP 7579L
Claim No.	SNM22D200154/C02
Policy No.	DMPCSNW00119782100
Accident Date	05/01/2022
Inspection Date	10/01/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Ref: CC6/CTI22000395/Apa3q2 Date: 30/08/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKP 7579L	Veh. Inspected	SLE 8977K
Policy No.	DMPCSNW00119782100	Coverage (\$)	0.00
Claim No.	SNM22D200154/C02	Excess (\$)	0.00
Assign From		Assign Date	10/01/2022
2. Vehicle Particulars & Condition			
Make & Model	HONDA VEZEL	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU11114635	Colour	WHITE
Odometer	69995 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	YOKOHAMA	6 mm
L/H Front Tyre	215/60 R16	YOKOHAMA	6 mm
R/H Rear Tyre	215/60 R16	YOKOHAMA	6 mm
L/H Rear Tyre	215/60 R16	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	05/01/2022	Inspection Date	10/01/2022
Survey held at	VENTURES AUTO PTE LTD 23 KAKI BUKIT AVENUE 4, #04-01, AAS KAKI BUKIT CENTRE, SINGAPORE 415933		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 8977K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	RR BUMPER	DEFORMED	765.00	765.00
1	RR BUMPER RH	TORN	177.00	177.00
1	RR BUMPER LH	TORN	177.00	177.00
1	RR BUMPER SIDE RETAINER RH	NECESSARY	66.00	42.00
1	RR BUMPER SIDE RETAINER LH	NECESSARY	66.00	42.00
1	RR BUMPER REFLECTOR RH	CRACKED	181.00	181.00
1	RR BUMPER REFLECTOR LH	NOT NECESSARY	181.00	-
1	RR TAILGATE	DENTED	1,166.00	1,166.00
1	RR TAILGATE LOGO	NOT NECESSARY	88.00	-
1	RR TAILGATE VEZEL EMBLEM	NECESSARY	92.00	92.00
1	RR TAILGATE REFLECTOR RH	NOT NECESSARY	418.00	-
1	RR TAILGATE REFLECTOR LH	NOT NECESSARY	418.00	-
1	RR TAILGATE WEATHERSTRIP	CUT	174.00	174.00
1	RR TAILGATE WINDSCREEN MLDG	NECESSARY	134.00	134.00
2	RR TAILGATE STOPED @\$16.00	NOT NECESSARY	32.00	-
1	RR TAILGATE KEYLESS RECEIVER SENSOR	DAMAGED	187.00	187.00
1	RR ARLARM BUZZER	DAMAGED	104.00	104.00
1	RR TAILGATE LOCK	DAMAGED	216.00	216.00
1	RR TAILGATE LOCK CATCHER	NOT NECESSARY	87.00	-
1	RR TAILGATE OUTER GARNISH	NOT NECESSARY	276.00	-
1	RR END PANEL	DENTED	598.00	598.00
1	RR END PANEL TOP GARNISH	CRACKED	120.00	120.00
1	RR TAILLAMP RH	NOT NECESSARY	613.00	-
1	RR TAILLAMP LH	NOT NECESSARY	613.00	-
1	RR TAILLAMP PANEL RH	NOT NECESSARY	114.00	-
1	RR TAILLAMP PANEL LH	NOT NECESSARY	114.00	-
1	RR FENDER PROTECTOR RH	CRACKED	206.00	206.00
1	RR FENDER PROTECTOR LH	NOT NECESSARY	206.00	-
1	RR FENDER INNER SHIELD RH	NOT NECESSARY	114.00	-
1	RR FENDER INNER SHIELD LH	NOT NECESSARY	114.00	-
1	RR FENDER INNER TRIM BOARD RH	NOT NECESSARY	386.00	-

Report Ref No. CC6/CTI22000395/Apa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RR FENDER INNER TRIM BOARD LH	NOT NECESSARY	386.00	-
1	RR EXHAUST SILENCER BOX	NOT NECESSARY	1,207.00	-
1	RR BUMPER UNDER DUST COVER	TORN	198.70	198.70
	LESS 20% DISCOUNT		-1,998.94	-915.94
			7,995.76	3,663.76
	<u>SPECIAL NETT ITEMS</u>			
10	RR BUMPER CLIP (SN)	NECESSARY	80.00	30.00
10	RR TAILGATE INNER TRIM BOARD CLIP (SN)	NOT NECESSARY	80.00	-
5	RR FENDER PROTECTOR CLIP (SN)	NOT NECESSARY	60.00	-
5	RR END PANEL TOP GARNISH CLIP (SN)	NECESSARY	60.00	20.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	100.00	60.00
1	RR REVERSE SENSOR (SN)	DAMAGED	220.00	200.00
1	RR REVERSE CAMERA (SN)	NOT NECESSARY	80.00	-
1	RR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	60.00
1	RR WINDSCREEN INNER SEAL (SN)	NOT NECESSARY	80.00	-
1	RR WINDSCREEN SOLAR FILM (SN)	NOT NECESSARY	40.00	-
			880.00	370.00
	<u>LABOUR</u>			
	TO RENEW DAMAGED PARTS ,REPLACE BEAT ,WELD ,REALIGN ,STRAIGHTENED MEMBER .		1,600.00	800.00
	TO RESPRAY AFFECTED AREAS .		1,600.00	800.00
	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR.		120.00	30.00
	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT.		100.00	80.00
	REMOVE AND REFIX SEAT CUSHION/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIRS.		160.00	80.00
	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST.		100.00	50.00
	TO REMOVE AND REFIX REVERSE CAMERA AND CONDUCT TEST.		100.00	50.00
	TO CONDUCT TRANSFER OF PARTS FROM OLD TAILGATE TO NEW TAILGATE.		160.00	80.00

Report Ref No. CC6/CTI22000395/Apa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIR OF VEHICLE.	NOT NECESSARY	80.00	-
	TO REMOVE AND REPLACE EXHAUST PIPE.	NOT NECESSARY	200.00	-
	TO REMOVE AND REFIX REAR TAIL GATE WINDSCREEN.		180.00	120.00
			4,400.00	2,090.00
GRAND TOTAL			13,275.76	6,123.76
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,900.00

Report Ref No. CC6/CTI22000395/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLE 8977K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLE 8977K

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLE 8977K

RE-INSPECTION

