3/1/23, 2:46 PM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG22000396/AYA3Q2

01/03/2023 Date:

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7210066126 **Claimant Vehicle** SLD8168J Insured Vehicle No: SNA7131M No:

Date of Loss: 10/01/2022 Nature of Claim: TP Claim No: 5954563403SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **SLD8168J** 

Make & Model: BMW 520I, 2.0 ADAP LED HL (A) 17706281B48B20A Engine No: Reg. Date: 26/02/2021 (Man. Year: 2020) Chassis No: WBA72AG0X0WX08559

Colour: Odometer: 14809 km Black

**Engine Capacity:** 1998 cc Market Value/New Car N/A Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): Yes **Engine Modification:** No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R18 245/45 R18 Rear Tyre Size: Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS      |                                   | Repairer's          | Adjuster's | Difference | Diff % |
|---------------------|-----------------------------------|---------------------|------------|------------|--------|
| Parts               |                                   | 7,966.00            | 3,100.50   | 4,865.50   | 61.08  |
| Miscellaneous Items |                                   | 0.00                | 0.00       | 0.00       |        |
| Labour              |                                   | 2,050.00            | 1,270.00   | 780.00     | 38.05  |
| Paintwork Labour    |                                   | 0.00                | 0.00       | 0.00       |        |
| Towing              |                                   | 0.00                | 0.00       | 0.00       |        |
|                     | Calculated Gross Total (S\$)      | 10,016.00           | 4,370.50   | 5,645.50   | 56.36  |
|                     | Approved Total (Overridden) (S\$) |                     | 3,500.00   |            |        |
|                     | Nett Amount (S\$)                 | 10,016.00           | 3,500.00   | 6,516.00   | 65.06  |
|                     | + Car Rental (2.0 x S\$1          | 50.00/day) (S\$)    | 300.00     |            |        |
|                     | + Doc/S                           | Search Fee (S\$)    | 7.45       |            |        |
|                     | Ne                                | ett Liability (S\$) | 3,807.45   |            |        |

**INSPECTION** 

Date of Assignment: 11/01/2022

Ysk Auto Workshop (HQ)

No.1 Kaki Bukit Avenue 6, #01-49 Autobay Date Inspected: 11/01/2022 Inspected At:

Singapore 417883

Estimated Period of Repair: 3.0 days

**ADRIAN LING** Adjuster: Manager: Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### **REPAIR DETAILS**

# **Recommended Parts**

| Qty   | Part No.     | Particulars   | Condition  | Repairer's   | Amount   |
|---|--------------|---|--|--|--|
| 1   |              | *REAR BUMPER  | Deformed   | 1,658.00 F   | *1,445.00 FL   |
| 1   |              | *REAR BUMPER CLIPS  | Necessary  | 50.00 F  | *50.00 FL  |
| 2   |              | *REAR BUMPER SIDE HOLDER  | Not Necessary  | 190.00 F   | *- FL  |
| 1   |              | *REAR BUMPER COVER GARNISH  | Deformed   | 328.00 F   | *328.00 FL   |
| 1   |              | *REAR BUMPER TOW COVER  | Not Necessary  | 40.00 F  | *- FL  |
| 2   |              | *REAR BUMPER REFLECTOR  | Not Necessary  | 136.00 F   | *- FL  |
| 1   |              | *REAR BUMPER REINFORCEMENT  | Dented   | 652.00 F   | *568.00 FL   |
| 1   |              | *REAR BUMPER CENTRE GARNISH   | Not Necessary  | 204.00 F   | *- FL  |
| 1   |              | *REAR BUMPER KICK SENSOR  | Not Necessary  | 405.00 F   | *- FL  |
| 1   |              | *REAR BUMPER KICK SENSOR COVER  | Cracked  | 259.00 F   | *259.00 FL   |
| 1   |              | *REAR BUMPER UNDERCOVER   | Not Necessary  | 214.00 F   | *- FL  |
| 4   |              | *REVERSE SENSOR   | Damaged (2 PCS ONLY)   | 1,000.00 F   | *500.00 FL   |
| 4   |              | *REVERSE SENSOR HOLDER  | Necessary  | 80.00 F  | *80.00 FL  |
| 1   |              | *REAR END PANEL   | Repair   | 995.00 F   | *- FL  |
| 1   |              | *REAR END PANEL SEALANT   | Not Necessary  | 60.00 FS   | *- FS  |
| 2   |              | *TAILLAMP   | Not Necessary  | 1,480.00 F   | *- FL  |
| 1   |              | *REAR BUMPER REINFORCEMENT COVER  | Cracked  | 215.00 F   | *215.00 FL   |
| chise   | part. S=Spcl | Nett. L=ListItemDisc.   |  |  |  |
|   |              |   | Sub Total (S\$)  | 7,966.00   | 3,445.00   |
| - List Item Discount on L Items 0.00/10.00% (S\$) |              |   |  | 0.00   | 344.50   |
|   |              |   | Total Parts (S\$)  | 7,966.00   | 3,100.50   |
|   |              | 1<br>1<br>2<br>1<br>1<br>2<br>1<br>1<br>1<br>1<br>1<br>1<br>1<br>1<br>1 | *REAR BUMPER CLIPS  *REAR BUMPER SIDE HOLDER  *REAR BUMPER COVER GARNISH  *REAR BUMPER TOW COVER  *REAR BUMPER REFLECTOR  *REAR BUMPER REINFORCEMENT  *REAR BUMPER CENTRE GARNISH  *REAR BUMPER KICK SENSOR  *REAR BUMPER KICK SENSOR COVER  *REAR BUMPER UNDERCOVER  *REVERSE SENSOR  *REVERSE SENSOR  *REVERSE SENSOR HOLDER  *REAR END PANEL  *REAR END PANEL  *REAR END PANEL SEALANT  *TAILLAMP  *REAR BUMPER REINFORCEMENT COVER  chise part. S=SpcNett. L=ListItemDisc. | *REAR BUMPER Deformed  *REAR BUMPER CLIPS Necessary  *REAR BUMPER SIDE HOLDER Not Necessary  *REAR BUMPER COVER GARNISH Deformed  *REAR BUMPER TOW COVER Not Necessary  *REAR BUMPER REFLECTOR Not Necessary  *REAR BUMPER REINFORCEMENT Dented  *REAR BUMPER CENTRE GARNISH Not Necessary  *REAR BUMPER KICK SENSOR Not Necessary  *REAR BUMPER KICK SENSOR COVER Cracked  *REAR BUMPER KICK SENSOR COVER Cracked  *REAR BUMPER UNDERCOVER Not Necessary  *REVERSE SENSOR Damaged (2 PCS ONLY)  *REVERSE SENSOR HOLDER Necessary  *REAR END PANEL Repair  *REAR END PANEL Repair  *REAR BUMPER REINFORCEMENT COVER Cracked  *Sub Total (\$\$)  - List Item Discount on L Items 0.00/10.00% (\$\$) | *REAR BUMPER Deformed 1,658.00 F *REAR BUMPER CLIPS Necessary 50.00 F  *REAR BUMPER SIDE HOLDER Not Necessary 190.00 F *REAR BUMPER COVER GARNISH Deformed 328.00 F  *REAR BUMPER TOW COVER Not Necessary 40.00 F  *REAR BUMPER REFLECTOR Not Necessary 136.00 F  *REAR BUMPER REINFORCEMENT Dented 652.00 F  *REAR BUMPER REINFORCEMENT Dented 652.00 F  *REAR BUMPER CENTRE GARNISH Not Necessary 204.00 F  *REAR BUMPER KICK SENSOR Not Necessary 405.00 F  *REAR BUMPER KICK SENSOR COVER Cracked 259.00 F  *REAR BUMPER UNDERCOVER Not Necessary 214.00 F  *REAR BUMPER UNDERCOVER Not Necessary 214.00 F  *REVERSE SENSOR Damaged (2 PCS ONLY) 1,000.00 F  *REVERSE SENSOR HOLDER Necessary 995.00 F  *REAR END PANEL Repair 995.00 F  *REAR END PANEL Repair 995.00 F  *REAR END PANEL SEALANT Not Necessary 1,480.00 F  *REAR BUMPER REINFORCEMENT COVER Cracked 215.00 F |

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

| No         | Particulars                | Lab.Type                              | Repairer's | Amount   |
|------------|----------------------------|---------------------------------------|------------|----------|
| <u>Lab</u> | our Items                  |                                       |            |          |
| 1          | PANEL BEATING              | New                                   | 800.00     | 500.00   |
| 2          | SPRAY PAINTING             | New                                   | 600.00     | 500.00   |
| 3          | WIRING                     | New                                   | 50.00      | 30.00    |
| 4          | TO REMOVE REVERSE SENSOR   | New                                   | 100.00     | 60.00    |
| 5          | TO REMOVE UPHOLSTERY       | New                                   | 150.00     | 40.00    |
| 6          | TO PERFORM DIAGNOSTIC TEST | New                                   | 200.00     | 100.00   |
| 7          | TO SPRAY TUFF COAT         | New                                   | 150.00     | 40.00    |
|            |                            | Gross Labour Cost (S\$)               | 2,050.00   | 1,270.00 |
|            | Report wa                  | as unsubmitted during this print-out. |            |          |

< END OF ESTIMATES >