



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2207311

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 25/11/2022
Reference CC6/CTI22000399/Kpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SML 9733S
Insured Veh. SFG 605Y
Claim No. SNM22D200172/C02
Policy No. DMPCSNW00011962100
Accident Date 06/01/2022
Inspection Date 10/01/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22000399/Kpa3q2	
			Date: 25/11/2022	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SFG 605Y	Veh. Inspected	SML 9733S	
Policy No.	DMPCSNW00011962100	Coverage (\$)	0.00	
Claim No.	SNM22D200172/C02	Excess (\$)	0.00	
Assign From		Assign Date	10/01/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	MR053REH104528846	Colour	METALLIC GREY	
Odometer	395057 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	YOKOHAMA	8 mm	
L/H Front Tyre	205/55 R16	YOKOHAMA	8 mm	
R/H Rear Tyre	205/55 R16	FIRENZA	7 mm	
L/H Rear Tyre	205/55 R16	FIRENZA	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/01/2022	Inspection Date	10/01/2022	
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SML 9733S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	LID	TO REPAIR SEE LABOUR	655.80	-
1	LID -COROLLA EMBLEM	NECESSARY	42.35	42.35
1	LID-ALTIS EMBLEM	NECESSARY	44.17	44.17
1	LID -TOYOTA LOGO	NECESSARY	50.25	50.25
1	LID HANDLE	SERVICEABLE	298.20	-
1	LID LOCK	TO REPAIR SEE LABOUR	382.00	-
2	LID REFLECTOR	SERVICEABLE	590.40	-
2	LID HINGE	TO REPAIR SEE LABOUR	184.00	-
1	END PANEL	TO REPAIR SEE LABOUR	581.20	-
1	END PANEL TOP GARNISH	DENTED	229.40	229.40
1	REAR BUMPER	BUCKLED	482.00	482.00
1	REAR BUMPER SPONGE	SERVICEABLE	75.20	-
1	REAR BUMPER RETAINER	DISTORTED	92.33	92.33
2	REAR BUMPER REFLECTOR	SERVICEABLE	113.80	-
1	REAR BUMPER ENFORCEMENT	BENT	301.60	301.60
2	TAILLAMP	O/S SERVICEABLE / N/S CRACKED	603.20	301.60
	LESS 25% DISCOUNT		-1,181.48	-385.93
			3,544.42	1,157.77
1	BOOT WEATHERSTRIP (50%) (SN)	DENTED / DISTORTED	166.40	83.20
	LESS 25% DISCOUNT		-41.60	-
			124.80	83.20
	<u>SPECIAL NETT ITEMS</u>			
1	REVERSE SENSOR (SN)	DENTED	220.00	200.00
			220.00	200.00

Report Ref No. CC6/CTI22000399/Kpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>LABOUR</u>			
	TO REMOVE DAMAGED PARTS & ATTACHMENTS WIELD AND CUT DAMAGED PANEL REPAIR /RESHAPE DENTED AREAS STRAIGHTEN REAR CHASSIS WHEN NECESSARY REPLACE /ALIGN ALL PARTS INTO POSITION.INCLUSIVE OF THE REPAIR OF LID,LID LOCK ,LID HINGE AND END PANEL.		1,100.00	450.00
	TO SPRAY PAINT.		1,200.00	600.00
			2,300.00	1,050.00
GRAND TOTAL			6,189.22	2,490.97
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,000.00

Report Ref No. CC6/CTI22000399/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SML 9733S

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SML 9733S

RE-INSPECTION

