



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBP 5809T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
2	BALANCER HANDLE @\$12.00	N/S CUT	24.00	12.00
1	BOARD FOOTREST LH	CUT	51.00	51.00
1	COVER SIDE LOWER LH (GREY)	CUT	21.00	21.00
1	COVER SIDE LOWER RH (GREY)	CUT	21.00	21.00
1	COWLING FRONT RH (GREY)	CUT	31.00	31.00
1	EMBLEM (YAMAHA) LOGO	NECESSARY	28.00	28.00
1	LAMP SIGNAL FRONT RH	CRACKED	34.00	34.00
1	PANEL 2 (MATTE BLACK) RH	CUT	21.00	21.00
1	SPRING FOR SIDE STAND	NOT NECESSARY	2.00	-
1	SPRING FOR SIDE STAND	NOT NECESSARY	5.00	-
1	STAND SIDE	DAMAGED	23.00	23.00
	LESS 10% DISCOUNT		-	-24.20
			261.00	217.80
	<b><u>LABOUR</u></b>			
	LABOUR - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.		189.00	150.00
	TRANSPORT CHARGES - BIKE TOWED BACK TO BHH.	NOT NECESSARY	56.00	-
			245.00	150.00
<b>GRAND TOTAL</b>			<b>506.00</b>	<b>367.80</b>

<b>RECOMMENDED COST OF REPAIRS</b>				<b>367.80</b>
------------------------------------	--	--	--	---------------

Report Ref No. CS/UOI22000400/Uvf3e2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.