

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	UNITED OVERSE	AS INSURANCE LTD	Ref	: CS/UOI22000400/Uvf3e2	
	146 ROBINSON R #02-01 UOI BUILD	OAD INGSINGAPORE 068909	Dat	e: 28/02/2022	
			Cod	de: UOI2	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YP 4174A	Veh. Inspected	FBP 5809T	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	M11D14472201	Excess (\$)	0.00	
	Assign From	JOSEPHINE WONG	Assign Date	12/01/2022	
2. Vehicle Particulars & Condition					
	Make & Model	YAMAHA NMAX	c.c	155	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	MH3SG431000011194	Colour	GREY	
	Odometer	70658 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	110-70-13	TIMSUN	6 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	130-70-13	TIMSUN	6 mm	
	L/H Rear Tyre			mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	08/01/2022	Inspection Date	12/01/2022	
	Survey held at	BAN HOCK HIN CO.PTE LTD			
		NO 6 DEFU LANE 4 SINGAPORE 539410			
5a.		Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.		Estimate Days of Repair			
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days			