

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG22000408/AVCN2**Date:** 23/03/2022**REFERENCE**

Insured/Claimant:	CHOO KA SING	Policy No:	2100379091	
Date of Loss:	08/01/2022	Nature of Claim:	OD	Claim No: 3005365014SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SGN6668C</b>		
Make & Model:	AUDI A3, 1.4 SEDAN TFSI (AMBIENTE) (A)	Engine No:	CXS203064
Reg. Date:	26/07/2014 (Man. Year: 2014)	Chassis No:	WAUZZZ8V0E1041650
Colour:	Bronze	Odometer:	84568 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$43,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	12,287.00	668.96	11,618.04	94.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,202.00	1,242.00	1,960.00	61.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>15,489.00</b>	<b>1,910.96</b>	<b>13,578.04</b>	<b>87.66</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,084.23</b>	<b>133.77</b>	<b>950.46</b>	<b>87.66</b>
<b>Nett Amount (S\$)</b>	<b>16,573.23</b>	<b>2,044.73</b>	<b>14,528.50</b>	<b>87.66</b>

**INSPECTION**

Date of Assignment:	13/01/2022		
Date Inspected:	11/01/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

**Adjuster:** ADRIAN LING**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,233.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	187.00 FS	*- FS
3	2		*FRONT BUMPER TRIM COVER-LH/RH	Not Necessary	326.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTER	Not Necessary	163.00 FS	*- FS
5	4		*FRONT BUMPER PULL STRAP-LOWER	Not Necessary	206.00 FS	*- FS
6	2		*FRONT BUMPER GUIDE SECTION-LH/RH	Not Necessary	78.00 FS	*- FS
7	2		*FRONT BUMPER AIR GUIDE GRILLE-LH/RH	Not Necessary	218.00 FS	*- FS
8	1		*RADIATOR GRILLE	Cracked	691.00 FS	*552.40 FS
9	1		*RADIATOR GRILLE COVER	Not Necessary	98.00 FS	*- FS
10	1		*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
11	1		*AIR COND STICKER	Not Necessary	8.00 FS	*- FS
12	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	137.00 FS	*- FS
13	1		*FRONT BUMPER LOWER COVER	Not Necessary	56.00 FS	*- FS
14	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	795.00 FS	*- FS
15	2		*HORN RETAINER-LH/RH	Not Necessary	400.00 FS	*- FS
16	2		*FRONT WHEEL HOUSING LINER-LH/RH	Not Necessary	338.00 FS	*- FS
17	2		*HEADLIGHT-LH/RH	Not Necessary	5,282.00 FS	*- FS
18	2		*LIFT CYLINDER-LH/RH	Not Necessary	386.00 FS	*- FS
19	1		*LIFT CYLINDER HOSE	Not Necessary	182.00 FS	*- FS
20	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	19.00 FS	*- FS
21	2		*RADIATOR AIR GUIDE-LH/RH	Not Necessary	50.00 FS	*- FS
22	1		*RADIATOR SEAL-RH OUTER	Not Necessary	8.00 FS	*- FS
23	1		*RADIATOR AIR GUIDE-UPPER CENTER	Not Necessary	12.00 FS	*- FS
24	1		*FRONT NO PLATE	Dented	100.00 FS	*100.00 FS
25	1		*SUNDRIES	Necessary	300.00 FS	*16.56 FS
					<b>Total Parts (S\$)</b>	<b>12,287.00      668.96</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	700.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHT.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
4	TO RESPRAY FRONT BUMPER	New	900.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,202.00</b>	<b>1,242.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >