

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22000409/ETCE2

Date: 16/04/2022

REFERENCE

Insured/Claimant: LIM WEI JIE, NIGEL (LIN WEIJIE) Policy No: 2070139095
Date of Loss: 09/01/2022 Nature of Claim: OD Claim No: 8436234286SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMV4752S**
Make & Model: AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A) Engine No: CZDC00124
Reg. Date: 30/09/2020 (Man. Year: 2020) Chassis No: WAUZZZF34L1123797
Colour: Black Odometer: 17816 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$150,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R19 Rear Tyre Size: 235/50 R19
Front Left Side: Michelin 4 mm Rear Left Side: Michelin 4 mm
Front Right Side: Michelin 4 mm Rear Right Side: Michelin 4 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,630.00	14,638.72	15,991.28	52.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,624.00	4,164.00	9,460.00	69.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	44,254.00	18,802.72	25,451.28	57.51
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	43,854.00	18,402.72	25,451.28	58.04
+ GST 7.00/7.00% (S\$)	3,069.78	1,288.19	1,781.59	58.04
Nett Amount (S\$)	46,923.78	19,690.91	27,232.87	58.04

INSPECTION

Date of Assignment: 12/01/2022

Date Inspected: 11/01/2022 Inspected At:

24 Benoi Sector

Singapore 629857

Repairer: Premium Automobiles Pte Ltd

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Dented	2,670.00 FS	*2,136.00 FS
2	1		*FRONT BUMPER CONNECTING PIECE	Not Necessary	145.00 FS	*- FS
3	1		*FRONT BUMPER FIXING PARTS	Not Necessary	414.00 FS	*- FS
4	2		*FRONT BUMPER CLOSING ELEMENT - LH / RH	Not Necessary	118.00 FS	*- FS
5	1		*FRONT BUMPER TRIM	Cut	356.00 FS	*284.40 FS
6	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	217.00 FS	*- FS
7	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	50.00 FS	*- FS
8	1		*FRONT BUMPER LOWER SENSOR COVER	Not Necessary	51.00 FS	*- FS
9	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	190.00 FS	*- FS
10	1		*FRONT BUMPER SPOILER	Cut	763.00 FS	*610.00 FS
11	1		*FRONT BUMPER BRACKET	Not Necessary	21.00 FS	*- FS
12	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	306.00 FS	*- FS
13	2		*FRONT BUMPER AIR GUIDE GRILLE TRIM - LH / RH	Not Necessary	328.00 FS	*- FS
14	2		*FRONT PARKING AID SENSOR BRACKET - LH / RH	Not Necessary	50.00 FS	*- FS
15	1		*FRONT RADIATOR GRILLE	Broken	1,928.00 FS	*1,542.40 FS
16	1		*FRONT STRIKER PLATE	Broken	244.00 FS	*194.80 FS
17	1		*FRONT BUMPER LOWER COVER CAP - CENTER	Cut	56.00 FS	*44.80 FS
18	1		*FRONT RADIATOR BRACKET	Not Necessary	41.00 FS	*- FS
19	1		*FRONT RADIATOR COVER	Not Necessary	244.00 FS	*- FS
20	1		*FRONT BUMPER CAMERA	Not Necessary	1,141.00 FS	*- FS
21	1		*SET FRONT BUMPER CAMERA WIRING	Torn	572.00 FS	*457.60 FS
22	2		*FRONT PARKING AID SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
23	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	9.00 FS	*- FS
24	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	102.00 FS	*- FS
25	1		*FRONT BUMPER REINFORCEMENT BAR	Dented	916.00 FS	*732.40 FS
26	2		*FRONT BUMPER GUIDE SUPPORT - LH / RH	Not Necessary	78.00 FS	*- FS
27	1		*FRONT BUMPER TOP COVER	Broken	123.00 FS	*98.00 FS
28	1		*AIR COND STICKER	Necessary	8.00 FS	*5.68 FS
29	2		*HORN - LH / RH	Not Necessary	267.00 FS	*- FS
30	2		*HORN BRACKET - LH / RH	Not Necessary	44.00 FS	*- FS
31	1		*FRONT FENDER - LH	Repair	1,286.00 FS	*- FS
32	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	63.00 FS	*- FS
33	1		*FRONT FENDER BRACE - LH	Not Necessary	88.00 FS	*- FS
34	1		*FRONT FENDER BRACKET - LH	Not Necessary	32.00 FS	*- FS
35	1		*FRONT BONNET	Dented	3,508.00 FS	*2,806.40 FS
36	1		*FRONT BONNET IMPACT PROTECTION	Necessary	28.00 FS	*21.84 FS
37	2		*FRONT BONNET HINGE - LH / RH	Not Necessary	146.00 FS	*- FS
38	1		*FRONT BONNET ATTACHEMENT PARTS	Not Necessary	296.00 FS	*- FS
39	2		*FRONT BONNET STRIKER - LH / RH	Not Necessary	220.00 FS	*- FS
40	1		*FRONT BONNET INSULATION COVER	Not Necessary	219.00 FS	*- FS
41	2		*FRONT BONNET HINGE COVER - LH / RH	Not Necessary	82.00 FS	*- FS
42	1		*FRONT BONNET BOWDEN CABLE	Not Necessary	58.00 FS	*- FS
43	1		*FRONT BONNET BOWDEN CABLE COVER	Not Necessary	10.00 FS	*- FS
44	1		*FRONT BONNET RELEASE CABLE	Not Necessary	58.00 FS	*- FS
45	1		*FRONT BONNET RELEASE LEVER	Not Necessary	14.00 FS	*- FS
46	2		*FRONT BONNET LOCK	Not Necessary	427.00 FS	*- FS
47	1		*FRONT BONNET GAS ABSORBER	Not Necessary	104.00 FS	*- FS
48	1		*FRONT HEADLIGHT MOUNTING - LH / RH	N/S Broken	236.00 FS	*94.40 FS
49	1		*FRONT HEADLIGHT - LH	Cut	5,589.00 FS	*4,471.20 FS
50	1		*FRONT HEADLIGHT LIFT CYLINDER - LH	Not Necessary	210.00 FS	*- FS
51	1		*FRONT HEADLIGHT HOSE - LH	Torn	80.00 FS	*63.44 FS
52	1		*FRONT RADIATOR SUPPORT	Not Necessary	1,272.00 FS	*- FS
53	1		*TEMPERATURE SENSOR BRACKET	Not Necessary	7.00 FS	*- FS
54	1		*AIR COND CONDENSER	Not Necessary	551.00 FS	*- FS
55	1		*ADDITIONAL RADIATOR	Not Necessary	920.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*RADIATOR	Not Necessary	1,035.00 FS	*- FS
57	6		*COOLANT	Broken	266.00 FS	*- FS
58	2		*FRONT AIR GUIDE - LH / RH	Not Necessary	76.00 FS	*29.76 FS
59	2		*FRONT WHEEL ARCH COVER - LH / RH	Necessary	1,072.00 FS	*857.60 FS
60	1		*AIR COND COMPRESSOR TO AIR CON CONDENSER	Not Necessary	337.00 FS	*- FS
61	1		*AIR COND CONDENSER TO CUT OFF POINT	Not Necessary	330.00 FS	*- FS
62	1		*FRONT NO PLATE	Bent	60.00 FS	*60.00 FS
63	1		*SUNDRIES	Necessary	400.00 FS	*128.00 FS
64	2		*FRONT AIR GUIDE - UPPER / LOWER	Not Necessary	82.00 FS	*- FS
65	1		*SIGN CAUTION STICKER	Not Necessary	16.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	30,630.00	14,638.72
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. VACUUM AND REGAS	New	1,700.00	0.00
4	TO RENEW LHS FRONT FENDER INNER AIRCON CONDENSER PIPE	New	280.00	0.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDERS AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,600.00	1,000.00
6	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, BONNET, HINGES, LHS FRONT FENDER AND BOTH WHEEL ARCH TRIMS	New	4,500.00	2,050.00
7	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE	New	280.00	0.00
8	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	384.00
Gross Labour Cost (\$\$)			13,624.00	4,164.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >