



ICOBOT TECH PTE LTD

32 Defu Lane #03-16 Singapore 539213
www.icobot.com.sg / email :admin@icobot.com.sg
Co.Reg.No. 20181362G GST Reg.No. 20181362G

Date : 12.012.022

To : YONG AIK CONSTRUCTION PTE LTD

Attention : Mr Marcus

Re : Finding Report of the Damaged TMA Blade Series Number 2021-Mounted on Vehicle Number XD6073U .

Dear Marcus,

We refer to your damaged TMA Blade with series nos. 2021-BC18 attached to Vehicle Nos. XD6073U. We wish to inform you that the main structure are bended and twisted and is impossible to repair. As TMA are a safety equipment's to protect life ,therefore in this case, we recommended changing the whole attenuator cartridge.

We had listed out parts that are visible damaged and finding for your reference.

1. Bended H Beam left and right
2. Yellow Tube seem to be bend
2. Broken tailgate lights
3. Alignments are off

*Note : Items which we are unable to inspect are the motor controlling the H beam, since the TMA are not in working order. Taking into account that it is unable to extend nor retract, sensor inside the yellow tube and gear rack mounted on the H Beam may have been affected as well.

The cost to repair these listed parts as above will not be cheaper than a complete cartridge after all.

Hereby we had attached photos of the damages for your references.

Should you need any clarifications, please kindly contact Joey Tan 8111 0535

Regards

Mr Joey Tan
Director


1. This Picture shown that the TMA had slid to one side towards the right of the driver side and the Tailgate light is broken.



2. The Yellow Tube are bend



The H Beam Both Left and Right Side are bend and twisted



The H Beam Both Left and Right Side are bend and twisted

