

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000414/AVF3Q2**Date:** 22/04/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00068512101

Claimant Vehicle No : GBH3160K **Insured Vehicle No :** GBB2141D

Date of Loss: 08/01/2022 Nature of Claim: TP Claim No: SNM22D200260/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBH3160K**

Make & Model: TOYOTA HIACE, 3.0 D DX (A) Engine No: 1KD2742132

Reg. Date: 17/04/2018 (Man. Year: 2017) Chassis No: KDH2010230875

Colour: Silver Odometer: 93036 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C

Front Left Side: Triangle 6 mm Rear Left Side: Triangle 6 mm

Front Right Side: Triangle 6 mm Rear Right Side: Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,547.50	3,622.50	6,925.00	65.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,360.00	1,760.00	3,600.00	67.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,907.50	5,382.50	10,525.00	66.16
Approved Total (Overridden) (\$\$)		4,300.00		
Nett Amount (\$\$)	15,907.50	4,300.00	11,607.50	72.97

INSPECTION

Date of Assignment: 11/01/2022

Date Inspected: 10/01/2022 Inspected At: JL Perfect Autowork Pte Ltd (HQ)
8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki
Bukit
Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Apr 2022)
Parts:	213	TOYOTA HIACE 3.0 D DX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH3160K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SLIDING DOOR RH	Distorted	1,650.00 FL	*1,650.00 FL
2	1		*SLIDING DOOR SWITCH CONNECTOR	Damaged	88.00 FL	*88.00 FL
3	1		*SLIDING DOOR STEP PANEL RH	Repair	817.00 FL	*- FL
4	1		*SLIDING DOOR LOWER RAILWAY PANEL RH	Repair	946.00 FL	*- FL
5	1		*SLIDING DOOR ROLLER (CENTRE) RH	Bent	317.00 FL	*317.00 FL
6	1		*SLIDING DOOR LOCK CATCHER RH	Not Necessary	26.00 FL	*- FL
7	1		*SLIDING DOOR INNER LOCK RH	Damaged	522.00 FL	*358.00 FL
8	2		*SET SLIDING DOOR STOPPER	Not Necessary	54.00 FL	*- FL
9	1		*SLIDING DOOR FRAME WEATHER STRIP RH	Necessary	331.00 FL	*331.00 FL
10	1		*SLIDING DOOR INNER BOARD RH	Torn	325.00 FL	*185.00 FL
11	1		*SLIDING DOOR GLASS RH	Shattered	960.00 FS	*780.00 FS
12	1		*SLIDING DOOR GLASS MOULDING RH	Necessary	181.00 FL	*181.00 FL
13	1		*REAR SIDE PANEL RH	Repair	1,848.00 FL	*- FL
14	1		*REAR SIDE PANEL MUDFLAP RH	Not Necessary	196.00 FL	*- FL
15	1		*ROCKER PANEL RH	Repair	388.00 FL	*- FL
16	1		*REAR AXLE	Not Necessary	1,989.00 FL	*- FL
17	1		*REAR SHOCK ABSORBER RH	Not Necessary	439.00 FL	*- FL
18	1		*REAR WHEEL HUP RH	Not Necessary	390.00 FL	*- FL
19	1		*REAR WHEEL HUP BEARING RH	Not Necessary	187.00 FL	*- FL
20	1		*REAR STABILIZER BAR	Not Necessary	436.00 FL	*- FL
21	1		*REAR STABILIZER LINKAGE RH	Not Necessary	160.00 FL	*- FL
22	1		*SET SLIDING DOOR INNER BOARD CLIP RH	Necessary	50.00 FS	*30.00 FS
23	1		*SLIDING DOOR GLASS SEALANT RH	Necessary	80.00 FS	*60.00 FS
24	1		*SLIDING DOOR GLASS INNER SEAL RH	Necessary	60.00 FS	*40.00 FS
25	1		*REAR SIDE PANEL SEALANT RH	Not Necessary	80.00 FS	*- FS
26	1		*REAR FLOOR PANEL TOP BOARD (SPECIAL TYPE)	Torn	850.00 FS	*380.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,370.00	4,400.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,822.50	777.50
Total Parts (\$\$)	10,547.50	3,622.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOCING AND REPLACING PARTS	New	1,800.00	700.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,600.00	700.00
3	TUFF COAT	New	250.00	60.00
4	WIRING CHECK	New	180.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	350.00	50.00
6	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
7	TRANSFER SLIDING DOOR MECHANISM RH	New	80.00	80.00
8	REMOVE AND REFIX SLIDING DOOR GLASS RH	New	100.00	60.00
9	REMOVE AND REFIX REAR SIDE PANEL RAILWAY RH	New	80.00	0.00
10	REMOVE AND REFIX REAR SIDE PANEL GLASS RH	New	100.00	0.00
11	VACUUM AND CLEAN FRONT WINDSCREEN GLASS SPLINTER	New	380.00	80.00
12	REMOVE AND REFIX REAR WHEEL BEARING	New	60.00	0.00
13	FOUR WHEEL ALIGNMENT	New	120.00	0.00
14	TO CHECK DIAGNOSTIC OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			5,360.00	1,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >