3/29/22, 10:40 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI22000416/KTCN2

29/03/2022 Date:

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MH001423 **Claimant Vehicle**

SHD9853E Insured Vehicle No: SKV2068X No:

Date of Loss: 31/12/2021 Nature of Claim: TP Claim No: M2200121

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD9853E

Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) 2ZR2H38514 Engine No:

Reg. Date: 23/12/2020 (Man. Year: 2020) Chassis No: JTDKB3FU703093242

Colour: Metallic Pearl White/Red Odometer: 83939 km

Engine Capacity: 1798 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15 Front Left Side: Rear Left Side: Dunlop 3 mm Firenza 9 mm Front Right Side: Firenza 9 mm Rear Right Side: Dunlop 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		14,851.85	5,747.45	9,104.40	61.30
Miscellaneous Items		0.00	0.00	0.00	
Labour		8,670.00	1,180.00	7,490.00	86.39
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	23,521.85	6,927.45	16,594.40	70.55
+	GST 7.00/7.00% (S\$)	1,646.53	484.92	1,161.61	70.55
	Nett Amount (S\$)	25,168.38	7,412.37	17,756.01	70.55

INSPECTION

Date of Assignment: 13/01/2022

Trans-cab Auto Services Pte Ltd Date Inspected: 11/01/2022 Inspected At:

No 2 Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

3/29/22, 10:40 AM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Mar 2022)

Parts: 144 TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List) **Print Code:** (Unsubmitted, no print-code for SHD9853E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*COVER FRONT BUMPER	Bent	521.00 FL	-	*521.00 FL
2	1		*BRACKET,FRONT BUMPER EXTENSION MOUNTING	Repair	110.50 FL	-	*-FL
3	1		*REINFORCEMENT SUB-ASSY,FRONT BUMPER	Repair	716.60 FL	-	*-FL
4	1		*ABSORBER,FRONT BUMPER ENERGY	Serviceable	80.20 FL	-	*- FL
5	1		*SUPPORT,FRONT BUMPER SIDE,RH	Distorted	80.10 FL	-	*80.10 FL
6	1		*EXTENSION,FRONT BUMPER,RH	Serviceable	120.10 FL	-	*- FL
7	1		*COVER,FRONT BUMPER HOLE,RH	Serviceable	30.20 FL	-	*- FL
8	1		*MOULDING,FRONT BUMPER SIDE,RH	Cracked	95.60 FL	-	*95.60 FL
9	1		*GRILLE SUB-ASSY,RADIATOR	Serviceable	422.50 FL	-	*- FL
10	1		*GRILLE,RADIATOR,LOWER NO.1	Serviceable	178.60 FL	-	*- FL
11	1		*EMBLEM ASSY,RADIATOR GRILLE	Necessary	105.80 FL	-	*105.80 FL
12	1		*JAR ASSY,WINDSHIELD WASHER	Repeated	219.10 FL	-	*- FL
13	1		*UNIT ASSY,HEADLAMP,RH	Mtg Cracked	2,637.60 FL	-	*2,637.60 FL
14	1		*FENDER SUB-ASSY,FRONT RH	Bent	977.80 FL	-	*977.80 FL
15	1		*LINER,FRONT FENDER RH	Distorted/Cracked	202.50 FL	-	*202.50 FL
16	1		*EMBLEM,SIDE PANEL,RH	Necessary	54.60 FL	-	*54.60 FL
17	1		*JAR ASSY,WINDSHIELD WASHER	Dented	219.10 FL	-	*219.10 FL
18	1		*HOOD SUB-ASSY	Repair	983.10 FL	-	*- FL
19	1		*HINGE ASSY,HOOD,LH	Repair	58.90 FL	-	*- FL
20	1		*HINGE ASSY,HOOD,RH	Repair	58.90 FL	-	*- FL
21	1		*COVER SUB-ASSY,FRONT PILLAR,UPR RH	Missing	100.40 FL	-	*100.40 FL
22	1		*MIRROR ASSY,OUTER REAR VIEW,RH	Serviceable	1,436.60 FL	-	*- FL
23	1		*RIM	Dented	1,900.10 FL	-	*1,900.10 FL
24	1		*TYRE	Punctured	350.00 FS	-	*250.00 FS
25	1		*HUB CAP	Dented	211.50 FS	; <u> </u>	*211.50 FS
26	1		*SET BUMPER CLIP FRT	Necessary	95.00 FS	-	*50.00 FS
27	1		*SET FRNT BUMPER RETAINER CLIP	Not Necessary	85.00 FS	-	*-FS
28	1		*FENDER LINER CLIP	Necessary	65.00 FS	-	*65.00 FS
29	1		*FENDER CLIP	Not Necessary	70.00 FS	-	*-FS
30	1		*WIRE,ENGINE ROOM MAIN	Not Necessary	7,323.90 FL		*- FL
F=Fr	anchica	nart S=9	SpcNett. L=ListItemDisc.	,			

F=Franchise part. S=SpcNett. L=ListItemDisc.

 Sub Total (\$\$)
 19,510.30
 7,471.10

 - List Item Discount on L Items 25.00/25.00% (\$\$)
 4,658.45
 1,723.65

Total Parts (S\$) 14,851.85 5,747.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	2,200.00	500.00
3	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
4	TO REMOVE AND REFIT ELECTRICAL WIRING,BATTERY AND OTHER NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	New	480.00	0.00
5	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	480.00	0.00
6	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR	New	380.00	0.00
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
8	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	30.00
9	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,200.00	550.00
10	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
11	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
12	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
13	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	220.00	20.00
14	TO REMOVE AND REFIT RADIATOR SUPPORT CROSS-MEMBER AND OTHER NECESSARY ITEMS TO ENABLE BODYWORK REPAIR	New	380.00	0.00
15	TO CONDUCT AND PERFORM A COMPREHENSIVE VEHICLE DIAGNOSTIC CHECK AND RESET VEHICLE WARNING INDICATORS	New	380.00	0.00
	Gross Labour	8,670.00	1,180.00	
	Report was unsubmitted during this	orint-out.		

< END OF ESTIMATES >