

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS4/AIG22000421/EVF3E2**Date:** 06/10/2022**REFERENCE**

Insured/Claimant:	TAN SEOW CHENG	Policy No:	1700093733-04	
Date of Loss:	24/12/2021	Nature of Claim:	OD	Claim No: 1638978477SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJB6428G		
Make & Model:	MERCEDES-BENZ A180, 1.6 FL STYLE (R17 HLG) (A)	Engine No:	27091031498275
Reg. Date:	16/01/2018 (Man. Year: 2017)	Chassis No:	WDD1760422J708669
Colour:	Grey	Odometer:	36787 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	S\$103,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Continental 4 mm	Rear Left Side:	Continental 4 mm
Front Right Side:	Continental 4 mm	Rear Right Side:	Continental 4 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	52,002.50	50,410.80	1,591.70	3.06
Miscellaneous Items	1,016.00	891.00	125.00	12.30
Labour	2,304.00	2,524.80	-220.80	-9.58
Paintwork Labour	1,065.05	1,149.19	-84.14	-7.90
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	56,387.55	54,975.79	1,411.76	2.50
- Excess (\$\$)	0.00	800.00	-800.00	
(\$\$)	56,387.55	54,175.79	2,211.76	3.92
+ GST 7.00/7.00% (\$\$)	3,947.13	3,792.31	154.82	3.92
Nett Amount (\$\$)	60,334.68	57,968.10	2,366.58	3.92

INSPECTION

Date of Assignment:	19/01/2022	Present Location:	Mova Automotive Pte Ltd (Bukit Merah)
Date Inspected:	12/01/2022	Inspected At:	Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3 Singapore 159722
Estimated Period of Repair:	18.0 days		

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*AIR CON COMPRESSOR (WCP)	Broken	2,090.00 F	*2,090.00 F
2	1	NA	*AIR CON CONDENSER (WCP)	Dented	732.00 F	*732.00 F
3	1	NA	*BONNET CABLE (WCP)	Not Necessary	40.00 F	*- F
4	1	NA	*CATALYST (WCP)	Dented	2,260.00 F	*2,260.00 F
5	1	NA	*CIRULATION PUMP (WCP)	Broken	350.00 F	*350.00 F
6	1	NA	*COMPR/CONDENSER PIPE (WCP)	Bent	175.00 F	*175.00 F
7	1	NA	*COMPRESSOR PIPE (WCP)	Not Necessary	225.00 F	*- F
8	1	NA	*CTR EXHAUST PIPE (WCP)	Bent	630.00 F	*630.00 F
9	1	NA	*CTR FRT REINF (WCP)	Bent	470.00 F	*600.00 F
10	1	NA	*ENGINE SEALANT (WCP)	Not Necessary	50.00 F	*- F
11	1	NA	*FRONT AXLE SUPPORT (WCP)	Dented	950.00 F	*950.00 F
12	1	NA	*FRONT BUMPER GRILLE (WCP)	Broken	85.00 F	*85.00 F
13	1	NA	*FRONT BUMPER SPOILER (WCP)	Missing	90.00 F	*90.00 F
14	1	NA	*FRONT BUMPER TRIM (WCP)	Broken	1,050.00 F	*1,050.00 F
15	1	NA	*FRONT CENTRE TRIM (WCP)	Broken	120.00 F	*120.00 F
16	1	NA	*FRONT CROSSMEMBER (WCP)	Dented	210.00 F	*210.00 F
17	1	NA	*FRONT GRILLE (WCP)	Broken	350.00 F	*350.00 F
18	1	NA	*FRONT GRILLE PANEL (WCP)	Broken	200.00 F	*200.00 F
19	1	NA	*FRONT IMPACT DAMPER (WCP)	Broken	90.00 F	*90.00 F
20	1	NA	*FRONT STABILISER (WCP)	Bent	220.00 F	*220.00 F
21	1	NA	*FRONT STAR EMBLEM (WCP)	Missing	90.00 F	*90.00 F
22	1	NA	*FRT BUMPER C-MEMBER (WCP)	Bent	90.00 F	*90.00 F
23	1	NA	*FRT LWR PROTECT PNL (WCP)	Missing	110.00 F	*110.00 F
24	1	NA	*FRT NO PLATE BACKG (WCP)	Missing	55.00 F	*55.00 F
25	1	NA	*FRT PROTECTION COVER (WCP)	Broken	30.00 F	*30.00 F
26	1	NA	*FRT TOWING EYE COVER (WCP)	Not Necessary	40.00 F	*- F
27	1	NA	*GEARBOX (WCP)	Broken	13,860.00 F	*13,860.00 F
28	1	NA	*GEARBOX CARRIER (WCP)	Broken	190.00 F	*190.00 F
29	1	NA	*HEATER BLOWER (WCP)	Broken	550.00 F	*550.00 F
30	1	NA	*INLET WATER HOSE (WCP)	Cut	50.00 F	*50.00 F
31	1	NA	*INTERCOOLER (WCP)	Dented	580.00 F	*580.00 F
32	1	NA	*L/CENTRE COVER (WCP)	Broken	50.00 F	*50.00 F
33	1	NA	*L/CHARGE AIR HOSE (WCP)	Cut	150.00 F	*150.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
34	1	NA	*L/DOOR MIRROR GLASS (WCP)	Broken	380.00 F	*380.00 F
35	1	NA	*L/DOOR MIRROR HSG (WCP)	Broken	170.00 F	*170.00 F
36	1	NA	*L/FASTENING CLIP (WCP)	Necessary	60.00 F	*27.00 F
37	1	NA	*L/F BRAKE HOSE (WCP)	Cut	60.00 F	*60.00 F
38	1	NA	*L/F BUMPER GRILLE (WCP)	Broken	30.00 F	*30.00 F
39	1	NA	*L/F DAMPER STOP (WCP)	Not Necessary	40.00 F	*- F
40	1	NA	*L/F DRIVE SHAFT (WCP)	Broken	1,300.00 F	*1,300.00 F
41	1	NA	*L/F HINGE COVER (WCP)	Broken	8.00 F	*8.00 F
42	1	NA	*L/F HUB CAP (WCP)	Not Necessary	35.00 F	*- F
43	1	NA	*L/F INN BUMPER COVER (WCP)	Not Necessary	25.00 F	*- F
44	1	NA	*L/F INNER SENSOR (WCP)	Broken	135.00 F	*135.00 F
45	1	NA	*L/F INN SPACER RING (WCP)	Necessary	10.00 F	*10.00 F
46	1	NA	*L/F INTERM PIECE (WCP)	Not Necessary	10.00 F	*- F
47	1	NA	*L/FLOOR COVER (WCP)	Bent	35.00 F	*32.00 F
48	1	NA	*L/F LWR BUMP SUPPORT (WCP)	Necessary	20.00 F	*20.00 F
49	1	NA	*L/F LWR CONTROL ARM (WCP)	Bent	350.00 F	*350.00 F
50	1	NA	*L/F LWR FLOOR COVER (WCP)	Broken	110.00 F	*110.00 F
51	1	NA	*L/F OUTER SENSOR (WCP)	Broken	135.00 F	*135.00 F
52	1	NA	*L/F OUT SPACER RING (WCP)	Not Necessary	10.00 F	*- F
53	1	NA	*L/FR SHOCK ABSORBER (WCP)	Bent	410.00 F	*410.00 F
54	1	NA	*L/FR WHEEL (WCP)	Broken	540.00 F	*550.00 F
55	1	NA	*L/F S-ABSORB BOOT (WCP)	Not Necessary	35.00 F	*- F
56	1	NA	*L/F SP/STRUT SUPPORT (WCP)	Not Necessary	45.00 F	*- F
57	1	NA	*L/F SPEED SENSOR (WCP)	Broken	65.00 F	*65.00 F
58	1	NA	*L/F STABI LINKAGE (WCP)	Bent	65.00 F	*65.00 F
59	1	NA	*L/F STEERING KNUCKLE (WCP)	Bent	580.00 F	*580.00 F
60	1	NA	*L/F STRUT BEARING (WCP)	Necessary	180.00 F	*400.00 F
61	1	NA	*L/F SUSPN BUFFER (WCP)	Not Necessary	8.00 F	*- F
62	1	NA	*L/F WHEELHOUSE COVER (WCP)	Broken	135.00 F	*135.00 F
63	1	NA	*L/F WING (WCP)	Dented	385.00 F	*385.00 F
64	1	NA	*L/F WING BRACKET (WCP)	Not Necessary	15.00 F	*- F
65	1	NA	*L/F WING COVER (WCP)	Not Necessary	40.00 F	*- F
66	1	NA	*L/GRILLE TRIM (WCP)	Cut	38.00 F	*45.00 F
67	1	NA	*L/HORN (WCP)	Broken	140.00 F	*140.00 F
68	1	NA	*L/LOWER BEARING (WCP)	Necessary	20.00 F	*20.00 F
69	1	NA	*L/LWR DAMPER RING (WCP)	Not Necessary	40.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
70	1	NA	*L/LWR RADIATOR BRKT (WCP)	Broken	35.00 F	*35.00 F
71	1	NA	*L/OUTER AIR DUCT (WCP)	Broken	38.00 F	*38.00 F
72	1	NA	*L/RADIATOR AIR GUIDE (WCP)	Not Necessary	25.00 F	*- F
73	1	NA	*L/RADIATOR HOSE (WCP)	Cut	30.00 F	*58.00 F
74	1	NA	*L/R BRAKE HOSE (WCP)	Necessary	60.00 F	*60.00 F
75	1	NA	*L/R CAMBER STRUT (WCP)	Cut	165.00 F	*165.00 F
76	1	NA	*L/R CONTROL ARM (WCP)	Broken	175.00 F	*175.00 F
77	1	NA	*L/RR SHOCK ABSORBER (WCP)	Bent	260.00 F	*260.00 F
78	1	NA	*L/RR WHEEL (WCP)	Not Necessary	540.00 F	*- F
79	1	NA	*L/R SPEED SENSOR (WCP)	Necessary	155.00 F	*155.00 F
80	1	NA	*L/R STABILIZER ROD (WCP)	Necessary	60.00 F	*60.00 F
81	1	NA	*L/R TIE ROD (WCP)	Bent	80.00 F	*80.00 F
82	1	NA	*L/R UPP CONTROL ARM (WCP)	Bent	180.00 F	*180.00 F
83	1	NA	*L/R WHEEL HUB (WCP)	Jammed	230.00 F	*230.00 F
84	1	NA	*L/R WHEEL SUPPORT (WCP)	Bent	820.00 F	*820.00 F
85	1	NA	*L/SILL PANEL COVER (WCP)	Broken	270.00 F	*270.00 F
86	1	NA	*L/TIE ROD LWR TRIM (WCP)	Broken	40.00 F	*40.00 F
87	1	NA	*L/TIE ROD UPP TRIM (WCP)	Broken	40.00 F	*40.00 F
88	1	NA	*L/UPPER BEARING (WCP)	Not Necessary	25.00 F	*- F
89	1	NA	*LEFT AIR DUCT (WCP)	Not Necessary	40.00 F	*- F
90	1	NA	*LEFT HEADLAMP ASSY (WCP)	Broken	590.00 F	*590.00 F
91	1	NA	*LOWER AIR GUIDE (WCP)	Broken	52.00 F	*52.00 F
92	1	NA	*MERCEDES STAR MOUNT (WCP)	Necessary	55.00 F	*55.00 F
93	1	NA	*R/CHARGE AIR HOSE (WCP)	Not Necessary	120.00 F	*- F
94	1	NA	*R/CTR COVER (WCP)	Not Necessary	45.00 F	*- F
95	1	NA	*R/FASTENING CLIP (WCP)	Necessary	60.00 F	*6.00 F
96	1	NA	*R/F INTERM PIECE (WCP)	Not Necessary	10.00 F	*- F
97	1	NA	*R/FLOOR COVER (WCP)	Broken	35.00 F	*35.00 F
98	1	NA	*R/F LWR CONTROL ARM (WCP)	Bent	350.00 F	*350.00 F
99	1	NA	*R/F LWR FLO00R COVER (WCP)	Broken	110.00 F	*98.00 F
100	1	NA	*R/GRILLE TRIM (WCP)	Cut	48.00 F	*48.00 F
101	1	NA	*R/LOWER BEARING (WCP)	Necessary	20.00 F	*20.00 F
102	1	NA	*R/LWR RADIATOR BRKT (WCP)	Broken	35.00 F	*35.00 F
103	1	NA	*R/RADIATOR AIR GUIDE (WCP)	Not Necessary	45.00 F	*- F
104	1	NA	*R/RADIATOR HOSE (WCP)	Cut	60.00 F	*60.00 F
105	1	NA	*R/R BRAKE WEAR INDIC (WCP)	Not Necessary	20.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
106	1	NA	*R/UPP ENGINE MNTG (WCP)	Broken	200.00 F	*200.00 F
107	1	NA	*R/UPPER BEARING (WCP)	Not Necessary	20.00 F	*- F
108	1	NA	*RAD GRILLE COVER (WCP)	Broken	105.00 F	*105.00 F
109	1	NA	*RADIATOR (WCP)	Dented	610.00 F	*610.00 F
110	1	NA	*RADIATOR CROSSMEMBER (WCP)	Dented	290.00 F	*270.00 F
111	1	NA	*REAR AXLE SUBFRAME (WCP)	Bent	1,050.00 F	*1,248.00 F
112	1	NA	*REAR BUMPER CAP (WCP)	Not Necessary	75.00 F	*- F
113	1	NA	*REAR LOWER BUMPER (WCP)	Not Necessary	280.00 F	*- F
114	1	NA	*REAR MOUNTING (WCP)	Not Necessary	10.00 F	*- F
115	1	NA	*REAR SILENCER (WCP)	Bent	650.00 F	*650.00 F
116	1	NA	*REAR STABILISER (WCP)	Bent	155.00 F	*155.00 F
117	1	NA	*RIGHT AIR DUCT (WCP)	Broken	45.00 F	*45.00 F
118	1	NA	*STAR EMBLEM (WCP)	Necessary	40.00 F	*40.00 F
119	1	NA	*STEERING GEAR (WCP)	Bent	3,700.00 F	*3,700.00 F
120	1	NA	*SUMP (WCP)	Broken	560.00 F	*560.00 F
121	1	NA	*TUNNEL COVER PANEL (WCP)	Broken	55.00 F	*55.00 F
122	1	NA	*UPPER AIR GUIDE (WCP)	Broken	45.00 F	*40.00 F
123	1	NA	*WASHER CONTAINER (WCP)	Broken	120.00 F	*120.00 F
124	1	NA	*WASHER PUMP (WCP)	Broken	75.00 F	*75.00 F
125	1	NA	*WATER HOSE (WCP)	Cut	35.00 F	*35.00 F
<u>Supplementary #1</u>						
126	1		*AUX W-PUMP BRACKET (WCP)	Broken	23.00 F	*23.00 F
127	1		*AUX W-PUMP BRACKET (WCP)	Broken	19.00 F	*19.00 F
128	1		*BACKUP BATTERY (WCP)	Shorted	125.00 F	*125.00 F
129	1		*BREATHER PIPE (WCP)	Bent	70.00 F	*70.00 F
130	1		*CATALYST COVER PANEL (WCP)	Bent	110.00 F	*110.00 F
131	1		*COOLANT LINE (WCP)	Necessary	40.00 F	*40.00 F
132	1		*ENGINE HARNESS (WCP)	Missing	25.00 F	*25.00 F
133	1		*ENG WIRE HARNESS (WCP)	Missing	38.00 F	*38.00 F
134	1		*EXPENSION TANK PIPE (WCP)	Bent	50.00 F	*50.00 F
135	1		*FR TUNNEL REINFORCEM (WCP)	Bent	23.00 F	*23.00 F
136	1		*F-TANK PROTECT PANEL (WCP)	Bent	70.00 F	*70.00 F
137	1		*HYD DIRECTCTRLVALVE (WCP)	Broken	88.00 F	*88.00 F
138	1		*L/CONNECTING SUPPORT (WCP)	Broken	55.00 F	*55.00 F
139	1		*L/DR SHAFT SUPPORT (WCP)	Broken	200.00 F	*200.00 F
140	1		*L/FABSCABLE BRKET (WCP)	Broken	30.00 F	*30.00 F

Report was unsubmitted during this print-out.

10/6/22, 4:40 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
141	1		*L/F BRAKE DISC (WCP)	Broken	165.00 F	*165.00 F
142	1		*L/R WHEELHOUSE COVER (WCP)	Torn	110.00 F	*110.00 F
143	1		*NUT (WCP)	Necessary	60.00 F	*60.00 F
144	1		*OIL LEVEL SENSOR (WCP)	Broken	75.00 F	*75.00 F
145	1		*PLASTIC NUT (WCP)	Necessary	45.00 F	*45.00 F
146	1		*R/F BRAKE DISC (WCP)	Cut	165.00 F	*165.00 F
147	1		*R/R SPEED SENSOR (WCP)	Broken	105.00 F	*105.00 F
148	1		*R/UPP ENGINE SUPPORT (WCP)	Bent	185.00 F	*185.00 F
149	1		*REAR AXLE TRIM (WCP)	Torn	40.00 F	*40.00 F
150	1		*REAR SILENCER CLAMP (WCP)	Bent	100.00 F	*100.00 F
151	1		*RR ENGINE SUPPORT (WCP)	Broken	185.00 F	*185.00 F
152	1		*RR TUNNEL REINF (WCP)	Bent	23.00 F	*23.00 F
153	1		*SCREW (WCP)	Necessary	60.00 F	*60.00 F
154	1		*UPP PROTECTION PANEL (WCP)	Necessary	20.00 F	*20.00 F
155	1		*V-BELT (WCP)	Torn	27.00 F	*27.00 F
156	1		*WASHER PUMP SEAL (WCP)	Necessary	5.00 F	*5.00 F
F=Franchise part.						
Sub Total (\$\$)					47,275.00	45,828.00
+ Margin on L,N Items 10.00/10.00% (\$\$)					4,727.50	4,582.80
Total Parts (\$\$)					52,002.50	50,410.80
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	L/F TYRE (70%) (Cut)	250.00	175.00
2	1	NO PLATE (Missing)	35.00	35.00
3	1	AIR COND GAS (Necessary)	50.00	50.00
4	1	ANTI FREEZE (Necessary)	20.00	20.00
5	1	AUTO OIL 6 LT @25X6 LT (Necessary)	150.00	150.00
6	1	ENGINE OIL 8 LT @25X8 LT (Necessary)	200.00	200.00
7	1	OD/TP Case (Insurer)	11.00	11.00
<u>Supplementary #2</u>				
8	1	RESET WARNING LIGHT (NECESSARY)	300.00	250.00
Sub Total (\$\$)			1,016.00	891.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paint Labour	New	748.80	816.00
2	Total Paint Materials	New	316.25	333.19
<u>Labour Items</u>				
3	Total Panel/Mechanical Labour	New	2,304.00	2,524.80
Gross Labour Cost (\$\$)			3,369.05	3,673.99

Report was unsubmitted during this print-out.

< END OF ESTIMATES >