3/21/22, 12:20 PM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22000424/BTF3N2

21/03/2022 Date:

**REFERENCE** 

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No:

DMCVSNW00130692101

**Claimant Vehicle** 

SME6141G

Insured Vehicle No:

**GBC3064G** 

No:

Nature of

Date of Loss:

06/01/2022

TP Claim:

Claim

SNM22D200287/C02/TANCHC

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**SME6141G** Reg No:

Make & Model: HONDA CIVIC, 1.6 VTI CVT (A) Reg. Date:

08/10/2018 (Man. Year: 2018)

Engine No: Chassis No: Odometer:

R16B25501935 MRHFC5650JT001666

Yes

Colour:

Grey

**Engine Capacity:** 1597 cc Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

37311 km

Handbrake (Serviceable):

Engine Modification: Yes

Pre-accident Condition: Nο

**CONDITION OF TYRES** 

Front Tyre Size: Front Left Side:

Front Right Side:

215/55 R16 Yokohama 5 mm Yokohama 5 mm Rear Tyre Size: Rear Left Side: Rear Right Side: 215/55 R16 Yokohama 5 mm Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,661.20	2,229.04	2,432.16	52.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,680.00	1,860.00	1,820.00	49.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,341.20	4,089.04	4,252.16	50.98
Approved Total (Overridden) (S\$)		3,250.00		
(S\$)	8,341.20	3,250.00	5,091.20	61.04
+ GST 7.00/7.00% (S\$)	583.88	227.50	356.38	61.04
Nett Amount (S\$)	8,925.08	3,477.50	5,447.58	61.04

**INSPECTION** 

Date of Assignment: 12/01/2022

Bifrost Auto Pte Ltd (Kaki Bukit)

Date Inspected:

13/01/2022 Inspected At:

8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit

Singapore 415875

Estimated Period of Repair:

7.0 days

Manager:

Adjuster: Lim Teow Guan DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### **REPAIR DETAILS**

#### Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Mar 2022)

Parts: 143 HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SME6141G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DISK WHEEL REAR RH	Not Damaged	480.00 FL	*- FL
2	1		*DRIVE SHAFT ASSY REAR RH	Not Damaged	927.90 FL	*- FL
3	1		*KNUCKLE COMPR REAR RH	Not Damaged	346.40 FL	*- FL
4	1		*STABILIZER COMP REAR RH	Not Damaged	103.60 FL	*- FL
5	1		*LINK COMP STABILIZER REAR RH	Not Damaged	25.00 FL	*- FL
6	1		*ARM COMP BR REAR RH LOWER	Not Damaged	67.40 FL	*- FL
7	1		*ARM COMP R REAR RH TRAILING	Not Damaged	67.10 FL	*- FL
8	1		*ARM COMP REAR RH UPPER	Not Damaged	130.20 FL	*- FL
9	1		*CAP REAR RHR SHOCK ABSORBER MOUNT	Not Damaged	1.30 FL	*- FL
10	1		*ARM COMP REAR RH LOWER	Not Damaged	45.60 FL	*- FL
11	1		*BEARING ASSY REAR RH HUB UNIT	Jammed	175.20 FL	*175.20 FL
12	1		*REAR RH FENDER	Dented	812.30 FL	*812.30 FL
13	1		*REAR WINDSCREEN MOULDING	Necessary	120.00 FL	*120.00 FL
14	1		*TAILLIGHT ASSYR	Cut	321.10 FL	*321.10 FL
15	1		*FACE ASSY,RR BUMPER	Cut	617.20 FL	*617.20 FL
16	1		*BEAM COMPRR. BUMPER	Not Damaged	188.00 FL	*- FL
17	1		*SPACERR RR BUMPER SIDE	Necessary	11.50 FL	*11.50 FL
18	1		*SPACERL RR BUMPER SIDE	Necessary	11.50 FL	*11.50 FL
19	1		*GARNISH,R RR BUMPER SIDE	Not Necessary	8.90 FL	*- FL
20	1		*PANEL L RR DOOR	Dented	783.80 FL	*717.50 FL
21	1		*MOLDING ASST L RR DR LINER	Not Damaged	58.20 FL	*- FL
22	1		*PANEL L RR DOOR INNER LOCK	Not Damaged	225.80 FL	*- FL
23	1		*PANEL L RR DOOR INNER LOCK REGULATOR	Not Damaged	298.50 FL	*- FL
F=Fra	ınchise	part. L=ListIte	emDisc.	_		
				Sub Total (S\$)	5,826.50	2,786.30
	- List Item Discount on L Items 20.00/20.00% (S\$)			1,165.30	557.26	
				Total Parts (S\$)	4,661.20	2,229.04

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labe	our Items			
1	INSPECT RR LIGHTING MECHANISMS, PERFORM WATER	New	80.00	0.00
2	RESET VEHICLE SMART ENTRY SYSTEM	New	280.00	0.00
3	REMOVE & TRANSFER ITEMS TO NEW RR L DR,ADJUST	New	120.00	80.00
4	REMOVE & INSTALL RR L QTR GLASS	New	200.00	60.00
5	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	New	200.00	0.00
6	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	200.00	0.00
7	CUT & RENEW RR L FENDER.RENEW ALL DAMAGE PARTS	New	1,200.00	800.00
8	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	1,000.00	800.00
9	REMOVE & INSTALL RR WINDSCREEN	New	150.00	120.00
10	SUPPLY & INSTALL SOLAR FILM ON REAR QTR GLASS	New	250.00	0.00
	Gross Labour Cost (S\$)		3,680.00	1,860.00
	Report was unsubmitted durin	g this print-out.		

< END OF ESTIMATES >