

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000427/KTF3N2**Date:** 25/01/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00181582101		
Claimant Vehicle No :	EL3U	Insured Vehicle No :	SLR7755Y		
Date of Loss:	10/01/2022	Nature of Claim:	TP	Claim No:	SNM22D200267/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	EL3U		
Make & Model:	MERCEDES-BENZ E200 AVG, 2.0 (R18 LED) (A)	Engine No:	27492031615709
Reg. Date:	13/12/2018 (Man. Year: 2018)	Chassis No:	WDD2130422A525540
Colour:	Metallic Silver	Odometer:	14050 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45R18	Rear Tyre Size:	245/45R18
Front Left Side:	Pirelli 9 mm	Rear Left Side:	Pirelli 9 mm
Front Right Side:	Pirelli 9 mm	Rear Right Side:	Pirelli 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,674.90	4,572.71	6,102.19	57.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,400.00	520.00	1,880.00	78.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,074.90	5,092.71	7,982.19	61.05
Approved Total (Overridden) (S\$)		3,900.00		
(S\$)	13,074.90	3,900.00	9,174.90	70.17
+ GST 7.00/7.00% (S\$)	915.24	273.00	642.24	70.17
Nett Amount (S\$)	13,990.14	4,173.00	9,817.14	70.17

INSPECTION

Date of Assignment:	12/01/2022		
Date Inspected:	12/01/2022	Inspected At:	Thiam Heng Huat Pte Ltd (SIN MING) 176 SIN MING DRIVE, #05-14 Singapore 575721
Estimated Period of Repair:	3.0 days		

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Jan 2022)

Parts: 143 MERCEDES-BENZ E200 AVG 2.0 (R18 LED) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for EL3U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER REINFORCEMENT	Repair	877.00 FL	*- FL
2	1		*FRONT BUMPER IMPACT ABSORBER	Serviceable	489.00 FL	*- FL
3	1		*HEADLAMP O/S	Cut	3,965.00 FL	*3,125.00 FL
4	1		*HEADLAMP LOWER BRACKET O/S	Serviceable	109.00 FL	*- FL
5	1		*FRONT BUMPER	Buckled/Mtg Cracked	1,569.00 FL	*1,508.00 FL
6	1		*FRONT BUMPER LOWER SPLASH COWLING	Serviceable	396.00 FL	*- FL
7	2		*FRONT BUMPER SIDE RETAINER	Serviceable	128.00 FL	*- FL
8	1		*FRONT BUMPER SIDE SENSOR HOLDER O/S	Missing	187.00 FL	*108.90 FL
9	1		*FRONT BUMPER LOWER SIDE GARNISH O/S	Serviceable	386.00 FL	*- FL
10	1		*FRONT BUMPER LOWER SIDE GARNISH SENSOR HOLDER O/S	Serviceable	565.00 FL	*- FL
11	12		*FRONT BUMPER CLIPS	Necessary	90.00 FS	*90.00 FS
12	8		*FRONT FENDER INNER SHIELD CLIPS O/S	Not Necessary	60.00 FS	*- FS
13	8		*FRONT BUMPER LOWER SPLASH COWLING CLIPS	Not Necessary	60.00 FS	*- FS
14	1		*FRONT ALLOY RIM O/S	Serviceable	850.00 FS	*- FS
15	1		*FRONT TYRE O/S	Serviceable	380.00 FS	*- FS
16	1		*FRONT BUMPER LOWER SIDE GARNISH SENSOR O/S	Shorted	280.00 FS	*215.00 FS
17	1		*FRONT BUMPER SENSOR HARNESS O/S	Serviceable	815.00 FS	*- FS
18	1		*FRONT BUMPER SIDE SENSOR O/S	Serviceable	286.00 FS	*- FS
19	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,542.00	5,046.90
- List Item Discount on L Items 10.00/10.00% (\$\$)	867.10	474.19
Total Parts (\$\$)	10,674.90	4,572.71

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE/RENEW ACCIDENT DAMAGED PORTIONS.TO PANEL BEAT,RESHAPE,STRAIGHTEN,ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	New	1,200.00	250.00
2	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS,RECONNECT AND CHECK FUNCTIONS INCLUDING FOCUSING HEADLAMPS	New	50.00	20.00
3	TO REMOVE AND REFIT O/S FRONT TYRE & RIM.TO PERFORM TYRE BALANCING	New	50.00	0.00
4	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA/PANEL	New	1,000.00	250.00
5	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR	New	100.00	0.00
Gross Labour Cost (\$\$)			2,400.00	520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >