

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22000428/BVF3N2**Date:** 17/02/2022**REFERENCE**Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00001172102

**Claimant Vehicle  
No :** SMZ7811P**Insured  
Vehicle No :** SJM8934R

Date of Loss: 10/01/2022

Nature of Claim: TP

Claim  
No: SNM22D200292/C02/LEWLC**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SMZ7811P**

Make &amp; Model: MERCEDES-BENZ GLC 250, 2.0 4MATIC (A)

Engine No: 27492031675360

Reg. Date: 10/01/2019 (Man. Year: 2018)

Chassis No: WDC2533462F543136

Colour: Silver

Odometer: 56828 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 255/45R20

Rear Tyre Size: 275/40ZR20

Front Left Side: Michelin 5 mm

Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Right Side: Michelin 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	11,086.73	3,359.39	7,727.34	69.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,000.00	980.00	2,020.00	67.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>14,086.73</b>	<b>4,339.39</b>	<b>9,747.34</b>	<b>69.20</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,450.00</b>		
<b>(S\$)</b>	14,086.73	3,450.00	10,636.73	75.51
<b>+ GST 7.00/7.00% (S\$)</b>	986.07	241.50	744.57	75.51
<b>Nett Amount (S\$)</b>	<b>15,072.80</b>	<b>3,691.50</b>	<b>11,381.30</b>	<b>75.51</b>

**INSPECTION**

Date of Assignment: 12/01/2022

Date Inspected: 13/01/2022 Inspected At:

 160 SIN MING DR  
 #01-14 SIN MING AUTO CITY  
 SINGAPORE 575722  
 REPAIRER: TEAM AUTOPRO PTE LTD

Estimated Period of Repair: 5.0 days

**Adjuster:** Lim Teow Guan**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 17 Feb 2022)

**Parts:** M1-SUV      MERCEDES-BENZ GLC 250 2.0 4MATIC (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SMZ7811P)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Broken	1,958.00 FL	*1,366.20 FL
2	1	*REAR BUMPER LOWER	Broken	983.35 FL	*605.00 FL
3	1	*REAR BUMPER OUTER CHROME GARNISH	Broken	441.60 FL	*305.00 FL
4	1	*REAR BUMPER INNER SPONGE	Broken	325.60 FL	*288.35 FL
5	1	*REAR BUMPER REINFORCEMENT	Not Damaged	851.33 FL	*- FL
6	2	*REAR BUMPER REINFORCEMENT BRACKET	No such part	304.00 FL	*- FL
7	2	*REAR BUMPER SIDE RETAINER	Necessary	371.20 FL	*210.00 FL
8	2	*REAR BUMPER BRACKET	No such part	291.64 FL	*- FL
9	1	*REAR BUMPER REFLECTOR (2 Pcs)	Broken (1 Pc only)	196.00 FL	*82.00 FL
10	1	*REAR BUMPER CENTRE BEAM	No such part	383.00 FL	*- FL
11	1	*REAR BUMPER LOWER CENTRE COVER W/ANTENNA	No such part	828.79 FL	*- FL
12	1	*REAR BUMPER REVERSE SENSOR (4 Pcs)	Short Circuit (2 Pcs only)	983.20 FL	*400.00 FL
13	2	*REAR NUMBER PLATE LAMP	Not Damaged	228.00 FL	*- FL
14	1	*REAR END PANEL	Not Damaged	2,136.60 FL	*- FL
15	1	*REAR END PANEL TOP GARNISH	Not Damaged	425.75 FL	*- FL
16	1	*REAR EXHAUST PIPE CHROME COVER (2 Pcs)	Dented (1 Pc only)	797.20 FL	*265.00 FL
17	1	*SUNDRIES	Not Necessary	80.00 FS	*- FS
18	1	*REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
19	1	*REAR BUMPER LOWER CLIPS	Necessary	60.00 FS	*30.00 FS
20	1	*REAR BUMPER REVERSE SENSOR SEAL (4 Pcs)	Necessary (2 Pcs only)	192.00 FS	*40.00 FS
21	1	*REAR END PANEL SEALANT	Not Necessary	100.00 FS	*- FS
22	1	*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	60.00 FS	*- FS
23	1	*REAR NUMBER PLATE WITH CHROME CASING	Broken	180.00 FS	*90.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>12,237.26</b>	<b>3,711.55</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	1,150.53	352.16
<b>Total Parts (\$\$)</b>	<b>11,086.73</b>	<b>3,359.39</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	R&R REAR BUMPER REVERSE SENSOR	New	100.00	60.00
2	UPHOLSTERY	New	300.00	0.00
3	CHECK WIRING	New	100.00	0.00
4	DIAGNOSTIC RESET FAULT CODE	New	300.00	120.00
5	PANEL BEATING	New	1,000.00	600.00
6	RUST PROOFING	New	200.00	0.00
7	SPRAY PAINTING	New	1,000.00	200.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,000.00</b>	<b>980.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >