

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22000442/UPA3Q2**Date:** 06/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100468553
Claimant Vehicle No :	GBJ9056D	Insured Vehicle No :	SGK9252P
Date of Loss:	09/01/2022	Nature of Claim:	TP
		Claim No:	7904790410SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ9056D		
Make & Model:	MERCEDES-BENZ CITAN, 1.2 112 6G-DCT (A)	Engine No:	H5FG412D173433
Reg. Date:	26/09/2019 (Man. Year: 2018)	Chassis No:	WDF4156032U256359
Colour:	Brown	Odometer:	41112 km
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,874.85	4,267.05	607.80	12.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,030.00	1,000.00	1,030.00	50.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,904.85	5,267.05	1,637.80	23.72
Approved Total (Overridden) (S\$)		3,600.00		
(S\$)	6,904.85	3,600.00	3,304.85	47.86
+ GST 7.00/7.00% (S\$)	483.34	252.00	231.34	47.86
Nett Amount (S\$)	7,388.19	3,852.00	3,536.19	47.86
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,159.45		

INSPECTION

Date of Assignment:	20/01/2022	Hock Wah Motor Workshop Pte Ltd (Bedok)
Date Inspected:	20/01/2022 Inspected At:	Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012
Estimated Period of Repair:	3.0 days	Singapore 489977

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

SPECIAL REMARKS

(FOR MANDATE ONLY)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	2,295.00 FL	*2,295.00 FL
2	1		*TAILGATE EMBLEM	Not Necessary	59.50 FL	*- FL
3	1		*TAILGATE LOGO -CITAN	Not Necessary	76.50 FL	*- FL
4	1		*TAILGATE LOGO -112	Not Necessary	85.00 FL	*- FL
5	1		*TAIL LAMP RH	Cracked	229.50 FL	*229.50 FL
6	1		*REAR BUMPER	Dented / Deformed	1,445.00 FL	*1,445.00 FL
7	1		*REAR BUMPER RETAINER RH	Not Necessary	255.00 FL	*- FL
8	1		*REAR BUMPER REFLECTOR RH	Cracked	306.00 FL	*160.00 FL
9	1		*REAR BUMPER TOP CORNER REFLECTOR GARNISH RH	Torn	545.00 FL	*545.00 FL
10	1		*TAILGATE STICKER -70KM/H	Necessary	30.00 FS	*10.00 FS
11	1		*TAILGATE STICKER -3PAX	Necessary	30.00 FS	*10.00 FS
12	2		*REAR WINDSCREEN SEALANT	Necessary	48.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,404.50	4,734.50
- List Item Discount on L Items 10.00/10.00% (\$\$)	529.65	467.45
Total Parts (\$\$)	4,874.85	4,267.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	800.00	300.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	800.00	500.00
3	ANTI-RUST COATING	New	100.00	30.00
4	TO REMOVE & REFIT WINDSCREEN	New	180.00	120.00
5	TO REMOVE & REFIT REVERSE SENSOR	New	150.00	50.00
Gross Labour Cost (\$)			2,030.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >