

TPAXA
Xiao Tony

SKV6915A. 2015 Sep
Mazda 5 1998cc
JM6CW1071G0122450

Rear Bumper	Deformed	961.50 /
Rear Bumper Clips	new	30(SN) /
Rear Bumper Side Holder x02	new	$47.6 \times 2 = 95.20$ /
Rear Bumper Reflector x02	crushed	$53 \times 2 = 106$ /
Rear Bumper Reinforcement Bar	Bent	294.80 /
Reverse Sensor	Damaged	280(SN) 200(SN) /
Rear End Panel	Dented	515.70 ✓
Rear End Panel Sealant	new	60(SN) ✓
Rear End Panel Top Garnish	crushed	214.50 /
Rear End Panel Top Garnish Clips	new	20(SN) /
Taillap x02	x16 new	$601.7 \times 2 = 1203.40$ X
Tailgate	Dented	1637 /
Tailgate Lock	Damaged	256.20 /
Tailgate Weatherstripe	Torn	204.50 /
Tailgate Inner Trim Board		421.60 X
Tailgate Inner Trim Board Clips	new	30(SN) X

• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

SKV6915A.

Tailgate Glass Moulding } per
Tailgate Glass Sealant

126.20 ✓

60(SN) ✓

Mazda Logo

} per

45.30 ✓

Mazda 5 Wordmark

59.40 ✓

Rear Exhaust Pipe.

Bent

991.80 ✓

Rear Exhaust Mounting

Not in

34.40. X

550840

S.N: 370

A40648

Panel Beating.

~~1200~~ 800

Spray Painting.

~~1000~~ 800

Wiring.

1980

~~50~~ 30

To remove cruise sensor

~~100~~ 50

To remove upholstery.

~~150~~ 40

To spray buff coat

~~150~~ 60

5.4k
06 days

To transfer tailgate fittings

~~150~~ 80

To remove tailgate glass

~~180~~ 120

Total 675648

1/5: 5 HK

06 Days