



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 8533K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRT DOOR MIRROR LH	BROKEN	670.00	670.00
1	FRT DOOR MIRROR HOLDER LH	SERVICEABLE	62.40	-
1	FRT DOOR LH	TO REPAIR SEE LABOUR	2,256.40	-
1	FRT DOOR GLASS LH	TO REPAIR SEE LABOUR	316.30	-
1	FRT DOOR OUTER HANDLE LH	CUT	132.30	132.30
1	FRT DOOR OUTER MOULDING LH	DENTED	153.10	153.10
1	FRT FENDER LH	DENTED	663.00	663.00
	LESS 20% DISCOUNT		-850.70	-323.68
			3,402.80	1,294.72
<u>SPECIAL NETT ITEMS</u>				
1	FRT DOOR COMFORT LOGO LH (SN)	NECESSARY	75.00	75.00
			75.00	75.00
<u>LABOUR</u>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRT DOOR LH AND FRT DOOR GLASS LH.		900.00	560.00
	SPRAY PAINTING CHARGE.		650.00	600.00
	TRANSFER OF FRT DOOR.	NOT NECESSARY	120.00	-
	TUFF KOTE.		60.00	20.00
	CHECK ALL LIGHTING.		60.00	20.00
			1,790.00	1,200.00
GRAND TOTAL			5,267.80	2,569.72
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,650.00

Report Ref No. NS/INC22000458/Vtcn2

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.